

AIRCRAFT ACCIDENT  
IDENTIFICATION  
NO.

704 05 101

## SUPPLEMENTARY (Card No. 2)

© 2004



## OTHER INJURED PERSONNEL

(Modified Card No. 3)

[illegible]

IBM: Place an "X" overpunch in CC80 if these cards are coded.



Parker Jan 396

I. D. Number	GCI	MODEL	FY	MODEL CODE
70405101	00	-A3B	7	01

TYPE A/C	TYPE MIS	WIND VEL	WAVE HEIGHT	WAVE PERIOD	VISIBILITY	AIR TEMP	WATER TEMP	ALERT FACTOR	LOC. SITE	SURV. LEFT	LOC. SURV.	SURV. FAC.	FATALS (NO RESCUE)	TRG. DATE	TRG. DATE	TRG. FACTOR	NO INJURY	INJURY	2 ZONE	SEQ OF IND.
AF14	422							NOFH	E			AHA		EE	EP		2A		01	

CARD 67

TIME OF DAY			LOC. DUTY RES. VEH.	RESCUE VEHICLE MODEL AND TYPE	NO TO BE RESCUED	NO RESCUED	BACK UP RES. VEH.	WATER TEMP	AIR TEMP	SEA COND	WEATHER	WIND VEL	RESCUE EQUIPMENT USED	TRG OF RES. TEAMS	COM. TECH AND EQUIP	RETRV TECH AND EQUIP	RES TEAM WORK	TYPE AIRCRAFT	TYPE MISCHAP	TOPOGRAPHY	DISTANCE	TIME MIS. TO ALERT	ALERT PROB.	METHOD OF ALERT	TIME DEPART	DEP Delay	INJURY	2 ZONE	SEQ OF IND																													
MIS HAP	DEPART	LOC / HAP N.																																																								
6	19	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 68

TIME ALERT TO LOC.	PROB IN RTE.	REASON LOC TO RECH.	LOCATOR MEANS	LOC PROB	SURV. SIG. PROB.	TYPE A/C	TYPE MIS	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	SURVIVOR PROBLEMS	SURV. COND	SURV. COND	TIME RECH. TO ACC.	TOT. TIME	RES REQ.	SEQ OF IND																																								
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 69

I.D. Number	GCI	MODEL	FY	Model Code
70405101	00	-A3B	7	01

[illegible]

CARD 65

[illegible]

CARD 65A

CARD 65 A		IN		No. of Cds		C Seg	
T	T	N	J	of	Cds	I	Seg
A	M						and
16	17	18	19	20	21	22	23
24	25	26	27	28	29	30	31
32	33	34	35	36	37	38	39
40	41	42	43	44	45	46	47
48	49	50	51	52	53	54	55
56	57	58	59	60	61	62	63
64	65	66	67	68	69	70	71
72	73	74					

CARD 65B

[illegible]

CARD 66

I. D. Number	GCI	MODEL	FY	MODEL CODE
70405101	00	-A3B	7	01

[illegible]

CARD 67

TIME OF DAY				LOC. DUTY RES. VEH.	RESCUE VEHICLE MODEL AND TYPE	NO TO BE RESCUED	NO RESCUED	BACK UP RES. VEH.	WATER TEMP	AIR TEMP	SEA COND	WEATHER	WIND VEL	RESCUE EQUIPMENT USED	TRG OF RES. TEAM	COM. TECH AND EQUIP	RETRV. TECH AND EQUIP	RES TEAM WORK	TYPE AIRCRAFT	TYPE MISHAP	TOPOGRAPHY	DISTANCE	TIME MIS. TO ALERT	ALERT PROB.	METHOD OF ALERT	TIME DEPART	DEP DELAY	INJURY	NO OF WOUND	SEQ OF WOUND																												
MISHAP	DEPART	LOCATE	ACQ/HABAN																																																							
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 68

TIME ALERT TO LOC.	PROB IN RTE.	FAIL TO REACH	REASON	TIME LOC TO PKH.	LOC PROB	SURV. SIG. PROC.	TYPE A/C	TYPE M/S	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	SURVIVOR PROBLEMS	SURV. COND	SURV. COND	TIME RCH. TO ACC.	TOT. TIME	PES REC.	SEQ OF IND																																							
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 69







I. D. Number.	GCI	MODEL	FY	MODEL CODE
70405101	00	-A3B	7	01

TYPE A/C	TYPE G/MIS	WIND VEL	WAVE HEIGHT	WAVE LENGTH	VISIBILITY	AIR TEMP	WATER TEMP	ALERT FACTOR	LOC. SURV.	SURV FAC.	FATALS (NO RESCUE)	TRG. DATE	TRG. DATE	TRG. FACTOR	NO ENTER	H HURRY	D NO ENTER	SEQ OF IND																																																																		
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
AFT 4										122										NOFHE										AHHA										EPPP										2A										03																								

CARD 67

TIME OF DAY				LOC. DUTY RES. VEH.	RESCUE VEHICLE MODEL AND TYPE	NO TO BE DROPPED	NO RESCUED	BACK UP RES. VEH.	WATER TEMP	AIR TEMP	SEA COND	WEATHER	WIND VEL	RESCUE EQUIPMENT USED	TAG OF RES. TEAM	COM. TECH AND EQUIP	RETRV. TECH AND EQUIP	RES TEAM WORK	TYPE AIRCRAFT	TYPE MISSION	TOPOGRAPHY	DISTANCE	TIME MIS. TO ALERT	ALERT PROB.	METHOD OF ALERT	TIME DEPART	DEP DELAY	INJURY	COST OF FIND																													
MONTH	DAY	YEAR	LOC. DUTY RES. VEH.																																																							
6	7	11	14	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 68

TIME ALERT TO LOC.	PROB IN RTE.	FAIL TO REACH	REASON	TIME LOC. TO RCH.	LOCATOR MEANS	LOC. PROB	SURV. SIG. PROB.	TYPE A/C	TYPE M/S	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	SURVIVOR PROBLEMS	SURV. COND	SURV. COND	TIME RCH. TO ARR.	TOT. TIME	PES REC.	SEQ OF IND																																						
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 69

I.D. Number	GCI	MODEL	FY	Model Code
70405101	00	-A3B	7	01

[illegible][illegible]

T A		M		J		Cds		Seg of ind																																																		
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

[illegible]

CARD 66

I. D. Number	GCI	MODEL	FY	MODEL CODE
70405101	00	-A3B	7	01

[illegible]

CARD 67

TIME OF DAY				LOC.	RESCUE VEHICLE MODEL AND TYPE	No TO BE RECOVERED	No RECOVERED	BACK UP RES. VEH.	WATER TEMP	AIR TEMP	SEA COND	WEATHER	WIND VEL	RESCUE EQUIPMENT USED	TRG OF RES. TEAM'S	COM. TECH AND EQUIP	RETRV TECH AND EQUIP	RES TEAM WORK	TYPE AIRCRAFT	TOPOGRAPHY	DISTANCE	TIME MIS. TO ALERT	ALERT PROB.	METHOD OF ALERT	TIME DEPART	DEP DELAY	INJURY	C NO OF WOUND	SEQ OF WOUND																													
MISHP	DEPART	LOC/H/HEA	DUFF RES. VEH.																																																							
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 68

TIME ALERT TO LOG.	PROB IN RTE.	FAIL TO REACH	REASON	TIME LOC TO RCH.	LOCATOR MEANS	LOG PROB	SURV. SIG. PROB.	TYPE A/C	TYPE M/S	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	SURVIVOR PROBLEMS	SURV. COND	SURV. COND	TIME RCH. TO ACC.	TOT. TIME	RES REC.	SEQ OF IND																																						
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74

CARD 69



## REQUEST FOR CODE SHEET CHANGES

From: Md M Dept.                     8.24.67  
(Date)To: (1) Coder  
(2) M&M  
(3) Log Clerk  
(4) IBM  
(5) File ClerkReturn to: Open File  
Closed File  
Master Coder  
OtherIdent. No. 70405101 Model A3B BUNO 125917 Model Code P1Card #1 - Chg. col.                      to                       
" "                      to                       
" "                      to                       
" "                      to                     Chg. col.                      to                       
" "                      to                       
" "                      to                       
" "                      to                     Card #2 - Chg. col.                      to                       
" "                      to                       
" "                      to                     Chg. col.                      to                       
" "                      to                       
" "                      to                     Card #                      Name                     Chg. col.                      to                       
" "                      to                       
" "                      to                       
" "                      to                     Card #                      Name                     Chg. col.                      to                       
" "                      to                       
" "                      to                       
" "                      to                     

## USE THIS SECTION FOR CHANGES TO CARDS 31 THROUGH 59 AND CARDS 20 THROUGH 29.

Card #                      Chg. col.                      to                       
" "                      " "                      to                       
" "                      " "                      to                       
" "                      " "                      to                       
" "                      " "                      to                       
" "                      " "                      to                     Card #                      Chg. col.                      to                       
" "                      " "                      to                       
" "                      " "                      to                       
" "                      " "                      to                       
" "                      " "                      to                       
" "                      " "                      to                     ☒ Card #(s) 45 IBM, SEE CHANGES TO NARRATIVE BRIEF.  
ORIGINATOR, USE REVERSE SIDE FOR CHANGES TO BRIEF.NOTE: (1) A separate change sheet will be used for each A/C involved.  
(2) Change sheet will be stapled to code sheet.

(b) (6)

Originator's Signature

☐ Change to 5 x 8 card required.



NOTE TO ORIGINATOR OF CHANGE: If change to narrative brief is required, use the below provided space to reflect the change. Give the whole card text which represents the line of print out containing the area of change. The coders will make the final change to the master code sheet.

Card No.

Narrative

45

Correct spelling of "VALUE"  
(See code sheet change of 7-17-67)

# REQUEST FOR CODE SHEET CHANGES

From: 11-11 Dept.

To:

(1) Coder no input 7/21

(2) M&M 7-14-67

(3) Log Clerk

(4) IBM

(5) File Clerk

30 JUL 1967

Return to: Open File

Closed File

Master Coder

Other

7-17-67  
(Date)

Ident. No. 70405121 Model A 33 BUNO 138917 Model Code 01

Card #1 - Chg. col. \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_

Chg. col. \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_

Card #2 - Chg. col. \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_

Chg. col. \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_

Card # \_\_\_\_\_ Name \_\_\_\_\_ Chg. col. \_\_\_\_\_ to \_\_\_\_\_

" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_

Card # \_\_\_\_\_ Name \_\_\_\_\_ Chg. col. \_\_\_\_\_ to \_\_\_\_\_

" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ to \_\_\_\_\_

USE THIS SECTION FOR CHANGES TO CARDS 31 THROUGH 59 AND CARDS 20 THROUGH 29.

Card # 33 Chg. col. 33-37 to 9999  
" " 33 " " 17-21 to 119999  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_

Card # \_\_\_\_\_ Chg. col. \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_  
" " \_\_\_\_\_ " " \_\_\_\_\_ to \_\_\_\_\_

☒ Card #(s) 44 - IBM, SEE CHANGES TO NARRATIVE BRIEF.  
ORIGINATOR, USE REVERSE SIDE FOR CHANGES TO BRIEF.

NOTE: (1) A separate change sheet will be used for each A/C involved.  
(2) Change sheet will be stapled to code sheet.

Originator's Signature

☐ Change to 5 x 8 card required.

REQUEST FOR DELETION OF RECORD  
OR CODING MODIFICATION FORM

FROM: RECORDS DEPT.

DATE 19 MARCH 1968

TO: (1) CODING SECT. \_\_\_\_\_  
(2) REC. CONT. BRANCH ADP  
(3) ADPE DIV 19 MAR 1968  
(4) REC. CONT. BRANCH \_\_\_\_\_

TRANSACTION CODES

D-Deletion of the entire MISHAP Master Record (use only cc 1-11 and code D in cc 77).

M-Modifying contents of any Master Record field. Use "00" in Person Seq. No. field, if field to be modified is in the Gen. Data Sect. of the Master Record. Otherwise use Person Seq. No. for the individual for which the change is to be made. These changes must be in Person Seq. No. order.

IDENTIFICATION NO.										
YEAR	MONTH	DAY	TYPE REPT	LOG	NUMBER	AIRCRAFT	NUMBER			
01	02	03	04	05	06	07	08	09	10	11
67	04	05	10	10	10	10	10	10	10	10

PARKS A 30-138917

	FIELD NAME	CARD NUMBER	CARD COL. OF FLD. START ADD.	FIELD'S STARTING ADDRESS	PERSON SEQ. NUMBER	FIELD LENGTH	DATA TO BE INSERTED (LEFT JUSTIFIED)																				TAPE REC DIV. NO.	TRANS CODE
							12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29				
1	SPEC DATA & CONDIT	06	67	03	22	00	00	00	03	D																		
2	2ND POSS CAUSAL	06	43	02	98	00	00	00	01	L																		
3	"	06	48	03	03	00	00	00	02	Q	5																	

NOTE: (1) For deletions of codes in a given field, leave the "DATA TO BE INSERTED" field blank and use "TRANS CODE" M in cc 77.

(2) Only corrections applying to personnel in one TAPE RECORD DIV. may be shown on a single CHANGE REQUEST form.

(b) (6)

ORIGINATORS SIGNATURE

3-18-68

# MAINTENANCE AND MATERIAL CODE SHEET (Narrative brief on reverse)

5ND 4621 (Rev. 11/65)

MAINTENANCE AND MATERIAL CARD NUMBER 33		CARD COL.
PRIMARY INVOLVED MATERIAL COMPONENT		16-21
SECONDARY INVOLVED MATERIAL COMPONENT		24-29
POSSIBLE INVOLVED MATERIAL COMPONENT	T 41 43	32-37
SPECIAL DATA AND CONDITIONS		40-42
SPECIAL DATA AND CONDITIONS		44-46
SPECIAL DATA AND CONDITIONS		48-50
SPECIAL DATA AND CONDITIONS		52-54
SPECIAL DATA AND CONDITIONS		56-58
SPECIAL DATA AND CONDITIONS		61-63
FIRST MAINT FLT SPEC COMPONENT		65-68
CARD NUMBER	3 3	79-80

MAINTENANCE AND MATERIAL CARD NUMBER 35		CARD COL.
POSSIBLE OR SECONDARY INVOLVED MATERIAL COMPONENT:		
MFG P/N		16-31
TOTAL HOURS		34-37
OVERHAUL ACTIVITY		39
NUMBER OF OVERHAULS		41
HOURS SINCE OVERHAUL		43-46
POWER PLANT MODEL NUMBER	J 57 P 10	49-56
POWER PLANT SERIAL NUMBER	P 607 625	58-64
DIR	2	68
CARD NUMBER	3 5	79-80

MAINTENANCE AND MATERIAL CARD NUMBER 34		CARD COL.
PRIMARY INVOLVED MATERIAL COMPONENT:		
MFG P/N		16-31
TOTAL HOURS		34-37
OVERHAUL ACTIVITY		39
NUMBER OF OVERHAULS		41
HOURS SINCE OVERHAUL		43-46
AIRCRAFT TOUR		48
AIRCRAFT FLIGHT HOURS SINCE ACCEPTANCE	5744.9 W	50
AIRCRAFT FLIGHT HOURS SINCE LAST INSPECTION	246	53-55
DAYS SINCE LAST AIRCRAFT INSPECTION	79	57-58
TYPE LAST AIRCRAFT INSPECTION	C	61
MONTHS SINCE PAR/OVERHAUL	6	67-68
CARD NUMBER	3 4	79-80

CAUSE FACTORS	2
COMPONENT NO. 1	
COMPONENT NO. 2	
DESIGN	
POSSIBLE CAUSE FACTORS	3
COMPONENT	T
DESIGN	

ACCIDENT DAMAGE	A
ACCIDENT INJURY	A
SPECIAL ATTN: ("X")	
Model Code	

COORDINATOR	
DIVISION OFFICER	

M&M CODING RECORD

PUNCHED	VERIFIED
PUNCHED	VERIFIED

FOR IBM

03 JUL 1967

FOR M&M FILING ONLY

MODEL	BUNG	DATE	IDENT. NUMBER
-------	------	------	---------------

REPORT NUMBER

CUSTODIAN



16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68

ACFT ON AUTHORITY  
CROSS COUNTRY INST & CHECK FLT. RADAR CONTACT LOST,  
RADIO CONTACT LOST, WITH ACFT OVER MOUNTAINOUS TER-  
RAIN. WITNESS SAW & HEARD ACFT CRASH IN DEEP SNOW &  
HEAVY DRIFTS. FLT PATH OF ACFT SHOWED TREES OF VARI-  
OUS SIZE SHEARED AT DIFFERENT HEIGHTS. SALVAGE &  
INVS WILL CONTINUE AFTER SNOW MELTS. PRIMARY CAUSE  
UNDET, POSSIBLE PORT ENG FAILURE & OR PLT DISTORTION-  
TION. ENGINEERING ANALYSIS OF COMPONENTS RECOVERED  
DID NOT REVEAL MALFUNCTION OF SIGNIFICANT VALUE IN  
DETERMINATION OF CAUSE.  
UNDET- POSS MAT FAILURE/MAL UNDET COMP PORT ENG. POSS  
PE- EMERG OR UNUSUAL SITUATION DEVELOPED WHICH PLACED  
PLT BEYOND LIMITS OF HIS EXPER LEVEL. ENGINEERING A-  
NALYSIS OF COMPONENTS RECOVERED DID NOT REVEAL MAL OF  
SIGNIFICANT VALUE IN DETERMINATION OF CAUSE.

CARD NO.

79 80

3 6

3 7

3 8

3 9

4 0

4 1

4 2

4 3

4 4

4 5

4 6

4 7

4 8

4 9

5 0

5 1

5 2

5 3

5 4

5 5

5 6

5 7

5 8

5 9

79 80

DISPATCH CARD  
A/C ACCIDENTS ONE  
(REV 4-65)

CODED 26 DATE 4-7  
LOGGED H DATE 4-7  
PUNCHED PRB DATE 11 APR 56

SUBJECT	DON'T COUNT	ENEMY ACTION	OTHER AIRCRAFT	CARD COLUMNS
IDENTIFICATION	7	4	5	1-8
ACCIDENT DAMAGE				9
ACCIDENT INJURY				10
MODEL AIRCRAFT				11-13
BUREAU NUMBER				16-21
REPORTING CUSTODIAN				22-24
TYPE DUTY				25
MAJOR COMMAND				26
AIRCRAFT DAMAGE				27
AIRCRAFT INJURY				28
TIME OF DAY				29
CARRIER HULL NO.				30
FIRST ACCIDENT TYPE				31-32
FIRST PHASE OF OPERATION				33-35
TYPE OF OPERATION				41-42
CONTRIBUTING CAUSE FACTORS				43-44
NUMBER "A" OR "L" OR "U" INJURIES				48-49
SPECIAL DATA AND CONDITIONS				62-65
PRIMARY CAUSE				67
DISPATCH CARD				74
FISCAL YEAR				75
MODEL CODE				76-77

IBM NOTE: Key punch a "12" overpunch in card column 8 to denote other aircraft.

NAVAL AVIATION SAFETY CENTER  
NAVAL AIR STATION  
NORFOLK, VIRGINIA 23511

11/hs  
Ser 325  
25 March 1968

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6 SERIES  
FOR OFFICIAL USE ONLY

From: Commander, Naval Aviation Safety Center  
To: Commanding Officer, Heavy Attack Squadron ONE TWO THREE  
Subj: VAH-123 AAR ser 1-67A concerning A-3B BuNo 138917 accident  
occurring 5 April 1967, pilot PARKS

1. The subject report and all endorsements thereon have been reviewed. Commander, Naval Aviation Safety Center concurs with the comments and recommendations of the Aircraft Accident Board as modified by subsequent endorsers.
2. The cause of this accident has been recorded at the NAVAVNSAFECEN as UNDETERMINED with MATERIAL FAILURE (undetermined component of engine) and PILOT (emergency or unusual situation developed which placed pilot beyond limits of his experience level) as probable contributing factors.

(b) (6)

By direction

Copy to:  
NAVAIRSYSCOMHQ (AIR 404) (2)  
COMNAVAIRPAC  
COMFAIRWHIDBEY  
COMRCVW-12  
NAVPLANTREPO LONG BEACH

FOR OFFICIAL USE ONLY



NAVAL AVIATION SAFETY CENTER  
NAVAL AIR STATION  
NORFOLK, VIRGINIA 23511

Code 62/Pn  
20 June 1967

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E  
FOR OFFICIAL USE ONLY

NAVAVNSAFECEN INVESTIGATION 54-67

Ref: (a) NAVAIRREWORKFAC NORIS 282356Z April 1967  
(b) NAVAIRREWORKFAC Alameda 191918Z April 1967  
(c) NAVAIRREWORKFAC Alameda 270102Z April 1967  
(d) NAVAIRREWORKFAC NORIS 220118Z April 1967  
(e) NAVAIRREWORKFAC Norfolk 042204Z May 1967

1. INTRODUCTION

a. The Accident. A-3B, BUNO 138917, assigned to HEAVY ATTACK SQUADRON ONE TWO THREE (VAH-123) and piloted by LCDR Richard Earl PARKS, USN, (b) (6) crashed (ALFA) on a snow covered mountain at the 7000-foot level, at 1432(U), 5 April 1967, eight miles southeast of Alturas, California. The four occupants of the aircraft sustained fatal injuries in the crash. The crash site was in a U. S. Forest Preserve, and property damage was limited to broken trees.

b. Synopsis of Flight. The aircraft was enroute from NAS Miramar to NAS Whidbey Island on an instrument flight plan at Flight Level (FL) 180. Flight Level 220 had been requested, but was not available. The weather in the area was cumulus buildups with tops at FL 200. The assigned altitude, therefore, placed the aircraft in the clouds for at least some of the time. Moderate to occasionally severe turbulence was reported in the buildups. The aircraft was directed to change frequencies for hand-off from Oakland Center to Seattle Center, but no contact was made with Seattle Center. Radar contact was lost in the vicinity of Alturas, California, and search was initiated. The crash site was located by Forest Rangers.

2. INVESTIGATION AND ANALYSIS

a. History

(1) Pilot. LCDR PARKS had 2821 total flight hours. He was a student replacement pilot in VAH-123 and had 25 hours in the A-3. The flight had been scheduled as an instrument check as a part of the syllabus training. He had 3.6 hours of instrument flight in the A-3 prior to departure from NAS

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

FOR OFFICIAL USE ONLY

Enclosure (1)



FOR OFFICIAL USE ONLY

NAVAVNSAFECEN INVESTIGATION 54-67

Whidbey Island the previous day. His previous experience was primarily in A-1H aircraft. His jet experience consisted of 72 hours. He held a special instrument rating and was considered well qualified for this flight.

(2) Instructor Pilot. LCDR Donald Edwin KING, USN, (b) (6) had 4209 total flight hours of which 1786 hours were in jet aircraft and 833 hours in the A-3.

(3) Plane Captain. Carl Virgil MILLER, ADJ3, USN, (b) (6) was a well qualified crewman with about 1100 hours in the A-3. He was probably in the fourth seat as it is the procedure for the plane captain to secure the hatch prior to taxiing.

(4) Passenger. LCDR James Merritt READER, USN, (b) (6) was a passenger enroute to NAS Whidbey Island for duty. His log books were aboard the aircraft and were not recovered. He was probably in the third crew position.

(5) Aircraft. BUNO 138917 was accepted on 28 December 1956 and had accumulated 3749 total hours. The sixth PAR was completed in October 1966 and 440 hours were subsequently flown. A calendar ODD inspection was completed on 19 January 1967 and 246 hours were since flown.

(6) Engines

(a) J57-P-10, serial number P607625, had accumulated 2435 hours since acceptance. The fourth overhaul was completed on 9 July 1966 at NAS North Island and the engine had since operated 440 hours. A calendar ODD inspection was completed on 19 January 1967 and the engine had since operated 246 hours. J57 Engine Bulletin 535-A1 was reported by reference (a) to have been incorporated in February 1964 and verified during the last overhaul. This engine was installed on the port side.

(b) J57-P-10, serial number 632289, had accumulated 2076 hours since acceptance. The third overhaul was completed on 11 July 1966 at NAS North Island and the engine had since operated 440 hours. A calendar ODD inspection was completed on 19 January 1967 and the engine had since operated 246 hours. J57 Engine Bulletin 535-A1 was reported by reference (a) to have been incorporated in September 1965 and verified during the last overhaul. The engine was installed on the starboard side.

(7) Weather. The nearest weather reporting station was Klamath Falls, Oregon. At 1400 (U) the reported weather was 3000-foot ceiling with

FOR OFFICIAL USE ONLY

NAVAVNSAFECEN INVESTIGATION 54-67

light snow showers, temperature 40 degrees F, dewpoint 25 degrees F, with lowering ceilings. Cumulus buildups were to FL 200. The aeronautical weather at Alturas, California, nearby the crash site is unknown; however, persons on the ground recall the clouds to be well below the mountain peaks with occasional snow.

b. Field Investigation. The field investigation was hampered by a four-foot accumulation of snow. The location of parts was not practicable beyond the immediate impact area. The physical removal of heavy components required prodigious effort; and, upon removal of the engines, further salvage operations were postponed until the snow melted. Certain smaller engine accessories and airframe components were located and carried out by hand. Parts removed from the mountain were flown to the designated overhaul points for failure analysis.

c. Failure Analysis

(1) The airframe components were examined by NAVAIRREWORKFAC Alameda and the report of the analysis is reference (b) and amplified by reference (c). Pertinent findings of these analyses are:

(a) Both air turbine motors (ATM) were turning at impact.

(b) Aileron boost and surface control hydraulic pump, P/N AA 65319F6, showed no evidence of seizure.

(c) The remote attitude indicator (VGI) had the sphere distorted such that it appeared the impact attitude of the aircraft was vertical and tail down. While no correlation is suggested, it should be noted that a typical unit with power removed would assume the orientation observed in the damaged unit.

(d) One DC generator had indications of stationary axial impact. No evidence of rotation at impact was found on the armature.

(e) Wing fuel boost pump was running at impact.

(f) The emergency escape chute had not been fired. One recovered cartridge was tested and it fired within voltage and current limits.

(2) The engines and accessories were examined by NAVAIRREWORKFAC North Island, and the report of the priority disassembly inspection (PDIR)

FOR OFFICIAL USE ONLY

## NAVAVNSAFECEN INVESTIGATION 54-67

is reference (d). The port engine was concluded to be stopped or at low RPM at impact. The starboard engine was rotating at impact. No indication of malfunction was found in the engine accessories. The engines were incomplete as recovered. The first, second, third, fifteenth stages of the port engine compressor were missing; with the fourth and sixteenth stages unattached. The first five spacers from the N1 compressor were missing. The first and second stages of the starboard engine were missing; with the third, fourth, and sixteenth stages unattached. The first, second, and fourth spacers from the N1 compressor were missing.

d. Other Investigation and Analysis

(1) NORAD radar was tracking BUNO 138917 along his route of flight. The computer readout indicated a ground speed of 443 knots and a steady track of 340°, along J-5 airway. At 1431.9(U) the readout suddenly changed to 396 knots and 327° track. Very shortly thereafter the radar return disappeared. The geographic plot of the point of lost radar contact by NORAD was 5 to 7 miles further along the track than the Seattle Center radar (located at Klamath Falls). The variation could be an indication of an electrical power loss causing the IFF to become inoperative and cause the center radar contact loss prior to the loss of the radar return by the NORAD radar. The speed loss and the course deviation were duplicated by a pilot of VAH-123 by an intentional sudden power reduction on one engine. The maneuver also resulted in a severe yaw which caused considerable control problems from which the pilot was able to recover under the existing VFR conditions.

(2) The combination of left course deviation observed by NORAD radar and the stopped or low RPM condition of the port engine led to concern about the possibility of failure or seizure of the port engine. During the course of the investigation, another mishap occurred in a VAH-10 aircraft, in the Caribbean area, which was operationally similar to the hypothesis formulated in this accident. This second mishap did not result in a crash. Two crewmen had bailed out while the aircraft was out of control. Upon reaching a low altitude the pilot successfully regained control and landed the aircraft. The starboard engine was found to have suffered severe damage in the compressor area and had extensive damage to the engine pod nose cowl. A PDIR was performed at NAVAIRREWORKFAC, Norfolk. Reference (e) is the report of this investigation and cites the cause of the engine failure to have been the use of the old type second stage compressor rotor two-rail spacer, P/N 206973, rather than the currently required three-rail spacer, P/N 366490. The engine log book indicated that J57 Engine Bulletin 535-A1 (new spacer) had been incorporated. As noted in 2c(2) above, this spacer has not been recovered from the crash site.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

FOR OFFICIAL USE ONLY

NAVAVNSAFECEN INVESTIGATION 54-67

3. CONCLUSIONS

a. The cause of this accident is undetermined.

b. The possible cause is a loss of flight control due to severe yaw brought about by a failure of the port engine. An electrical power failure and temporary loss of hydraulic systems may have resulted from a pilot reaction to reduce power on the remaining starboard engine, causing the ATM's to fall below operating RPM. Such conditions in an instrument flight situation would render the aircraft uncontrollable due to the tumbled VGI, asymmetrical thrust, and limited hydraulic flight control. If, as in the VAH-10 mishap, the engine failure also caused compressor case and nose cowl damage, an undetermined but severe amount of asymmetrical drag would be experienced causing further control difficulty.

4. RECOMMENDATION. None, pending further salvage efforts which are planned when snow conditions permit.

Distribution:  
List A  
CNO (Op-05F)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

FOR OFFICIAL USE ONLY



## DEPARTMENT

COMMENTS FOR "CLOSE OUT" LETTER ON  
OF FINAL REVIEW

1. Negative report is required.  
2. Positive comments will be in a format suitable for inclusion in the "close out" letter.  
3. Attach additional sheets if more space is required.

## M&amp;M DEPT:

THE BOARD'S CONCLUSIONS AND RECOMMENDATIONS ARE BASED ON MEAGER FACTUAL INFORMATION AND MODERATE CONJECTURE. THE PRIMARY CAUSE OF THIS ACCIDENT WILL REMAIN UNDETERMINED UNTIL SUCH TIME AS ADDITIONAL INFORMATION MAY BE GLEANED FROM FURTHER INVESTIGATION, AS ADDITIONAL COMMENTS MAY BE RECOVERED.

LPX 221C 221  
INITIAL/CCDE

## AERO-MED DEPT:

The NAVAIRsyscom is having a study conducted to determine the feasibility of installing the YANKEE extraction system in the A3 type aircraft.

Concur with conclusions & recommendations of AAR & enclosures. H.W.P./433  
J.S./42.

INITIAL/CODE

## COMPLETION SHEET

Action to Correction to		Action Required	Completed Code/Date
3750-1			/
DIR			/
Misc. Items for Action or Correction			
To Code	From Code/Date	<del>1.02 - if you want to cut WX as a "misc" change index to 3, met <math>\frac{u}{1}</math> &amp; then you can add WX.</del>	(b) (6)
	/		/
	/		/
	/		/
	/		/
	/		/
	/		/
	/		/
	/		/

Endorsements Reviewed and Action Completed on All Phases of this Report.

UNIT VAA 143  
MODEL A3B  
BUNO 138917

AAR REVIEW ROUTING SHEET

ADVANCE ROUTING

PRI	DEPT	DATE IN	DATE OUT	INIT	INTER DEPT	ROUTING CODE/INIT
1	M&M	7-19-67	8-1-67	0		
	AERO MED	7-21-67	8-4-67	0		

DEPARTMENT REPRESENTATIVES INITIALS FOR RECEIPT OF REPORTS

REMARKS

ORIGINAL ROUTING

DEADLINE DATE OUT OF NASC 14 FEB 1968 (10 working days)

EXTENSIONS

DEPT	DATE IN	DEPT	DEADLINE	DATE OUT	INIT	INTER DEPT	ROUTING
A&R							

NASC ENDORSEMENT ROUTING

PRI	DEPT	DATE IN	DATE OUT	INIT
1	R&S	3-18-68	3-19-68	820
2	M&M		3-15	0
3	ADMIN			

ROUTING AFTER CLOSE OUT

DEPT	DATE IN	DATE OUT	INIT	INTER DEPT	ROUTING
AERO MED					

- NOTES
- 1 No person other than those assigned to the Records Control Branch will remove any part of this document from the folder
  - 2 Departments will be fully responsible and accountable for documents in their custody until checked back into Records Control Branch
  - 3 Any Department desiring to retain this report longer than five (5) working days must notify Records Control Branch of their need for extension.

25 JAN 1968

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES 123

FIFTH ENDORSEMENT on VAE-123 AAR ser 1-67A concerning A-3B BuNo. 138917  
accident occurring 5 April 1961, pilot PARKS

From: Commander, Naval Air Systems Command  
To: Commander, U. S. Naval Aviation Safety Center

Subj: Aircraft Accident Report

1. Forwarded.

2. The A-3 YANKEE Extraction tests have been basically completed by the contractor. It has been determined that the installation of the YANKEE Extraction system in the A-3 aircraft is technically feasible. Final determination on the requirement, priority and funding for the installation of the YANKEE Extraction system in the A-3 aircraft will be made by the Chief of Naval Operations.

(b) (6)

By direction

Copy to:  
COMNAVIAIRPAC  
COMREMAINTKCARAIRWING 12  
COMFAIRWIDBDBY  
NAVPLANTREPO LONG BEACH  
CO HATRON 123



1. DISASSEMBLY ACTIVITY NAVAIRWORKFAC ALAMEDA (300)		2. REPORT NO. 927	3. DATE OF R/I 16 Nov 67	4. ASSEMBLY NOMENCLATURE AND PART NO. Horizontal stabilizer actuator		5. P/N 5380824-549	6. ENGINE
7. DISASSEMBLY (Model)	8. ASSEMBLY (Serial)	9. ASSEMBLY MFR 88277	10. DATE REMOVED	11. REMOVED FROM (Eng Rod)	12. REMOVED FROM (Eng Ser)		
13. TOTAL HRS UNKNOWN	14. HRS SINCE LAST DIS UNKNOWN	15. DATE LAST S/W	16. LAST OVERHAUL ACTIVITY	17. NO. PREV D/W'S	18. AIRCRAFT (Model) A-3B	19. AIRCRAFT (S/N) 138917	
20. OPERATING ACTIVITY VAH-123		21. FOR LIFE, AAR, I/PW/SA		22. REASON FOR REMOVAL AND CODE Accident/incident damage		23. LB	

24. DISCREPANCY	25. BASIC MFG/DESIGN DISCREPANCY	26. NON-BASIC (MAINT/OPER) DISCREPANCY	27. FOREIGN OBJECT DAMAGE	28. PRIMARY PART FAILURE (Part No.)	29. COND	30. CODE
31. DESCRIPTION OF FINDINGS (Include name and part no. of primary part failure)				32. DISCREPANT PARTS (Part No.)	33. COND	

Ref: (a) VAH-123 msg 252311Z Oct 1967  
(b) NAVAIRWORKFAC ALAMEDA DIR 854 of 18 Jul 1967

a. A remaining part of the horizontal stabilizer actuator was recovered as reported by reference (a). This part was received for DIR as a continuation of reference (b), which reported the actuator was jammed by crash impact in approximately the neutral position.

b. Only the lower mounting portion comprising the housing assembly P/N 5380909-501 was received. The transmitter, AC motor assembly P/N XA30525 and DC motor assembly P/N D919 were torn away by crash impact and missing.

c. Disassembly disclosed no discrepancies other than those caused by crash impact.

**PRIORITY**

34. PRIORITY DIR	35. REQUESTED BY NAVAIRSYSCOMREPAC msg 310110Z Oct 67.	36. REFERENCE Control No. 3282-67.	37. DISC 114	38. APPLICABLE INCORPORATED	39. DATE 30 November 1967
40. (b) (6)			41. WEAPONS SYSTEMS ENGR DIV HEAD		

DISASSEMBLY AND INSPECTION REPORT, NAVJEPs FORM 4730/2 (11-61)

REPORT SYMBOL BUMPS 4730-2

27. CONCLUSIONS: There is no evidence to indicate this portion of the actuator was not operating satisfactorily prior to crash impact.

28. RECOMMENDATIONS: None.

**DISTRIBUTION:**

NAVAIRSYSCOMHQ (AIR-1113) (AIR-LOW)  
COMNAVAIRPAC  
COMFAIRALAMEDA  
NAVAIRSYSCOMREPAC  
NAVAIRSAFECEN NORVA  
NAVAIRTECHSERVPAC PHILA  
VAH-123  
NAVPLANTREPO LBEACH  
NAVAIRWORKFAC QUONPT  
NAVAIRWORKFAC JAZ

704051 -

3750

Ser 80/ 2397

SPECIAL HANDLING REQUIRED IN ACCORDANCE  
WITH OPNAVINST 3750.6 SERIES

8 JUN 1967

FOURTH ENDORSEMENT on VAH-123 AAR ser 1-67A concerning A-3B BuNo 138917  
accident occurring 5 April 1967, pilot PARKS

From: Commander Naval Air Force, U.S. Pacific Fleet  
To: Commander, U.S. Naval Aviation Safety Center  
Via: Commander, Naval Air Systems Command

Subj: VAH-123 AAR ser 1-67A

Ref: (a) OPNAVINST 3750.6E

1. Readdressed and forwarded for NAVAIRSYSCOMHQ comments concerning the recommendation contained in Part X concerning installation of the YANKEE Extraction system in A-3B aircraft.
2. The conclusions and recommendations of the Aircraft Accident Board, as modified by the remarks contained in subsequent endorsements, are concurred with.
3. The first endorsement does not show complete copy to distribution. By copy of this endorsement, the Commanding Officer, VAH-123 is requested to ensure complete copy to distribution in accordance with subparagraph 48h of reference (a).

(b) (6)

By direction

Copy to:  
NAVAIRSYSCOMHQ  
COMNAVAVNSAFECEN (2)  
COMREADATKCARAIRWING 12  
COMFAIRWHIDBEY  
NAVPLANTREPO LBEACH  
CO HATRON 123

3750

Ser 80/ 3097

SPECIAL HANDLING REQUIRED IN ACCORDANCE  
WITH OPNAVINST 3750.6 SERIES

8 JUN 1967

FOURTH ENDORSEMENT on VAH-123 AAR ser 1-67A concerning A-3B BuNo 138917  
accident occurring 5 April 1967, pilot PARKS

From: Commander Naval Air Force, U.S. Pacific Fleet  
To: Commander, U.S. Naval Aviation Safety Center  
Via: Commander, Naval Air Systems Command

Subj: VAH-123 AAR ser 1-67A

Ref: (a) OPNAVINST 3750.6E

1. Readdressed and forwarded for NAVAIRSYSCOMHQ comments concerning the recommendation contained in Part X concerning installation of the YANKEE Extraction system in A-3B aircraft.
2. The conclusions and recommendations of the Aircraft Accident Board, as modified by the remarks contained in subsequent endorsements, are concurred with.
3. The first endorsement does not show complete copy to distribution. By copy of this endorsement, the Commanding Officer, VAH-123 is requested to ensure complete copy to distribution in accordance with subparagraph 48H of reference (a).

(b) (6)

By direction

Copy to:  
NAVAIRSYSCOMHQ  
COMNAVAVNSAFECEN (2)  
COMREADATKCARAIRWING 12  
COMFAIRWIDBEY  
NAVPLANTREPO LBEACH  
CO HATRON 123

Code 015-ee

3750

Ser: 678

2 JUN 1967

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

THIRD ENDORSEMENT on VAM-123 AAR Ser 1-67 of 5 April 1967, A-3B BUNC  
138917, Pilot PARKS

From: Commander Fleet Air, Whidbey  
To: Commander, U. S. Naval Aviation Safety Center  
Via: Commander Naval Air Force, U. S. Pacific Fleet

Subj: Aircraft Accident Report; forwarding of

1. Forwarded. Commander Fleet Air, Whidbey concurs in the comments and recommendations of the Board as modified by the first two endorsements, except as noted below.
2. Insufficient evidence exists to include pilot deviation from NATOPS procedures as a contributing cause factor. The starboard engine was operating near the idle range; however, the reason for this is a matter of conjecture.
3. Commander Fleet Air, Whidbey concurs in the need of an extraction system for A-3 crew members. The number of possible saves for Whidbey based aircraft are correctly stated in the second endorsement. These do not include combat losses.
4. Plans for further investigation at the crash site are being made. It is estimated that the snow will have receded enough by 1 July to permit access to the area.

*J. H. Jaeger*  
J. H. JAEG

Copy to:  
NAVAIRSYSCEMIG  
COMNAVAVNSAFECEN (2)  
COMNAVAIRPAC  
COMRCVW-12  
NAVPLANTREP LBEACH  
HATRON ONE TWO THREE

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES



SECOND ENDORSEMENT on VAH-123 ser 1-67 of 5 April 1967, A3B BUNO 138917  
Pilot PARKS

From: Commander Readiness Attack Carrier Air Wing TWELVE  
To: Commander, U. S. Naval Aviation Safety Center  
Via: (1) Commander Fleet Air, Whidbey  
(2) Commander Naval Air Force, U. S. Pacific Fleet

Subj: Aircraft Accident Report; Forwarding of

1. Forwarded, concurring with the conclusions and recommendations of the board as modified by the remarks of the first endorser and with the following comments:

a. Exception is taken to the unsubstantiated remarks made by the medical officer in paragraph VII A.3. in the conclusions of his report. A review of the accident statistics for A3 aircraft reveals this is the third accident in 40 months in which an ejection system could have conceivably prevented fatal injuries. In one of these cases an ejection system with at least a "zero - zero", capability would have been required. This is not to say that an ejection system for A3 aircraft is not an urgent requirement. This endorser certainly recognizes the need for an escape system for crew members of all high speed/high performance aircraft. However, it is the opinion of this endorser that conclusions, and recommendations must be made from a basis of fact, and not from an emotional viewpoint.

2. It is noted that the instructor pilot for this flight had last completed the NATOPS Standardization Check on 8/14/64. Subsequent investigation reveals a sagging emphasis on this point in that two instructor pilots of VAH-123 are overdue for NATOPS qualification checks. It is further noted that a program, whereby each instructor is checked for NATOPS standardization in conjunction with his annual examination for proficiency in instrument flying, has been initiated. By copy of this endorsement the Commanding Officer, Heavy Attack Squadron ONE TWO THREE is directed to insure the standardization of each instructor, in accordance with current directives at the earliest possible date.

3. It is further noted that section A.19. of the Aircraft Accident Report Form 3750-1 should be changed to reflect altitude 7200 feet above mean sea level and zero feet above terrain.

*R. E. Gallatin*  
R. E. GALLATIN

SPECIAL HANDLING REQUIRED IN ACCORDANCE  
WITH OPNAVINST 3750.6 SERIES

Copy to:  
CO, VAH-123  
NAVAIRSYSCOMHQ  
COMNAVAVNSAFECEN (2)  
COMNAVAIRPAC  
COMFAIRWHIDBEY  
NAVPLANTREPO DALLAS

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

12 MAY 1967

FIRST ENDORSEMENT on VAR-123 ser 1-67 of 5 April 1967 A3B BUNO 138917 Pilot  
PARKS

From: Commanding Officer, Heavy Attack Squadron One Two Three  
To: Commander, Naval Aviation Safety Center  
Via: (1) Commander Readiness Attack Carrier Air Wing Twelve  
(2) Commander Fleet Air, Whidbey  
(3) Commander Naval Air Force, U. S. Pacific Fleet

Subject: Aircraft Accident Report; forwarding of

1. Forwarded concurring with the conclusions and recommendations of the board with the following exceptions:

a. Concur. Although it cannot be determined why the crew made no effort to abandon the aircraft, it must be re-emphasized that bailout is the proper course of action when faced with an emergency at altitudes less than 10,000 feet above the terrain. This is the NATOPS procedure and is taught to all A-3 flight crews. It will be continually re-emphasized at all crew meetings.

b. Do not concur. Flight crews must always be aware of the type of terrain below their aircraft. This information is available on other charts and its inclusion on the enroute FLIP charts would detract from what now is a highly useable inflight chart.

c. Do not concur. [REDACTED]

(b) (5)

d. Concur.

e. Concur. All possible efforts will be made to recover further wreckage and ascertain additional facts concerning the accident. Any new developments will be forwarded when available.

2. The board's conclusions and recommendations are based on a meager amount of factual evidence and much conjecture. The possibilities are almost limitless and the actual factors may never be determined. The port engine failure by itself would not cause the accident, but the action taken by the pilot or the instructor could have aggravated the emergency.

3. An examination of LCDR PARKS flight log shows that he had not been involved in a previous pilot caused accident.

4. The last COMNAVAIRPAC Accident Prevention Survey was completed on 30 March 1967

  
J. P. SUNDBERG

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6  
SERIES

From: Commanding Officer, Heavy Attack Squadron ONE TWO THREE


To: Commander, U S. Naval Aviation Safety Center

Subj: Supplementary Accident Data concerning VAH-123 AAR serial 1-67A.  
A3B BUNO 138917 occurring 5 April 1967. Pilot PARKS, Instructor  
Pilot KING  
submission of

Ref: (a) NASC ltr ser: 50/B155 of 19 APR 1967

- Encl: (1) Supplementary Accident Data Form for subject accident pages 1  
through 5 & 1-3  
(2) Reproduction of subject pilot's log covering month of accident  
and two (2) preceding calendar months and co-pilot's.  
(3) ~~CONTAINING DISCLOSURE INFORMATION~~  
(4) ~~ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED~~

1. As requested by reference (a), the enclosures are forwarded.

  
J. P. SUNDBERG

FOR OFFICIAL USE ONLY



FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6  
SERIES

SUPPLEMENTARY ACCIDENT DATA

In addition to answering the following questions, enclose a duplicate of the pilot's log covering the month in which the accident occurred as well as the preceding two calendar months.

1. Date of mishap: year 1967 month April day 5
2. Aircraft model A-3B
3. Bureau Number of aircraft 138917
4. Reporting custodian VAH-123
5. Pilot file number 584656
6. Branch of service: Marine        Navy X
7. Readiness Attack Carrier Air Wing (RCVW) trained? Yes        No X  
LINGERING RCVW TRAINING WHEN ACCIDENT OCCURRED.  
If Yes, date completed 1 / 1  
RCVW Squadron VAH-123
8. Percentage of training completed if in a formal training status 25%
9. Length of time (mo.) in present squadron 4mo
10. Pilot currently qualified in following aircraft (model and series)  
A3B TF9J

FOR OFFICIAL USE ONLY

AVIATORS FLIGHT LOG BOOK  
LCDR PARKS

[illegible]

LCDR PARKS


[illegible]



11. a. Specify training time (hrs.) with reference to date of mishap as follows:

	WST		OFT		CPT		LINK
	This model	All other models	This model	All other models	This model	All other models	
Previous 12 months			9	UNK			
Previous 6 months			9	UNK			
Previous 3 months			9	Ø			
Previous 1 month			9	Ø			

If training time in this model during previous three months was less than 3 hours in Weapons Systems Trainer (WST), Operational Flight Trainer (OFT), or Cockpit Training (CPT), indicate reason by checking appropriate spaces in part b.

b.	WST	OFT	CPT	LINK
(1) Pilot deployed				
(2) Trainer not in area (station _____)				
(3) Down for maintenance				
(4) Not available due to trainer schedule				
(5) Lack of trainer personnel				
(6) Not available due to pilot's schedule				
(7) Other reasons (specify): _____ _____				



## Co-Pilot Form

## FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6  
SERIES

## SUPPLEMENTARY ACCIDENT DATA

In addition to answering the following questions, enclose a duplicate of the co-pilot's log covering the month in which the accident occurred as well as the preceding two calendar months.

1. Date of mishap: year 1967 month April day 14
2. Aircraft model A-3B
3. Bureau Number of aircraft 138917
4. Reporting custodian VAH-123  
Co-pilot
5. ~~XXX~~ file number 575768
6. Branch of service: Marine        Navy X
7. Readiness Attack Carrier Air Wing (RCVW) trained? Yes X No         
If Yes, date completed 8 RB/61  
RCVW Squadron VAH-123
8. Percentage of training completed if in a formal training status
9. Length of time (mo.) in present squadron 16mo  
Co-pilot
10. ~~XXX~~ currently qualified in following aircraft (model and series)  
A-3B A-6A

FOR OFFICIAL USE ONLY

AVIATORS FLIGHT LOG BOOK  
LCDR KING

DAY	MODEL	SERIAL NUMBER	KING OF FLIGHT CODE	TOTAL PILOT TIME	FIRST PILOT	CO- PILOT	INST TIME DAY NIGHT	NIGHT VFR TIME	OTHER LAND OR SEA	STD INST APPR COM- PLETED	REMARKS
2-3-67	A-6A	152621	1A1	2.5	2.5		1.0 A 1.0 S		1	1JRA	BNAV-2
2-6-67	A-6A	152616	1A1	2.6	2.6		0.1 A 1.0 S		1	1JRS	
2-6-67	TA-3B	144856	1A1	4.1	4.1		1.4 A 3.0 S		1	1JRA	RN-3
2-9-67	A-6A	152616	1A1	2.3	2.3		1.0 A 1.0 S		1	1JRA	
2-14-67	A-6A	152616	1A1	2.5	2.5				1		
2-17-67	A-3B	138944	1R2	2.6	2.6				1	1JTS	NKY
2-23-67	A-3B	142364	3A4	3.8		3.8		3.8			
2-27-67	TA-3B	144867	1A1	2.0	2.0		0.5 A		1		RN-2
3-6-67	A-3B	142634	1A1	1.5		1.5					
3-7-67	A-6A	152617	1A1	2.1	2.1				1	1AS	
3-9-67	A-6A	152622	1A1	5.0	2.5	2.5	0.5 A 1.0 S		1	1GA	NW MIRAMAR
3-10-67	A-3B	142644	1A1	1.4		1.4	1.5 A 0.5 S		4	2GA, 2TA	
3-13-67	A-3B	142634	1A1	1.9		1.9					
3-15-67	A-6A	152901	1A7	2.0	2.0		0.5		1		
3-14-67	A-6A	152613	1A7	2.6	2.6		0.5 A 1.0 S		1	1RS	BWPS ING


AVIATORS FLIGHT LOG BOOK  
LCDR KING  
(CONT)

DAY	MODEL	SERIAL NUMBER	KING OF FLIGHT CODE	TOTAL PILOT TIME	FIRST PILOT	CO- PILOT	INST TIME		NIGHT VFR TIME	OTHER LAND OR SEA	STD INST APPR COM- PLETED	REMARKS
3-22-67	A-3B	138906	3A4	0.4		0.4						COA-64
3-22-67	A-3B	138921	1A1	2.5	2.5		0.7 A	1.0 S		1	1RA	NKX
3-16-67	A-3B	142634	1A1	3.0		3.0	1.0 A					NKX
3-27-67	A-3B	138917	1A2	1.9	0.4	1.5				2		
3-29-67	A-6A	152615	1A1	2.5	2.5		0.1			1		BNAV-4
4-1-67	A-6A	152900	1A7	2.3	2.3		0.1 A			1		NWW NWW
4-3-67	A-6A	152623	1A7	2.2	2.2					1		BDM
4-4-67	A-6A	152623	1A1	2.7	1.5	1.2	0.2			3	1GA	PFAM-1
TOTAL				56.4								

11. a. Specify training time (hrs.) with reference to date of mishap as follows:

	WST		OFT		CPT		LINK
	This model	All other models	This model	All other models	This model	All other models	
Previous 12 months	_____	_____	_____	_____	_____	_____	_____
Previous 6 months	_____	_____	_____	_____	_____	_____	_____
Previous 3 months	_____	_____	_____	_____	_____	_____	_____
Previous 1 month	_____	_____	_____	_____	_____	_____	_____

If training time in this model during previous three months was less than 3 hours in Weapons Systems Trainer (WST), Operational Flight Trainer (OFT), or Cockpit Training (CPT), indicate reason by checking appropriate spaces in part b.

b.	WST	OFT	CPT	LINK
(1) Pilot deployed	_____	_____	_____	_____
(2) Trainer not in area (station _____)	_____	_____		_____
(3) Down for maintenance	_____	_____	_____	_____
(4) Not available due to trainer schedule	_____	_____	_____	_____
(5) Lack of trainer personnel	_____	_____	_____	_____
(6) Not available due to pilot's schedule	_____	X	_____	_____
(7) Other reasons (specify): _____ _____	_____	_____	_____	_____



## FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6  
SERIES12. ~~XX~~~~XX~~

co-pilot's

13. Commanding Officer's rating of ~~XXXX~~ ability: Superior X

Average \_\_\_\_\_ Below Average \_\_\_\_\_

14. ~~XX~~a. ~~XXXXXXXXXXXXXXXX~~ \_\_\_\_\_b. ~~XX~~ \_\_\_\_\_15. ~~XX~~a. ~~XXXXXXXXXXXXXXXXXXXX~~ \_\_\_\_\_b. ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX~~ \_\_\_\_\_c. ~~XXXXXXXXXXXXXXXXXXXX~~ \_\_\_\_\_16. ~~XX~~~~XX~~~~XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX~~17. ~~XX~~~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~18. ~~XX~~~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~ \_\_\_\_\_

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6  
SERIES

12. If flight was a maintenance test flight, was pilot designated by Commanding

Officer as qualified maintenance test pilot? Yes ☐ No ☐

13. Commanding Officer's rating of pilot's ability: Superior ☐

Average ☒ Below Average ☐

14. Length of time (mo.) Commanding Officer

a. Has been aboard 3000

b. Has been in command of this squadron 3000

15. Estimate of total time (hrs.) involved in accident investigation by:

a. Accident board members 788

b. Wreckage recovery and salvage 710

c. Supporting Personnel 1220

16. Best estimate of operation and maintenance funds expended for investigation

and salvage (e.g. civilian salaries, O&R cost, equipment rental, etc.) \$23.00

Attach itemized breakdown. GASOLINE 12.50  
BLACK IRON PIPE 10.50  
\$23.00

17. Did funding cause a delay in wreckage recovery? Yes ☐ No ☒

If Yes, how long? ☐ (days)

18. Was equipment for wreckage recovery adequate? Yes ☒ No ☐

If No, list deficiencies. WRECKAGE RECOVERY LIMITED BY WEATHER AND

DENSE SNOWCOVER, LOCAL AUTHORITIES AND SMALL BUSINESS  
FIRMS PROVIDED MUCH ASSISTANCE AT NO COST.

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

19. Number of accident board members 4
20. Specify number of accident board members who have attended the following schools :
- a. Safety Officer's School, USC 0
  - b. Safety Officer's School, Monterey 0
  - c. Safety Center 5-day ASO School 1
  - d. Monterey Baccalaureate Curriculum Safety Course 0
  - e. SEE BELOW
  - f. None of the above
21. Specify by checking if the:

	Manufacturer's Technical Reps were			Manufacturer's Engineers were		
	Requested	Available	Utilized	Requested	Available	Utilized
Airframe	<u>      </u>	<u>X</u>	<u>X</u>	<u>      </u>	<u>X</u>	<u>X</u>
Engine	<u>      </u>	<u>X</u>	<u>X</u>	<u>      </u>	<u>X</u>	<u>X</u>
Other	<u>      </u>	<u>      </u>	<u>      </u>	<u>      </u>	<u>      </u>	<u>      </u>

22. Was pre-accident plan adequate? Yes X No

FOR OFFICIAL USE ONLY

INVESTIGATIVE ASSISTANCE<sup>4</sup> WAS PROVIDED BY  
 AVIATION SAFETY CENTER REPRESENTATIVE  
 COMFAIRWING/AVIATION SAFETY OFFICER  
 VAH-123 A-6 AVIATION SAFETY OFFICER  
 ALL GRADUATES OF SAFETY OFFICERS SCHOOL, USC

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6  
SERIES

23. Did previous training adequately prepare the accident board for its duties?

Yes X No     

(If answer to questions 22 or 23 is No, please make comments)

COMMENTS:

24. Has the command submitted any previous recommendation that included

factors similar to those associated with this mishap? Yes X No     

COMMENTS:

THIS COMMAND HAS MADE MANY RECOMMENDATIONS  
FOR SOME EJECTION SEAT ESCAPE CAPABILITY AND CONTINUES  
TO DO SO. THE NEED FOR AN ESCAPE SYSTEM IS  
REEMPHASIZED BY THIS MISHAP.

FOR OFFICIAL USE ONLY



1. NAME OF ACTIVITY: NAVAIKREWORKFAC NORIS 2. REPORT NO: 31 3. DATE OF D/T: 5-9-67 4. ASSEMBLY NOMENCLATURE AND PART NO: ENDING ☒ X

5. ASSEMBLY (Model): J57-P10 6. ASSEMBLY (Serial): P607625 & P632289 7. ASSEMBLY APP: 77445 8. DATE REMOVED: 4-5-67 9. REMOVED FROM (Eng Mod): 10. REMOVED FROM (Eng Ser):

11. TOTAL HRS SINCE REM: 12. HRS SINCE LAST USE: 13. DATE LAST USE: 14. LAST OVERHAUL ACTIVITY: 15. NO. PREVIOUS: 16. AIRCRAFT (Model): 17. AIRCRAFT (Serial):  
See Page 2 See Page 2 NAS NORIS See Page 2 A3B 138917

18. OPERATING NO ACTIVITY: VAH-123 19. FOR LIFE: AAR-1-67A 20. REASON FOR REMOVAL AND CODE: Aircraft Accident 4B

21. FINDINGS: ☒ NO DISCREPANCY ☐ BASIC (MFG/DESIGN) DISCREPANCY ☐ NON-BASIC (MAINT/OPER) DISCREPANCY ☐ FOREIGN OBJECT DAMAGE

22. DESCRIPTION OF FINDINGS (Include name and part no. of primary part failure): See attached sheets.

**Distribution:**

NAVIAIRSYSOMHQ (AIR-4113/53613/4012/504) NAVPLANTREPO L. BEACH  
NAVIAIRSYSOMREPAC NAVPLANTREPO E. HARTFORD  
NAVIAIRTECHSERVAFAC NAVAIKREWORKFAC NORVA  
NAVAVNSAFECEN NORVA  
COMNAVAIRPAC  
COMNAVAIRLANT  
NAVIAIRWORKFAC ALAMEDA  
COMFAIRWHIDBEY  
COMREADATKCARAIRWING ONE TWO  
HATRON ONE TWO THREE



COMNAVAIRPAC

COMNAVAIRLANT

NAVIAIRWORKFAC ALAMEDA

COMFAIRWHIDBEY

COMREADATKCARAIRWING ONE TWO

HATRON ONE TWO THREE

23. COMMENTS:

24. RECOMMENDATIONS:

See attached sheets.

25. PRIORITY:

☒ HIGH

26. REQUESTED BY:

27. REFERENCE:

(b) (6)

NAVIAIRSYSOMREPAC Control No. 3282-67 131804Z Apr '67

28. TITLE:

29. DATE:

DISASSEMBLY AND INSPECTION REPORT NAVWPS FORM 4730/2 (11-61)

WEAPONS ENGINEERING DEPARTMENT SUPT. 5/12/67

23. PRIMARY PART FAILURE (Part No.):

24. DISCREPANT PARTS (Part No.):

25. PERTINENT BULLETINS, CHANGE, ETC. INCORPORATED:

NUMBER YES NO

E.B. 535-A1 X

26. APPLICABLE INCORPORATED:

27. DATE:

28. DATE:

29. DATE:

REPORT SYMBOL DUNEPS 4730-2

NAVAIREWORKFAC NORIS PRIORITY DIR NO. 31

NAVAIRSYSCOMREPAC 131804Z April 1967 Control No. 3282-67 requested a failure analysis on J57-P10 engines, Serial Nos. P607625 and P632289, removed from A3B aircraft BUNO 1J8917, due to an aircraft accident. NAVAIREWORKFAC NORIS 220118Z and 282356Z April 1967 refer.

26. Description of Findings:

Supplemental Data to Form 4730/2

Engine Serial No. P607625

11. Total hours since new - 2864.5
12. Hours since last overhaul - 439.7
13. Date last overhaul - 18 July 1966
15. No. of previous overhauls - (4)

Engine Serial No. P632289

11. Total hours since new - 2076.1
12. Hours since last overhaul - 439.7
13. Date last overhaul - 19 July 1966
15. No. of previous overhauls - (3)

a. Visual inspection revealed that both engines had suffered major impact-type damage. Engine rotating components were found severed into five sections, as shown in enclosure (1).

b. Examination of damaged parts from L/H engine S/N P607625, i.e., N<sub>1</sub> and N<sub>2</sub> compressors, as shown in enclosures (2) and (3), respectively, revealed that the compressor blades were relatively straight and negligible rotor rotation was in evidence, indicating that engine speed was low RPM or rotors stopped at impact.

(1) Examination of the third and second stage turbine discs, as shown in enclosure (4), substantiates further that rotor speed of engine S/N P607625, was low RPM or stopped at impact, as indicated by the blade tip bending and absence of rotational rub marks.

(2) A review of the N<sub>1</sub> and N<sub>2</sub> compressors and discs of engine S/N P607625, revealed that Nos. 1, 2, and 3 discs were missing; No. 4 disc was found unattached; No. 5 disc was missing; Nos. 6 through 14 discs were found assembled together; No. 15 disc was missing and No. 16 disc was found unattached.

NAVAIREWORKFAC NORIS PRIORITY DIR NO. 31

c. Examination of damaged compressor parts of R/H engine S/N P632289, indicated rotor rotation at impact. Engine speed was probably in the idle RPM range, as disclosed by the anti-rotation right-angle bending and clipped-off N<sub>1</sub> and N<sub>2</sub> compressor blades shown in enclosure (5).

d. The No. 1 main bearings were missing from both engines. All other main bearings of both engines were examined and found to have operated satisfactorily prior to suffering impact damage.

e. Those parts of engine, S/N P607625 and P632289, affected by E.B. 535-A1 were not received; therefore, inspection could not verify physical incorporation of this bulletin.

f. Research of history data indicates:

(1) Engine S/N P607625 - NORIS shops engine assembly records indicate J57 E.B. 535-Amendment 1 incorporation was certified 9 July 1966; NAVWEPS Form 13090/40 indicates incorporation of J57 E.B. 535 Amendment 1 by NORIS on 3 February 1964 and certification of incorporation by NORIS on 9 July 1966.

(2) Engine S/N P632289 - NORIS shops engine assembly records indicate J57 E.B. 535 Amendment 1 incorporation was certified 11 July 1966; NAVWEPS Form 13090/40 indicates incorporation of J57 E.B. 535 Amendment 1 by NORIS on 25 September 1965 and certification of incorporation by NORIS on 11 July 1966.

g. Accessories:

(1) The pressurizing and dump valve removed from engine S/N P607625 was disassembled and examined without testing, because of impact damage; no indication of malfunction was found.

(2) The upper body group of one unidentified fuel control was received. These parts were examined; no indication of malfunction was found.


27. Conclusions:

a. Engine S/N P607625 was stopped or at low RPM at impact. Engine S/N P632289 was rotating at impact, probably in the idle RPM range.


b. Examination and analysis of engine components as received revealed no indications of malfunction.


28. Recommendations: None.


Encl: (1) NAVAIREWORKFAC NORIS Photo No. LAA-34898  
(2) " " " " " -34897  
(3) " " " " " -34895  
(4) " " " " " -34899  
(5) " " " " " -34896













ENCL 61



NNNNZCZCNASC729CSLA038  
RTTU JAW RUWJMUA5959 2002204-UUUU--RUCILSA.  
ZNR UUUUU

R 192204Z JUL 67  
FM NAVACREWORKFAC NORIS  
TO ZENI/NAVAIRSYSCOMREPAC  
INFO RUEDBHB/NAVAIRSYSCOMHQ  
ZENI/COMNAVAIRPAC  
RUWMFTA/COMFAIRWHIDBEY  
RUWJAPA/COMREDATKCRARIWING ONE TWO  
RUWMFTA/HATRON ONE TWO THREE  
RUCILSA/NAVAVNSAFCE  
RUEOHRA/NAVAIRTECHSERVFAC  
RUWMHVA/NAVAIREWORKFAC ALAMEDA  
RUWJNDA/NAVPLANTREPO L BEACH  
RUEDDPA/NAVPLANTREPO E HARTFORD

BT  
UNCLAS  
NAVAIRSYSCOMHQ PASS TO AIR-4113/504/53613  
A3B BUNO 138917 A/C ACCIDENT INVESTIGATION  
A. YOUR 280121Z JUN 67

1. REF A CONTROL NO. 3282-67 REQ AN ENGINEERING ANALYSIS ON MAIN FUEL CONTROL, P/N 507650-L16, S/N 20112, REMOVED FROM ONE ENGINE OF SUBJ

PAGE TWO RUWJMUA5959 UNCLAS  
A/C.

2. INVESTIGATION REVEALED:

- A. FUEL CONTROL SUFFERED MAJOR IMPACT DAMAGE.
- B. CONTROL MECHANISMS (CONTROL SHAFT, LINKAGE, BRACKET, AND LEVER ASSY, ETC.) WERE MISSING.
- C. FUEL STRAINERS WERE CLEAN.
- D. PRESSURE REGULATING VALVE - CLOSED POSITION (NORMAL). NO DISCREPANCIES.

E. FLYWEIGHT GOVERNOR ASSY - NO DISCREPANCIES.

F. CYLINDER CAM SPEED SENSOR - NO DISCREPANCIES.

3. CONCLUDE: DETERMINATION OF FUEL CONTROL OPERABILITY OR MALFUNCTION PRIOR TO IMPACT NOT FEASIBLE DUE TO MUTILATED CONDTION OF PARTS.

4. THIS IS A SUPPLEMENTAL REPORT TO NAVAIWORKFAC NORIS PRIORITY DIR NO. 31 OF 12 MAY 1967.

BT

729/67

Cog m+m  
Records

A3B 138917

704051--

JUL  
192204Z

1. OVERHAUL ACTIVITY NAVAIREWORKFAC ALAMEDA (300)		2. REPORT NO. 854	3. DATE OF D/I 12 Jul 67	4. ASSEMBLY NAME AND PART NO. Horizontal stabilizer actuator		ENGINE <input type="checkbox"/>
5. ASSEMBLY (Model)	6. ASSEMBLY (Serial)	7. ASSEMBLY MFR 88277	8. DATE REMOVED	9. REMOVED FROM (Eng Mod)	10. REMOVED FROM (Eng Ser)	
11. TOTAL HRS SINCE NEW Unknown	12. HRS SINCE LAST D/I Unknown	13. DATE LAST D/I	14. LAST OVERHAUL ACTIVITY	15. NO. PREV D/I'S	16. AIRCRAFT (Model) A-3B	17. AIRCRAFT (Serial) 138917
18. OPERATING ACTIVITY HATRON-123		19. PUR - SPR - AAR - I/PN/GA		20. REASON FOR REMOVAL AND CODE Accident/Incident Damage LB		
21. FINDINGS <input type="checkbox"/> NO DISCREPANCY		<input type="checkbox"/> BASIC (MFG/DESIGN) DISCREPANCY		<input type="checkbox"/> NON-BASIC (MAINT/OPER) DISCREPANCY		<input type="checkbox"/> FOREIGN OBJECT DAMAGE
22. DESCRIPTION OF FINDINGS (Include name and part no. of primary part failure)				23. PRIMARY PART FAILURE (Part No.)		
<p>Only the top mounting portion of the actuator was received at this Facility. It consisted of a fractured ball screw assembly and a damaged ball nut P/N 5660-2. These parts were jammed in position by crash impact. This position corresponded with the approximately neutral position or zero degree trim of the actuator.</p>				24. DISCREPANT PARTS (Part No.)		
25. PERTINENT BULLETINS, CHANGES, ETC. INCORPORATED				26. DATE		
NUMBER				YES NO		
27. CONCLUSIONS		28. RECOMMENDATIONS				
Actuator was in approximately neutral position or zero degree trim during impact.		None.				
29. PRIORITY D/I		30. REQUESTED BY		31. REFERENCE		32. DATE
(b) (6)		NAVAIRSYSCOMREPAC 280121Z Jun 67		Control 3282-67.		18 July 1967
33. SIGNATURE		34. TITLE		35. DATE		
		WEAPONS SYSTEMS ENGR DIV HEAD		18 July 1967		

DISASSEMBLY AND INSPECTION REPORT NAVJEPs FORM 4730/2 (11-61)

REPORT SYMBOL BUMPS 4730-2

DISTRIBUTION:  
 NAVAIRSYSCOMHQ (AIR-4113) (AIR-4011)  
 COMNAVAIRPAC  
 COMFAIRALAMEDA  
 NAVAIRSYSCOMREPAC  
 NAVAVNSAFECEN NORVA  
 NAVAIRTECHSERVPAC PHILA  
 HATRON-123  
 NAVPLANTREPO LBEACH  
 NAVAIWORKFAC QUONPT  
 NAVAIWORKFAC JAX

704051 -

PART I GENERAL

1. AIRCRAFT ACCIDENT BOARD APPOINTED BY <b>CO. HATRON-123</b>	2. SERIAL NO <b>1-67A</b>	3. DTG (LOCAL) OF MISHAP <b>051131U APR</b>	4. MODEL AIRCRAFT <b>A-3B</b>	5. BUREAU NUMBER <b>138917</b>
6. TO: Commander, Naval Aviation Safety Center	7. VIA: <b>Commander Readiness Attack</b> <b>Carrier Air Wing Twelve</b> <b>Commander Fleet Air Whidbey</b> <b>Commander Naval Air Force</b> <b>Pacific</b>	8. LOCATION OF MISHAP <b>41-17 N/120-16 W</b>	9. TIME OF DAY <b>AFTERNOON</b>	10. DAMAGE <b>ALFA</b>
11. TIME OF DAY <b>AFTERNOON</b>	12. TIME IN FLIGHT <b>1 + 15</b>	13. FLIGHT CODE <b>1/1</b>	14. CLEARED <b>FROM NAS MIRMAR TO N.S. WHIDBEY</b>	15. TYPE CLEARANCE <b>IFR</b>
16. BRIEF DESCRIPTION OF MISHAP <b>TERR. FT. COLLISION WITH GROUND</b>	17. ALTITUDE <b>450 E</b>	18. ALTITUDE <b>56,000 (EST)</b>	19. ELEVATION AT TIME OF MISHAP <b>5,720</b>	20. TERRAIN <b>7,200</b>
21. LIST MODEL BUREAU REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED: (Complete OPNAV Form 3750-1A for each A/C)				

FACTOR	FACTOR	FACTOR
1. PILOT ERROR IN TECHNIQUE/JUDGMENT	9. SERVICING PERSONNEL	17. WEATHER
2. PILOT DEVIATION FROM HATOPS PROCEDURES	10. LANDING SIGNAL OFFICER	18. DESIGN AIRCRAFT
3. PILOT INCORRECT OPERATION OF A/C SYSTEM	11. OTHER PERSONNEL (Specify)	19. DESIGN GROUND EQUIPMENT
4. PILOT OTHER (Specify)	12. ADMINISTRATIVE	20. DESIGN OTHER (Specify)
5. CREW	13. FACILITIES-RUNWAY OVER/UNDER TAXIWAY FLIGHT PATH	21. ROLLING/PITCHING DECK ROUGH SEAS
6. MAINTENANCE PERSONNEL	14. FACILITIES-NAV AIDS LANDING AIDS (CGA, CGALS, MINIMUM)	22. MATERIAL FAILURE/MALFUNCTION
7. MAINTENANCE SUPERVISORY PERSONNEL	15. FACILITIES-CATAPULT, ARRESTING GEAR (Ship or field)	23. UNDETERMINED
8. SUPERVISORY OTHER (Specify)	16. FACILITIES OTHER (Specify)	24. OTHER (Specify)

1. NAME (Last, First, Middle Initial)	2. GRADE	3. SERVICE NO.	4. SERVICE	5. AGE	6. YEARS	7. YEARS	8. GRADE	9. POSITION	10. GRADE
PILOT (last controls at time of mishap)									
<b>PARKS, Richard E.</b>	<b>1CGR</b>	<b>(b) (6)</b>	<b>USN</b>	<b>35</b>	<b>11 YRS</b>	<b>FRP</b>	<b>PILOT</b>	<b>A</b>	
CO-PILOT (identify & establish separate rows)									
<b>KING, Donald E.</b>	<b>1CGR</b>		<b>USN</b>	<b>36</b>	<b>14 YRS</b>	<b>INST</b>	<b>B/N</b>	<b>A</b>	

ITEM	ITEM	ITEM
11. ALL MODELS	17. CV LANDINGS DAY/NIGHT	ALL
12. ALL MODELS IN LAST 12 MONTHS	18. FOLP LANDINGS LAST 6 MONTHS DAY/NIGHT	IN MODEL
13. ALL MODELS IN LAST 3 MONTHS	19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED	IN MODEL
14. ALL SERIES THIS MODEL	20. NIGHT HOURS LAST 3 MONTHS	IN MODEL
15. ALL SERIES THIS MODEL (LAST 12 MONTHS)	21. TOTAL HOURS IN SETS (if not finished)	DATE
16. ALL SERIES THIS MODEL (LAST 3 MONTHS)	22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL	DURATION
23. DATE/GRADE LAST HATOPS STANDARDIZATION CHECK	24. TYPE INSTRUMENT CARD	

25. NAME (Last, First, Middle Initial)	26. GRADE	27. SERVICE NO.	28. SERVICE	29. AGE	30. YEARS	31. GRADE	32. POSITION
<b>MILLER, Carl V. Jr.</b>	<b>ADJ3</b>	<b>USN</b>	<b>(b) (6)</b>			<b>FATAL</b>	<b>P/C COCKPIT</b>
<b>READER, James M.</b>	<b>XX</b>	<b>LCGR</b>	<b>USN</b>			<b>VF-126</b>	<b>FATAL</b>
							<b>PAX COCKPIT</b>



## PART 1 GENERAL

1. AIRCRAFT ACCIDENT BOARD APPOINTED BY	2. SERIAL NO.	3. DTG (LOCAL) OF MISHAP	4. MODEL AIRCRAFT	5. BUREAU NUMBER
CO. HUTTON-123	1-67A	051431U APR	A-3H	138917
6. COMMANDER, Naval Aviation Safety Center	7. LOCATION OF MISHAP	8. TIME OF DAY	9. TIME IN FLIGHT	10. FLIGHT CODE
VIA	11. CLEARED FROM	12. TYPE CLEARANCE	13. AIRSPEED	14. A/C WEIGHT
15. BRIEF DESCRIPTION OF MISHAP	16. ELEVATION AT TIME OF MISHAP	17. S. L.	18. TERRAIN	
19. LIST MODEL, RUINO, REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete OPR-1 Form 3750-1 for each A/C)				

FACTOR	FACTOR	FACTOR
1. PILOT ERROR IN TECHNIQUE/JUDGMENT	9. SERVICING PERSONNEL	17. WEATHER
2. PILOT DEVIATION FROM NATOPS PROCEDURES	10. LANDING SIGNAL OFFICER	18. DESIGN AIRCRAFT
3. PILOT INCORRECT OPERATION OF A/C SYSTEM	11. OTHER PERSONNEL (Specify)	19. DESIGN CREW EQUIPMENT
4. PILOT OTHER (Specify)	12. ADMINISTRATIVE	20. DESIGN OTHER (Specify)
5. CREW	13. FACILITIES-RUNWAY, OVERRUN TAXIWAY, FLIGHT DECK	21. ROLLING/PITCHING DECK ROUGH SEAS
6. MAINTENANCE PERSONNEL	14. FACILITIES-NAV AIDS, LANDING AIDS (LOCAL, DCA, ILS, HARBOR)	22. MATERIAL FAILURE/MALFUNCTION
7. MAINTENANCE SUPERVISORY PERSONNEL	15. FACILITIES-CATAPULT, ARRESTING GEAR (Ship or field)	23. UNDETERMINED
8. SUPERVISORY OTHER (Specify)	16. FACILITIES OTHER (Specify)	24. OTHER (Specify)

1. NAME (Last, first, & middle initial)	2. GRADE	3. SERVICE NO.	4. DESIG.	5. BRANCH OF SERVICE	6. A/C	7. DATE OF MISHAP	8. BULLET	9. POSITION	10. DUTY
PILOT (see comments at back of mishap)									
CO PILOT (Specify & submit separate page 1)									
KING, Donald E.	LCDR	(b) (6)		USN	36	14	YES	PILOT	B/N

ITEM	ITEM	TOTAL
11. ALL MODELS	17. CV LANDINGS DAY/NIGHT	180
12. ALL MODELS IN LAST 12 MONTHS	18. FCPL LANDINGS LAST 6 MONTHS DAY/NIGHT	100 / 112
13. ALL MODELS IN LAST 3 MONTHS	19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED	8 / 10
14. ALL SERIES THIS MODEL	20. NIGHT HOURS LAST 3 MONTHS	5 / 5
15. ALL SERIES THIS MODEL LAST 12 MONTHS	21. TOTAL HOURS IN JETS (if jet mishap)	1786
16. ALL SERIES THIS MODEL LAST 3 MONTHS	22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL	4 April 1967
23. DATE/GRADE LAST NATOPS STANDARDIZATION CHECK	24. TYPE INSTRUMENT CARD	SPED

25. NAME (Last, first, & middle initial)	26. GRADE	27. SERVICE NO.	28. DESIG.	29. BRANCH OF SERVICE	30. A/C	31. DATE OF MISHAP	32. BULLET	33. POSITION



PART II MAINTENANCE MATERIAL AND FACILITIES DATA										
A. A/C HISTORY	1. DATE OF MANUFACTURE	2. FLIGHT HRS SINCE ACCEPTANCE	3. NO OF PAR/OVERHAUL	4. MONTHS SINCE LAST PAR/OVERHAUL	5. FLT HRS SINCE LAST PAR/OVERHAUL	6. LAST PAR/OVERHAUL ACTIVITY	7. TYPE OF LAST CHECK PERFORMED	8. FLIGHT HOURS SINCE LAST CHECK	9. DAYS SINCE LAST CHECK	
	28 Dec 56	3748.9	6	6	439.7	NAS	CAL. ODD	246.3	79	
B. ENGINE HISTORY	1. ENGINE MODEL	2. ENGINE SERIAL NUMBER	3. FLIGHT HRS SINCE ACCEPTANCE	4. NUMBER OF OVERHAULS	5. WAS DIR REQUESTED	6. FLT HRS SINCE LAST OVERHAUL	7. LAST OVERHAUL ACTIVITY	8. TYPE OF LAST CHECK PERFORMED	9. FLIGHT HOURS SINCE LAST CHECK	10. DAYS SINCE LAST CHECK
	(1) J-57 P607						NAS			
	P-10 625	2434.7	4	YES	439.7	NORTS	CAL. ODD	246.3	79	
	(2) J-57 P632						NAS			
	P-10 289	2076.1	3	YES	439.7	NO ITS	CAL. ODD	246.3	79	
C. COMPONENT HISTORY	1. COMPONENT INVOLVED NOMENCLATURE	2. MANUFACTURERS PART NUMBER	3. TOTAL HRS ON PART	4. NO OF TYP. HOURS	5. HOURS SINCE LAST OVERHAUL	6. OVERHAUL ACTIVITY	7. WAS DIR REQUESTED	8. SER. NO. TYP. AMPLE		
	(1) ATM					NAS				
	78P-247	352040-0-1	1746.2	2	543.6	AL-MED	YES			
	(2) ATM					NAS				
	PX-44-175	352030-0-2	1883.9	5	453.7	AL-MED	YES			
D. INCIDENTS & GROUND ACCIDENTS & REPAIRS	1. PARTS REPAIRED			2. PARTS REPLACED			3. DIRECT MANHOURS INVOLVED			
	PART NUMBER	NOMENCLATURE		PART NUMBER	NOMENCLATURE					
E. ENGINE FAILURES	JET ENGINE FLAMEOUT (Include intentional securing to prevent engine damage)									
	AT TIME OF FLAMEOUT	1. ALTITUDE	2. IAS	3. RPM	4. EGT	5. MANEUVER AT TIME OF FLAMEOUT	6. FUEL FLOW	7. ALTITUDE		
	18,000'	360K EST	UNK	UNK	LEVEL FLT	UNK	LEVEL			
	8. G FORCES	9. RELIGHT	10. ALTITUDE	11. IAS	12. MAX EGT	13. FUEL CONTROL	14. NO. RELIGHT ATTEMPTS			
	UNK	<input type="checkbox"/> ATTEMPTED <input type="checkbox"/> ACCOMPLISHED			<input type="checkbox"/> PRIMARY <input type="checkbox"/> MANUAL					
	15. ENGINE SYMPTOMS	16. CAUSE OF SYMPTOMS								
	UNK	UNKNOWN								
RECIPROCATING ENGINE FAILURE										
	17. ALTITUDE	18. IAS	19. ALTITUDE	20. RPM	21. MAP	22. TORQUE/BNP	23. FUEL FLOW PRESSURE	24. OIL PRESSURE		
	25. ENGINE SYMPTOMS	26. CAUSE OF SYMPTOMS								
F. OTHER REPORT	IDENTIFY OTHER REPORTS CONCERNING THIS MISHAP									
	1. AMPLE SERIAL NUMBER									
	2. DIR MESSAGE REQUEST DATE/TIME GROUP V4H-123 110345Z									
	3. OTHER									

1. EQUIPMENT INVOLVED <input type="checkbox"/> CATAFULT <input type="checkbox"/> AIRCRAFT		2. PRESSURE SETTING		3. WIND OVER DECK		4. RELATIVE WIND		5. APPROACH AND SPEED	
6. HIRE NUMBER		7. HIRE NUMBER		8. LOCATION OF SHIP		9. LAUNCHING BRIGGS TWO INDELT ARRESTER			
10. DATA/UT/APP/... OF NON GRADE USED									
11. This portion shall be completed whenever (1) an aircraft accident involves arresting gear barrier and/or barricade equipment or (2) an aircraft accident involves malfunctioning of arresting gear barrier and/or barricade equipment. Incidents of routine damage to cables, windings and other approachable equipment need not be recorded herein.									
12. ENGAGED		13. DECK RAM BURNOUT TRAVEL (FEET)		14. CONTROL VALVE SETTINGS CONSTANT PRESSURE DOML (P.S.I.)		15. CONSTANT RUNOUT (WT. LBS.)		16. ACCUMULATOR PRESSURE (PSI)	
17. DECK PENDANT		18. DECK PENDANT		19. BARRIER BARRICADE		16. COMMENTS (for cable failures specify no. landings and months in service)			
FOR ACCIDENTS ABOARD CARRIERS (continue on page 2)									
1. DATE DEPLOYED/CONTR.				2. DAY HOURS/LANDINGS SINCE DEPLOYMENT				3. DAY HOURS LANDING LAST 30 DAYS	
4. TWO DAYS OPERATING PERIOD				5. NIGHT HOURS/LANDINGS SINCE DEPLOYMENT				6. NIGHT HOURS LANDING LAST 30 DAYS	
7. INST. HOURS/LOADS SINCE DEPLOYMENT ACTUAL/IMAGINED									
WEATHER AT SCENE OF MISHAP									
1. SEATING		2. VISIBILITY		3. RELATIVE WIND DIRECTION AND VELOCITY		4. TEMPERATURE RUNWAY OUTSIDE AIR		5. CLOUD POINT	
6. ALTITUDE SETTING									
OTHER WEATHER CONDITIONS (clouds, drizzle, fog, rain, snow, density, turbulence, etc. as appropriate)									
See weather enclosure.									
PART II (ADDITIONAL INFORMATION)									
PART		SECTION		ITEM		REMARKS		COPY DISTRIBUTION	
						Time extension granted by CNAP 202226Z APR 67		200 NAVJAG/INSTR DIRECTOR 100 JAGMERS DIRECTOR 100 COMNAVJAG 100 COMSALM HIDEBOY 100 COMECV-12 100 PLANT 1000 LONG BEACH	
3. GOVERNMENT PROPERTY									
COST DAMAGE TO: Various trees of unknown value									
4. PRIVATE PROPERTY									
DATE SUBMITTED TO: 5 MAY 1967									
PART III SIGNATURES OF THE BOARD									
1. (b) (6)		OPERATIONS OFFICER		2. (b) (6)		SAFETY OFFICER		UNIT FILED	
3. (b) (6)		FLIGHT SURGEON		4. (b) (6)		MATERIAL OFFICER		UNIT FILED	

When preparing Incident and Ground Accident reports, items indicated by an asterisk in the upper right hand corner must be filed in. Other items considered appropriate should also be filed in.

V THE ACCIDENT

On 5 April A3B BUNO 138917, NJ309, departed NAS Miramar at 1316 local for NAS Whidbey Island via Bakersfield, J-5 Seattle direct NAS Whidbey at flight level 220, airspeed 450 knots TAs. The flight progressed normally, deviating from filed flight level to 180. At 1428 approximately 95 nautical miles SSE of Lakeview VORTAC Oakland Center advised 138917 to contact Seattle Center on frequency 306.3 MCS. This transmission was acknowledged with no statement of difficulty. At 1430 the aircraft reported at flight level 180 to Seattle Center but did not acknowledge when subsequently requested to SQUAWK IDENT. At 1431 Seattle Center observed the aircraft make an abrupt left deviation from flight track and disappear from radar at 41 - 27N, 120 - 15W.

Agencies concerned were alerted at this time and at 1630 search and rescue attempts were initiated by Air Rescue Center at Hamilton AFB. At approximately 1430 a witness 8 1/2 miles from the scene heard an explosion and observed smoke. He subsequently notified the MODOC county sheriff in Alturas, California. Search and rescue aircraft maintained a vigil over the scene throughout the remainder of the day and all during the night. Search efforts were hampered by dense cloud cover and restricted visibility in snow showers. The following morning, 6 April 1967, the MODOC county sheriff in a light civil aircraft visually spotted the wreckage at 41° - 17'N, 120° - 16'W. The wreckage was located on the western side of the Warner Mountain range at 7400' level amidst a forested area with snow depths approximately 4 - 6 feet (see enclosure 2). Coincidentally, a ground party of two U. S. Forest Rangers assigned to the Modoc National Forest reached the scene via snow tractor and established that there were no survivors at the wreckage site. A navy flight surgeon, dropped by helo later during the day, verified that there were no survivors at the crash scene. On 8 April the navy aircraft accident investigative team from V.H-123 established that all four occupants had remained with the aircraft and further search efforts terminated. Rescue report, OPN.V form 3750-13 is contained as enclosure (3).

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPN.VINST 3750.6E

## VI DAMAGE TO AIRCRAFT

The aircraft sustained ALFA damage as a result of impacting a thickly forested area in a 35° nose down, upright attitude. Explosion occurred following impact with several massive trees and wreckage was strewn over an area approximately 2000' X 500' against a rising 40° slope in a conical expanding pattern. Complete examination of the wreckage was not possible due to heavy snow cover and fallen trees in the initial impact area. Prior to impact the aircraft had severed numerous trees as it approached the ground. The area upslope showed patchy areas of residual ground fire of short duration. Fragments of nose radome and port outer wing panel were located along the flight path 350 feet prior to the impact area. Fragmentation of the aircraft was severe and no components were found intact. Engines were located up slope from the impact center, the port engine broken into 2 major sections and the starboard into 3 sections. All recovered engine sections and accessory components that could give evidence of inflight operation were salvaged and shipped for DIRM.

Portions of both ATM's and accessories were located close to the left side of the impact area. Scroll and nozzle guide vanes from both ATM's were found. Stators to both AC generators, a DC generator housing, a DC armature, pressurization turbine, and wing fuel pump were located in the same vicinity. An ATM turbine and an internal section of hydraulic pump were found approximately 300' upslope. These parts were submitted for DIRM.

A number of cockpit instruments were recovered. The T/CAN DME gauge, VGI, standby gyro, angle of attack and turn & bank were found and submitted for DIRM. A portion of fiber glass curtain approximately 1½' X 2½' was recovered and found charred though its location was in an upslope area devoid of other ground fire indications. One of the two escape chute actuating cylinders, found nearly intact, was submitted for DIRM.

See enclosure (4) for a general wreckage diagram. This diagram does not indicate all wreckage found but is submitted to permit a better understanding of the crash site. A great number of components of interest to the investigators were not recovered due to thick snow cover (4 to 6' in depth) and continued snow flurries which daily recovered the site.



## VII THE INVESTIGATION

### A. Flight Investigation

On 4 April 1967 the aircraft had flown to NAS Miramar for the dual purpose of conducting an instrument training flight for LCDR PARKS and providing transportation for LCDR KING and LCDR (b) (6) for attendance at a 0800 5 April COMCEN-12 conference. LCDR KING served as flight instructor for the flight to Miramar. The landing at Miramar was exceptionally hard as noted in LCDR (b) (6) statement (enclosure (5)). It was not in his mind severe enough to be considered a "hard landing" of sufficient magnitude to require an inspection. No repairs were conducted on the aircraft.

The following day 5 April 1967 the aircraft was scheduled for a 1300 departure from Miramar to Whidbey Island. The flight was properly constituted as an instrument training flight with LCDR PARKS as replacement pilot in the pilots seat, the instructor pilot LCDR KING occupying the bombardiers seat, ADJ3 MILLEN as plane captain and LCDR READER as passenger. It is not known which seat positions LCDR READER or ADJ3 MILLEN occupied.

The flight was properly filed (see enclosure (6)) and departed NAS Miramar at 1316 via direct Bakersfield, J-5 Seattle direct Whidbey Island with FL 220 assigned. In the Los Angeles Center area of control the aircraft was descended to FL 180 for reasons unknown. A study of the complete flight tape transcripts does not reveal any reason for descent to lower altitude.

Flight thru the Oakland area was uneventful till after passing the Reno 155/78 radial. At 1419 numerous calls were made by Oakland Center with no acknowledgement. From then until last contact at 1431 radio communications were intermittent. See enclosure (7) for a transcript of communications during this period. At 1431 Seattle Center observed on radar the aircraft deviate from flight track in a sharp left turn and disappear from contact at 41 - 27N, 120 - 15W.

NORAD radar maintained a plot on the aircraft till losing contact at 1431.9. A plot of their computerized track (see enclosure (2)) shows a left deviation from track commencing at 1429.4 with increased left turn aggravation occurring at 1431.5. The last reliable fix was at 1431.9. During the period of left track deviation the ground speed slowed from 463 KTS to 396 KTS. The portion of final track from 1431.5 to 1431.9 records a change of ground speed from 443 KTS to 396 KTS. Last contact from the NORAD plot occurred at 41 - 20N, 120 - 13W.

The actual crash location was sighted by a witness 8 1/2 miles from the scene (see enclosure (8)) who heard an explosion and saw smoke. His subsequent report via telephone to the county sheriff in Alturas, California was instrumental towards visual spotting of the wreckage the following day. The correct crash location was established as 41 - 17N, 120 - 16W.

## B. Site Investigation

The crash occurred in a moderately forested area in approximately 4 feet of snow with higher drifts. Trees of varying trunk size from 6 inches to 2 feet in diameter were severed and or fallen both prior to ground contact and following. Others were canted at varying degrees from vertical from the impact point forward along the path of the crash. Elevation of the impact point was approximately 7200 feet with wreckage strewn over a 500' X 2000' area against a rising 40° slope to 7400'. Site photos are contained as enclosure (9).

Examination of the site and severed trees along the flight path indicates that the aircraft initially encountered the top of a tree in a nose low, slight right wing down condition heading 205° magnetic. Continued tree contact for approximately 400 feet at a 35° dive angle caused the aircraft to impact the ground in a slight left wing down condition. Explosion occurred upon contact with the trees. The identification and positioning of the wreckage confirmed that the aircraft had been in an upright attitude with some degree of left wing down condition at impact. At or near the impact point no indications of ground fire existed. However, upslope 300' to 900' slightly burned patchy areas were evident indicating residual ground fire of short duration.

Major sections of both engines were located. The port engine sections were to the left of the crash path. All sections were severely damaged with some discs and the majority of compressor and turbine blades missing. Very little engine case remained attached to the main bodies. Shafts showed little evidence of torsional failure. A number of Z bent compressor & turbine blades were found, some remaining on the engine, others located from digging efforts. No large compressor blades from the port N-1 compressor were located. Major pieces of fuel control, fuel heater and oil filter were found near the left side of the impact point. All port engine components and accessories that could be found were shipped to NAS North Island for DIR. Enclosure (10) contains photographs of engine sections.

The starboard engine was found in three sections. The compressor and burner sections were partially surrounded by engine casing while the turbine section was devoid of external cover. Again, the majority of blades were missing from the engine, however, numerous blades were recovered along the starboard side of the flight path. Shafts showed some evidence of torsional failure. No engine accessories to the starboard engine were found. All components located were sent to NAS North Island for DIR. Starboard front engine sections, speedrings or oil coolers were not located.

It could not be definitely established that the airframe was intact at the time of the impact. Portions of the upper vertical stabilizer, rudder assembly, horizontal stabilizer, port aileron counter weights and outer wing panel skin were identifiable. Wing, horizontal stabilizer, and elevator extremities were not located. The recovery of small

fragments conditionally identified as outer wing panels, elevators and ailerons tends to imply a completeness. However, evidence recovered is insufficient to state irrefutably an intact airframe.

Portions of both air turbine motors and accessories were recovered and inspected for evidence of rotation or inflight operation. Both ATM shrouds and an ATM turbine wheel were intact and some slight degree of rotation was evident on all units. See enclosure (11) for photographs of all airframe accessory components. The pressurization cooling turbine and exhaust vanes showed some indications of turning at impact. Both AC generator stators, one DC generator stator, one DC generator armature, and portions of a hydraulic pump were examined and showed little or no evidence of rotation. All components were shipped to NAS Alameda for DIR.

An AC wing fuel transfer pump was recovered and submitted for DIR. A nearly intact escape chute firing cylinder was recovered and submitted for DIR.

Pilot cockpit instruments recovered included the VGI, standby gyro horizon, TACAN (ID-310), oil temperature gauge, angle of attack, and turn and bank indicator. The VGI indicated the aircraft to be in an inverted nose high attitude. This is a like position a VGI assumes when power is lost from the instrument. The standby gyro horizon face was obliterated and nothing could be determined from this instrument. The TACAN DME (ID-310) showed a mileage indication at 76 NM, however, the OFF bar was missing. The oil temperature gauge indicated 150° on the starboard engine but no reading was possible on the port since the needle was missing. The angle of attack face had an OFF flag indication implying no power to the instrument. The turn & bank instrument reading indicated a slightly less than a half standard rate right turn. All instruments were submitted for DIR.

All wreckage was closely examined for signs of inflight fire. An unidentified piece of impregnated fiberglass cloth approximately 1 1/2' X 2 1/2' in size bore some evidence of possible fire and overheating prior to impact. It was found in an area of no surrounding ground burn indications. All other wreckage was examined for evidence of burning or overheating inflight. The fiberglass material was submitted for DIR.

There was no indication of any survival equipment having been utilized. All parachutes were located in the crash site and remained attached to torso harness KOCH fittings. All survival equipment suffered severe crash damage. Limited evidence indicated that some seat belts and shoulder harnesses were still fastened.

Dense snow cover severely hampered the recovery of additional pertinent wreckage. Daily snow flurries frequently covered previous days efforts and restricted movement by helicopter. Access by ground means via truck, snow tractor and snowshoes was limited by the carrying capacity of the snow tractor and the excessive traveling time required. (6 hour round-trip)

### C. Aircraft History

A3B BUNO 138917 was accepted by the Navy from Douglas Aircraft Co. on 28 December 1956. Subject aircraft was in the seventh (7) month of service period number seven (7) with the last progressive aircraft rework being completed at NAS Alameda on 16 September 1966. Wing damage was received during a carrier landing on 5 May 1959. Repair of the outboard wing panel, wing tip and starboard engine nacelle was effected by O & R Alameda. Due to corrosion, the aircraft was restricted from loft bombing in Oct 1962 with subsequent replacement of upper left and right hand wing skins. Grindouts in lower wing skins were within allowable tolerance and repairs were completed by NAS Alameda on 21 June 1963. On 14 Aug 1963 the aircraft received class "C" damage as a result of a port engine failure and partial engine disintegration. Numerous holes were patched in the fuselage and the upper vertical stabilizer and rudder assembly. The center wing slat, L/H main landing gear door, L/H pylon and nacelle, fuel dump and outlet assembly were replaced by an O & R Field team.

The above history is from the aircraft log book. The following history was obtained from the contractor and is included without amplification:

- a. 9 Jan 1960 tail hook and shank failure.
- b. 13 Feb 1960 wheels up landing due to hydraulic failure, Echo damage.
- c. 4 Sep 1960 Delta damage to nose section from taxi accident.
- d. Oct 1960 5" crack in keel repaired.

Both engines were installed during PAR at NAS Alameda in September 1966. Since installation, the accumulated time had been 439.7 hours. Total time since acceptance by the Navy was 2864.5 hours on the port engine, and 2076.1 hours on the starboard engine. Total time since overhaul was 439.7 hours on the port engine, and 439.7 hours on the starboard engine.

Routine maintenance was performed with no unusual incidents recorded on the engines during this operating period.

Total accumulated flight time since acceptance was 3748.9 hours. Total flight time since last PAR was 438.6 hours. Twelve (12) weeks and six (6) days had elapsed since the last "ODD" aircraft inspection was performed.



A complete review of the log book indicates all applicable directives that were required to make the aircraft operational had been performed. The following "F" code technical directives had not been completed.

AFC 303 - Wing Tank Pressurization Vent

AFC 380 - Radome Boot

AFC 382 - High Frequency Antenna

AFC 388 - Flex Waveguide

AFC 395 - Periscope Cover Switch

AFC 404 - MLG Wheel Bearing

AFB 77 - Flap Hinge Fitting

AFB 88A - Fuel Filter Installation

The following Aircraft Service Changes and Airframe Changes were not incorporated by higher level maintenance activities.

28	Receiver Probe & New Lox
228	Baird Atomic Sextant
336	MOD ARC-27 ANT Cable
363	Tail Cone Removal/Blank off inlet scoop
376	ATM Ejector Duct Assy Replacement
377	Bleed air System (Bleed Air Pylons Shutoff)
390	Flap Hinge Fittings Change
395	Periscope
405	Wing Slat Track (Reinforcement)

A review of the last ten "B" sections to the OPNAV form 3760-2 was not possible since there documents accompanied the aircraft. Therefore the Maintenance Officer's statement (enclosure (12)) contains a listing of work orders from the maintenance control register for the period 22 March to 4 April. Oil consumption rates were checked and found to be normal on both engines.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

#### D. DIR Investigation

The engine DIR was accomplished by the Naval Air Rework Facility, North Island. Their message report is contained in enclosure (13). As stated both engines received major impact damage.

A study of the port engine indicated low or no RPM on impact. Subsequent telephone conversation revealed that in addition to the missing number one (1) main bearing, the first three (3) stages of the N-1 compressor section were also absent. No evidence was discovered to establish an engine malfunction.

The starboard engine was rotating at impact and investigation revealed no evidence of malfunction. As with the port, the starboard engine number one (1) main bearing was missing.

Naval Air Rework Facility, N.S. Alameda conducted the investigation on the ATM components, airframe accessories and cockpit instruments. Their message report is contained in enclosure (13).

The following evidence was established:

1. Both air turbine motors were turning at impact.
2. Screw failure on an AC generator indicated unit rotating on impact.
3. One DC generator bearing damage indicated stationary axial impact.
4. Pressurization turbine turning at impact.
5. Wing fuel AC boost pump running at impact.
6. Aileron and surface control hydraulic pump had no evidence of seizure.
7. Escape chute cylinder had not been fired.
8. The T/CAN DME (ID-310) indicator reading at 76NM is probably reliable within plus three, minus four miles.
9. Angle-of-attack indicator face read OFF, no angle-of-attack reading possible.
10. Burned fiberglass material identified as a portion of fuel tank liner surrounding the aft or forward fuselage fuel cell. Marks and burn pattern could not be established as having occurred inflight.

All other materials shipped for DIR yielded no pertinent facts unknown to the accident board.

## E. Crew Factors

The crew was properly prepared for the return flight from NAS Miramar to NAS Whidbey. There is no evidence of adverse physical or psychological factors effecting crew performance.

LCDR PARKS a replacement pilot on an instrument training flight had demonstrated slightly above average ability in the A3B. Initial jet aircraft experience had been acquired in VF-126 just prior to reporting to VAH-123. In VF-126 he amassed a total of 55 hours in the TF-9J demonstrating above average ability in the jet transition phase and average proficiency in the instrument phase. He had met all requirements for flight in the A3B. Ditching and bail out drill had been completed on 10 February 1967. A resume of LCDR PARKS's past five years of flight experience is contained in enclosure (14).

LCDR KING, the instructor pilot with 4200 total flight hours had compiled a total of 833 hours in the A3B. He held a current SPECIAL instrument rating and was considered qualified for flight operations in the A3B. It should be noted that LCDR KING maintained a dual aircraft qualification in the A6A. As senior squadron LSO it was necessary that this dual qualification be maintained. A resume of LCDR KING's past five years flight experience is contained in enclosure (14).

ADJ3 MILLER, was a designated A3B plane captain with over 1100 hours in the aircraft. He was considered qualified for flight operations in the A3B.

LCDR READER, a passenger, with orders to VAH-123 for A6A training was not qualified in the A3B. Information on LCDR READER's past flight experience is not available. It is assumed that he had been properly briefed on emergency escape procedures from the aircraft, however no formal ditching and bailout drills were given.

## F. Weather Investigation

Enclosure (15) is an analysis of weather conditions in the area of the crash. The weather is interpolated from reporting stations nearest to the site and is considered an expert estimate of prevailing weather at 1430 5 April 1967.

Capt. (b) (6) USN, on 5 April in a F-101 from Kingsley AFB was vectored to the scene by Seattle Center for a communications search at the time of the mishap. His statement, enclosure (16), is in basic agreement with the weather estimate.

## VII THE ANALYSIS

### A. Flight Analysis

The return flight to NAS Whidbey Island was planned for and originally flown at FL 220. The flight was descended to FL 180 shortly after initial level-off, probably because of conflicting traffic.

Flight progress was normal until the aircraft experienced intermittent UHF radio difficulties approximately 25 minutes prior to the crash. It should be noted that this particular area on J-5, between Lakeview and Reno, has in the past been an area of poor communications in many A-3B aircraft. Voice communications that were completed between 1406 and 1430 were normal and indicated no difficulty.

Three minutes before impact the aircraft commenced left turn deviation. The turn began at 1429.4 with the aircraft heading 352°, 463 KTS ground speed. From then until 1431.5 left turn increased to 339° and ground speed decreased to 443 GS. From 1431.5 to 1431.9, left turn rate increased drastically from 339° to 327°. Ground speed reading during this time interval dropped sharply from 443 to 396 GS. Actual altitude is not known.

The position of last reliable radar contact was three miles from the impact point.

The aircraft initially contacted numerous trees at a 35° dive angle in a slight right wing down, upright attitude. Tree contact caused the aircraft to roll to a slight left wing down condition at ground impact. Final aircraft heading was 205° magnetic.

The only witness, Mr. BROOKS, stated he could not see the top of Eagle Peak five miles distant from the crash scene. He did state that he could see the ridgeline at the crash site. Eagle Peak elevation is 9883' while the crash site is at the 7400' elevation. Somewhere between these altitudes the aircraft reached VFR conditions. Since the aircraft crashed in a nearly wings level condition it is possible that the pilot had some degree of control over the aircraft and was attempting to recover from a steep dive.

### B. Material Failure/Malfunction

The following evidence supports inflight port engine failure:

- (1) DII investigation revealed little or no rotation on impact.
- (2) The flight track deviated to the left.
- (3) Ground speed slowed from 463 KTS to 396 KTS.

The following additional facts further substantiate port engine failure and infer catastrophic disintegration inflight. A review of past catastrophic failures in the A3B revealed several cases



where control of the aircraft was momentarily lost or marginal. IFR conditions would aggravate this problem. The first three stages and number one main bearing of the N-1 compressor section were not found in the wreckage. No large N-1 compressor blades were located as belonging to the port engine. Oil coolers, fairings or speed rings were not recovered. A secured engine would have been windmilling at a much higher rotational speed than was indicated in the DIR. DIR on recovered engine sections found no cause for engine stoppage.

The starboard engine was running at impact at low or IDLE RPM. No evidence was found contrary to the belief that it was functioning normally.

Analysis of ATM's and accessories indicate operating conditions. A variance exists between the DIR message report that the ATM's were running at impact and that a DC generator indicated only impact damage. Since the DC generator is spline shafted directly to the ATM gear train it is not likely that an ATM can be rotating without rotation on the DC generator. A sheared generator shaft or broken gear train would be the only circumstances that would allow such an event. Since generator shafts have a designed shear strength, a failure from a sheared shaft remains a possibility. In any event, the seizure or stoppage would not adversely effect the operation of the other DC generator or the battery.

A study of cockpit instruments indicates a probable number one AC generator power loss of unknown duration prior to impact.

The TACAN (ID-310) DME indicator showed a fixed range at 76NM. DIR results stated this reading possible within plus three minus four miles. When AC power is taken from the instrument the mileage indication stops and records the last mileage received. A loss of LOCK ON is manifested by continually spinning counters. Had power from the number one AC been available, the aircraft would have LOST LOCK ON when below the line of sight to Lakeview and the DME counters would have revolved to some number indication of 0 to 199. To have lost LOCK ON and revolved to a 76NM reading at impact seems remote. A measure of TACAN distance from Lakeview VORTAC to the impact point is 72 nautical miles.

The remote attitude indicator (VGI) was located and examination of the face indicated an inverted nose up wing down attitude. This is the position the VGI assumes with power removed from the aircraft. Again it appears remote that the VGI would move to this position at impact had their been AC power applied.

These individual indications are inconclusive separately but collectively provide a strong argument to support loss of number one AC generator power.

For the number two generator, a DIR of the wing fuel transfer pump established that it was running at impact. Since there is no evidence to contradict number two AC generator power availability it

where control of the aircraft was momentarily lost or marginal. IFR conditions would aggravate this problem. The first three stages and number one main bearing of the N-1 compressor section were not found in the wreckage. No large N-1 compressor blades were located as belonging to the port engine. Oil coolers, fairings or speed rings were not recovered. A secured engine would have been windmilling at a much higher rotational speed than was indicated in the DIR. DIR on recovered engine sections found no cause for engine stoppage.

The starboard engine was running at impact at low or IDLE RPM. No evidence was found contrary to the belief that it was functioning normally.

Analysis of ATM's and accessories indicate operating conditions. A variance exists between the DIR message report that the ATM's were running at impact and that a DC generator indicated only impact damage. Since the DC generator is spline shafted directly to the ATM gear train it is not likely that an ATM can be rotating without rotation on the DC generator. A sheared generator shaft or broken gear train would be the only circumstances that would allow such an event. Since generator shafts have a designed shear strength, a failure from a sheared shaft remains a possibility. In any event, the seizure or stoppage would not adversely effect the operation of the other DC generator or the battery.

A study of cockpit instruments indicates a probable number one AC generator power loss of unknown duration prior to impact.

The TACAN (ID-310) DME indicator showed a fixed range at 76NM. DIR results stated this reading possible within plus three minus four miles. When AC power is taken from the instrument the mileage indication stops and records the last mileage received. A loss of LOCK ON is manifested by continually spinning counters. Had power from the number one AC been available, the aircraft would have LOST LOCK ON when below the line of sight to Lakeview and the DME counters would have revolved to some number indication of 0 to 199. To have lost LOCK ON and revolved to a 76NM reading at impact seems remote. A measure of TACAN distance from Lakeview VORTAC to the impact point is 72 nautical miles.

The remote attitude indicator (VGI) was located and examination of the face indicated an inverted nose up wing down attitude. This is the position the VGI assumes with power removed from the aircraft. Again it appears remote that the VGI would move to this position at impact had their been AC power applied.

These individual indications are inconclusive separately but collectively provide a strong argument to support loss of number one AC generator power.

For the number two generator, a DIR of the wing fuel transfer pump established that it was running at impact. Since there is no evidence to contradict number two AC generator power availability it

must be assumed that the standby gyro horizon was functioning as well.

The above conditions can be caused by insufficient bleed air supply to the ATM's.

Examination of ATM scrolls showed both sets of nozzle guide vanes to be in a nearly closed position. This is the position the guide vanes will assume when the ATM governor attempts to maintain designed ATM speed from insufficient bleed air. Normally, at single engine 70 percent RPM on the ground under static minimum load conditions, sufficient bleed air is available to operate both ATM's with associated hydraulic pumps and generators. Application of additional loads to the hydraulic pumps such as operation of speed brakes, cycling of surface controls or electrical demands on the generators, (such as AC trim actuation), will burden the ATM's to sufficient extent to cause a loss of AC power from both under frequency and under voltage conditions. This can occur to both generators. However, normally the number one AC generator, which carries the greatest electrical load, will fail in advance of number two since more bleed air is required to maintain ATM speed. Unless an increased quantity of bleed air is supplied, the generator will operate under low RPM with continued under frequency and under voltage output. The majority of AC electrical systems are frequency sensitive and require a steady state  $400 \pm 20$  CPS for proper operation. Both TACAN and VGI instruments are considered frequency sensitive and unreliable below an estimated 300 CPS.

A reduced bleed air supply in an aircraft operating under single engine conditions can be derived in three ways. A faulty flapper check valve, ruptured bleed air duct or single engine operation at reduced RPM will deny sufficient bleed air to operate at the ATM's governed speed.

In the event of engine failure the flapper check valves, located near the wing roots at bleed air duct coupling joints, are designed to prevent the escape of bleed air through the failed engine. Squadron aircraft are started on starboard engines on odd calendar days and port engine on even number days. This action provides a check on the operation of the valve. No past discrepancies were reported and it is assumed that valve operation was satisfactory.

That a ruptured bleed air duct could have caused a reduced air supply is a consideration. All past known catastrophic engine failures that disintegrated in flight and shed parts into the airframe caused damage to the airframe aft of the engine disintegration point. A section of bleed air ducting is aft of a lateral plane measured from the forward N-1 compressor stage. This ducting is located in the wing and on the engine side of the flapper check valve. At engine failure this line would be isolated by the closing of the flapper check valve. From the check valve inboard to the fuselage, and subsequent, all ducting common to both engines is very near to or forward of the lateral plane. Approximately 18 inches of ducting common to both engines is vulnerable to shrapnel damage. This section could have been punctured or severed by flying shrapnel. A study of

past engine failures indicates this probability remote but not impossible.

The third likely cause of bleed air reduction is reduced power to the starboard engine. Idle RPM on both engines is considered sufficient to operate ATM's at designed speed with no load. From past A3B experience, AC generators have dropped off the line under dual engine IDLE conditions when hydraulic loads or heavy electrical loads were placed on the ATM's. Single engine low power, at or near the IDLE range, is considered insufficient to sustain the ATM's in normal operation. Though bleed air is available to drive the ATM's, they will operate at reduced RPM's with the generators at under frequency, under voltage output. Following the starboard engine DIR report, a phone call to O & R North Island established that the starboard engine was operating in the IDLE range at impact.

Evidence of inflight fire is inconclusive. All wreckage recovered was examined for indications of inflight fire. One piece of fiberglass material was found and its manner of fold and burned areas suggested the possibility of having occurred inflight. DIR analysis of the material determined it to be fuel cell tank liner used as external covering around the forward and aft main fuel cells. Since the material also bears indications of ground fire, though recovered in an area devoid of noticeable ground fire activity, the evidence is controversial. It should be noted that a sizable number of wreckage items became entangled in tree branches and subsequently fell to the ground in the days following the accident. Conceivably, burning could have taken place in the upper tree branches. In any event, no other indications of inflight fire were found. Without further support, evidence of inflight fire is inconclusive.

A review of the aircraft history contains no revelant information as possible contributory factors to the accident. Existing records indicate that J-57 Engine Bulletin 535 had been incorporated in the port engine. Verification from engine examination was not possible since front stages of the port N-1 compressor section were not recovered.

#### C. Weather Analysis

The weather at FL 180 was IFR with patchy intermittent VFR conditions. With decreasing altitude, VFR conditions became more predominant. A PIREP reported turbulence as occasionally light with no icing reported. Surface conditions in the area appear to have been broken conditions between 9880' MSL and 7500' MSL with visibility reduced in areas of snow flurries.

#### D. Survival Equipment Analysis

Examination of all evidence indicates there was no use of any escape systems or equipment. No personal survival equipment was utilized.

The emergency escape chute cylinder was recovered and submitted for DIR. Examination revealed only impact damage. The impulse car-

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E



tridge was removed and test fired within voltage and current requirements. A minimum of 6 volts is required to fire the cartridge. This voltage is available on the 28V DC battery bus. This bus is active at all times regardless of any cockpit switch position. Therefore it seems certain that no attempt was made to vacate the aircraft.

#### E. Pilot/Personnel Factor Analysis

Strong evidence supports starboard engine operation at low RPM. This condition was most probably a result of pilot response. Nothing provides evidence to suggest the starboard engine low power to be a result of material malfunction.

Available evidence indicates no attempt to abandon the aircraft. The emergency escape door was not fired. The decision to delay bail-out was most probably based on the erroneous conclusion that the aircraft altitude of 18,000 feet permitted sufficient time to attempt recovery from an unusual attitude prior to passing 10,000 feet. Once the aircraft passed 10,000 feet in a steep dive only seconds remained prior to impact. Even if the aircraft was in VFR conditions at that time it would have been obvious to the crew that they were too low to bail out.

#### F. NATOPS Factors

The A-3 NATOPS Manual, Section I, page 72N, contains the following CAUTION note:

"During single engine flight do not throttle the engine to IDLE as the engine bleed air is not sufficient to operate the ATM units".

Other than the evidence that the starboard engine was operating at IDLE, there is no indication that the NATOPS Manual was not being compiled with or that NATOPS requirements or procedures were a factor in the accident.

A recommendation to include further CAUTION warnings concerning the above note in the A-3B Pocket Checklist and the Emergency Section of the A-3B NATOPS Manual has been submitted in accordance with OPNAV INST 3510.9B.

# VIII CONCLUSIONS

The cause of the accident is determined to be inflight port engine failure. The cause of the engine failure is undetermined. The most probable cause of engine failure is inflight disintegration of the primary N-1 compressor stages or malfunction of number one main bearing. It is felt that the failure may have been catastrophic involving explosion in flight causing some degree of control loss to the aircraft. Evidence of bleed air duct rupture was not found and therefore not considered. Evidence of inflight fire is inconclusive.

The following additional factors severely aggravated the mishap.

The weather is considered a prime factor to the accident. It is felt that the aircraft may have been initially out of control in IFR conditions. Recovery on a single engine by an inexperienced A3B pilot under IFR conditions would be extremely difficult. The instructor pilot in the right-hand seat could not fully analyze and respond with proper voice instruction rapidly enough to prevent the development of aggravated aircraft performance.

It is further suggested that the crew was occasionally VFR. Perhaps enough to suggest that better VFR weather could be encountered immediately below FL 180. This expectation of improved VFR conditions and partial regaining of control may have led to intentional continued descent to lower altitude. That such action was contemplated may account for the apparent lack of attempt to bail out.

All available evidence has shown no mechanical reason for the starboard engine to have been operating in the IDLE range. This appears to have been a pilot action either to descend voluntarily or to reduce excessive airspeed built up during an uncontrolled descent. Had the descent been completely uncontrolled, some evidence would be manifest that preparations had been made to BAIL OUT. The following events would result in a power reduction on the starboard engine:

1. Port engine disintegration.
2. Aircraft yaw to left.
3. Some degree of control loss.
4. Nose down condition aggravated by loss of port engine thrust.
5. Possible expectation of VFR weather at lower altitude.
6. No awareness of actual terrain clearance.
7. Pilot response, throttle RETARD.

The action of retarding a single engine to the IDLE range will cause a loss of AC generator power to below that required to maintain

the AC cockpit instruments on the line. Initially, at electrical power loss, the number one AC generator fails. If the pilot responds to the situation by securing the number one generator in order to effect a BMS TIE, thereby transferring the electrical load to the number two AC generator, then the number two AC generator will assume all electrical load and subsequently fail in the same manner. With only limited bleed air available, the AC generators may intermittently reach operating frequency. However, this possibility is remote unless more bleed air is forced to the ATM's by engine power application.

It is considered a strong probability that loss of AC electrical power occurred during the pilot's attempts to regain positive control of the aircraft.

The board's conclusions are based on limited evidence and findings are, in part, circumstantial. All evidence supports the findings. No evidence is to the contrary. Due to the inaccessibility of the crash site and dense snow cover a great deal of wreckage was not found that could establish further proof or modify the board's conclusions. As snow cover recedes in warmer weather, additional wreckage will be exposed that may provide further information.

## II Recommendations

1. The need for an early decision to abandon the aircraft in uncontrolled flight conditions must again be reemphasized to all flight crew personnel.

2. (b) (5)

3. The installation of the YANKEE Extraction system in A-3B aircraft should proceed on a priority basis.

4. Include additional explanation and warning concerning the single engine power setting requirements to sustain complete ATM operation in the A-3B Pocket Checklist and the Emergency Section of the A-3B NATOPS Manual. A routine change has been proposed in accordance with OPNAV INSTRUCTION 3510.9B.

5. With improving weather and greater accessibility to the crash site further wreckage recovery should establish additional evidence pertinent to the investigation. It is recommended that further investigation be conducted and new evidence, as received, be disseminated to all concerned.



A3B 138917 PILOT PARKS

AIRCRAFT ACCIDENT REPORTENCLOSURESENCLTITLE

- 1 Medical Officers Report (original only)
- 2 Maps of Flight Track, Crash Location
- 3 Rescue Report, OPNAV 3750-13 (original only)
- 4 Wreckage Diagram
- 5 LCDR (b) (6) Statement
- 6 Copy of Flight Plan
- 7 PW's Flight Transcript
- 8 Mr. Floyd BROOK's Statement
- 9 Wreckage Site Photographs
- 10 Engine Photographs
- 11 Airframe Component Photographs
- 12 Maintenance Officers Statement
- 13 DII Message Reports
- 14 Pilot/Co-pilot Flight Time Resume
- 15 Weather Analysis
- 16 Capt. (b) (6) Statement

INDEX OF ENCLOSURES TO THE MEDICAL OFFICER'S REPORT ON AAR 1-67A,  
HEAVY ATTACK SQUADRON ONE TWO THREE, OAK HARBOR, WASHINGTON

I. THE ACCIDENT

II. STATEMENTS

- A. LCDR (b) (6) USN
- B. CAPT. (b) (6) USAF
- C. MR. FLOYD BROOKS
- D. WEATHER ANALYSIS(LCDR (b) (6) USN)
- E. MAINTENANCE OFFICER(LCDR (b) (6) USN)
- F. FAA FLIGHT TRANSCRIPT
- G. FLIGHT TIME RESUME: LCDR PARKS, PILOT
- H. FLIGHT TIME RESUME: LCDR KING, CO-PILOT

III. PHOTOGRAPHS AND DIAGRAMS

- A. MAP OF FLIGHT PATH
- B. WRECKAGE DIAGRAM
- C. WRECKAGE SITE PHOTOGRAPHS
  - 1. Flight Path
  - 2. Flight Path
  - 3. Impact Angle
  - 4. Wreckage Site
- D. ENGINE PHOTOGRAPHS (COMPOSITE)
- E. COCKPIT INSTRUMENTS
- F. #1 ATM SCROLL
- G. #2 ATM SCROLL
- H. FUEL TANK LINER
- I. ESCAPE CHUTE CYLINDER

IV. DAMAGE TO THE AIRCRAFT(AAR)

V. INVESTIGATION(AAR)

VI. THE ANALYSIS(AAR)

VII. CONCLUSIONS(AAR)

VIII. RECOMMENDATIONS(AAR)

IX. CONCLUSIONS AND RECOMMENDATIONS OF MEDICAL OFFICER

## SECTION A - IDENTIFICATION

1. FROM (Name and mailing address of activity)		HEAVY ATTACK SQUADRON ONE TWO THREE,		2. MOR NUMBER		3. LEAVE BLANK	
Oak Harbor, Washington 98277				1-67			
4. TYPE OF MISHAP		5. TIME & ZONE		6. DATE		7. GEOGRAPHICAL LOCATION	
<input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> GROUND ACCIDENT <input type="checkbox"/> INCIDENT		1432Z		5 April 1967		Near Eagle Peak, 20 mi. SE of Alturas, California	
8. MODEL A/C		9. BUONO		10. NO. OF OCCUPANTS		11. DAMAGE CODE	
A3B		138917		4		VAH 123	
13. INDIVIDUALS INVOLVED USE ADDITIONAL SHEETS IF REQUIRED NAME (Last, first and middle initial)		14. UNIT TO WHICH ATTACHED		15. RANK/ RATE		16. FILE/SERV. NO. DESIGNATOR	
A. PARKS, Richard E.		VAH-123		LCDR (b) (6)		A A 1/12/67	
B. KING, Donald E.		VAH-123		LCDR		H H 3/27/66	
C. READER, James M.		VF-126		LCDR		R R 3/17/66	
D. MILLER, Carl V., Jr.		VAH-123		ADJ (b) (6)		X X 3/1/67	
17. DUTY ASSIGNMENT ABOARD AT A/C MISHAP		18. DATE OF LAST PHYSICAL		19. PHYSICALLY QUALIFIED FOR FLIGHT		20. BRANCH OF SERVICE	
				Yes		1 A A	
				Yes		1 A A	
				Yes		1 A A	
				Yes		1 A A	
21. CLARIFICATION OF ITEMS 13-22 WHEN NECESSARY		22. INJURY CODE		23. DISPO ITION			

24. MODEL OTHER A/C IF INVOLVED	25. BUONO	26. NO. OF OCCUPANTS	27. UNIT OPERATING A/C	28. DAMAGE CODE	29. MOR NO.
N.A.					

30. NARRATIVE ACCOUNT OF MISHAP (Use additional 8 x 10 1/2 sheets if required)

See enclosure (1).

31. PRIMARY CAUSE FACTOR ASSIGNED BY ACCIDENT BOARD	
Inflight failure of port engine	
32. CONTRIBUTING CAUSE FACTOR ASSIGNED BY ACCIDENT BOARD	
Weather	
33. POSSIBLE CAUSE FACTOR ASSIGNED BY ACCIDENT BOARD	
34. HAVE ALL FINDINGS, CONCLUSIONS, & RECOMMENDATIONS BEEN MADE AVAILABLE TO THE A/C ACCIDENT BOARD? IF NO, EXPLAIN	
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
35. REPORT PREPARATION CHECK LIST	
<input checked="" type="checkbox"/> ALL PARTS OF FORM COMPLETED <input checked="" type="checkbox"/> DRAWINGS, SKETCHES, PHOTOS <input checked="" type="checkbox"/> SURVIVORS' NARRATIVES <input checked="" type="checkbox"/> WITNESS STATEMENTS <input checked="" type="checkbox"/> CONCLUSIONS & RECOMMENDATIONS <input checked="" type="checkbox"/> REQUIRED COPIES FURNISHED	
36. REPORT FILED BY: (Name & signature of medical officer)	DATE
(b) (6)	(b) (6)
LCDR MC USN	8 May 1967
(b) (6)	CDR USN
	12 May 1967

MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT - PAGE 1

OPNAV FORM 3750-8A (REV. 2-63)

SPECIAL HANDLING REQUIRED. - See OPNAV INST 3750.16 for instructions.

OPNAV REPORT 3750-7

SECTION B - FACTORS CONTRIBUTING TO OR RELATING TO MISHAP BY PHASE OF MISHAP (List in order in accordance with Section B of Inst.)

1. FACTORS	2. PHASE OF MISHAP (See code at right)				PHASE CODE: A - ACCIDENT E - ESCAPE/EGRESS S - SURVIVAL R - RESCUE	REMARKS	FACTOR WEIGHT: H - MAJOR C - CONTRIBUTING Q - QUESTIONABLE OR POSSIBLE
	A	E	S	R			
Material failure(portengine)	M					This emergency was severe and would have taxed a very experienced pilot in type. Aircraft was intermittently IFR/VFR and when emergency began and progressed,obacuration may have made vertigo a possible factor.	
Weather	M						
Pilot inexperience	Q						
Vertigo.	Q						

SECTION C AIR CREW DATA					SECTION D ANTHROPOMETRIC DATA. (Compare with health record)	
1. FLIGHT TIME LAST 30 DAYS (All models)		24				AGE 34
2. FLIGHT TIME LAST 24 HOURS (All models)		3.8				HEIGHT (b) (6)
3. NO. FLIGHTS LAST 24 HOURS (Include present flight)		2				WEIGHT
4. TIME AT CONTROLS THIS FLIGHT		1+15				A. SITTING HEIGHT
5. TOTAL FLIGHT TIME ALL MODELS		2821				B. TRUNK HEIGHT
FLIGHT TIME THIS MODEL	25	24	25	25		C. FUNCTIONAL REACH
10. NO. GROUNDINGS PAST YEAR		0				D. BUTTOCK-KNEE
11. NO. DAYS GROUND PAST YEAR		0				E. LEG LENGTH
12. DATES AND TYPES OF PRIOR MISHAPS	None known.					F. SHOULDER WIDTH (HIDELOID)
13. NO. HRS. IN A DUTY STATUS LAST 24 HRS.		15 1/2				
14. DIRECTION FACING AT TIME OF MISHAP	Forward					
15. LOCATION AT TIME OF MISHAP	In pilot's seat;strapped in.					

16. See Pathologist's Report.			LABORATORY TESTS AND RESULTS		
SPECIMEN	TEST PERFORMED	RESULTS	SPECIMEN	TEST PERFORMED	RESULTS
BLOOD	1.		TISSUE: (CNS)		
	2.			MUSCLE	
	3.			VISCERA	
URINE			OTHER:		
G.I. CONTENT					
17. X-RAY RESULTS					
MOD NO.	MODEL A/C	SUNO	IDENTIFICATION OF INDIVIDUAL		
1-67	A3B	130317	A		
NAME OF INDIVIDUAL					
PARKS, Richard E. LCOR (b) (6)					



OPNAV FORM 3750-8B (REV. 3-63)

SPECIAL HANDLING REQUIRED - See OPNAV INST 3750.4B for instructions.

SECTION E

INDIVIDUAL CHRONOLOGICAL DATA

SEE PAGE 8 PARA. 10 OF INSTRUCTION  
TO BE COMPLETED ON PLANE COMMANDER, PILOT, CO-PILOT, OTHER INDIVIDUAL  
IN CONTROL OF AIRCRAFT AT TIME OF MISHAP, AND/OR INDIVIDUAL CAUSING THE MISHAP

LOCAL TIME AND BRIEFLY RECORD ACTIVITY WITHIN EACH COLUMN

48 HOURS PRIOR TO MISHAP

TIME Monday, 3 April 1967

1200 Lunch in mess hall area

1730 Home-bourbon, beer(2)

1930 Dinner (ham, baked potatoes, squash, tomato juice)

2200 In bed, watched TV

2315 Sleep

Tuesday, 4 April 1967

0615 Arose

No breakfast

0700 Departed for squadron

1200 Departed squadron area for errands in town

1400 Hamburger at home

1500 Departed for squadron

1800 Sandwich in ready room

1950 Manned aircraft (A3B BuNo 138917)

2021 Departed NAS Whidbey Island for NAS Miramar

2255 Deplaned at NAS Miramar

2330 At BOQ, watched late show on TV

Wednesday, 5 April 1967

0130 Retired after show

0830(est) Arose

(Wife guesstimated that he had breakfast consisting of 2 eggs, toast and black coffee)

1230 Briefed for return to NAS Whidbey

1316 Departed NAS Miramar for NAS Whidbey Island, box lunches in aircraft

1428 Oakland Center granted permission to contact Seattle Center

1430 Reported to Seattle Center but when requested to squawk IDENT, did not reply.

1431 Seattle Center radar noted left turn and lost contact.

TIME

ACCIDENT PHASE

1432

Crashed near Eagle Peak,  
20 miles SE of Alturas,  
California

ESCAPE PHASE

SURVIVAL PHASE

TIME OF RESCUE

MOR NO.

MODEL A/C

BURO

IDENTIFICATION OF INDIVIDUAL

1-67

A3B

138917

A

NAME OF INDIVIDUAL

PARKS, Richard E. LCDR (b) (6)

OP-017

☆ U. S. GOVERNMENT PRINTING OFFICE: 1963-681975

## SECTION F

### PATHOLOGICAL DATA

(Refer to Section P of instructions.)

1. INJURY CODE AND DISPOSITION

## 2. PRE-EXISTING PHYSICAL DEFECTS

A/A

None

### 3. UNCONSCIOUSNESS

☒ NO ☐ YES DURATION: \_\_\_\_\_

4. DROWNED	5. ASPHYXIATED	6. SHOCKED
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

N.A.

H. GROUNDED? IF YES, GIVE REASON:

☐ NO ☐ YES

13. PRIMARY CAUSE OF DEATH

14. SECONDARY CAUSE OF DEATH

INJURIES, MULTIPLE, EXT. TIME #8690

N.A.

15. AUTOPSY CONDUCTED BY:

 PATHOLOGIST, MEDICAL  
OFFICER, PRESENT

PATHOLOGY: MEDICAL  
DEVICE NOT PRESENT

☐ MEDICAL OFFICER

16. ☒ PROTOCOL ATTACHED

☐ WILL BE FORWARDED

17 WAS "AUTOPSY MANUAL, NAVMED P5055" USA

☒ YES ☐ NO

18. IF NO AUTOPSY CONDUCTED, GIVE REASON

INJURIES

PHASE SUSTAINED

**CAUSE AND MECHANISM** (If unknown, theorize)

INJURIES, MULTIPLE, EXTREME

A	E	S	R
---	---	---	---

Cockpit disintegrated as aircraft crashed through trees.

## 20. REMARKS

See Pathologist's Report and NAVMED N which are attached.

MOR NO.	MODEL A/C	SUNO	IDENTIFICATION OF INDIVIDUAL
---------	-----------	------	------------------------------

1-67

A3B

138917

A

NAME OF INDIVIDUAL

PARKS, Richard E. LCDR (b) (6)

CERTIFICATE OF DEATH  
NAVMED FORM 1300-1 (REV. 4-58) FROM

See HANDED DEPT. for instructions regarding  
number of copies and submission.

FROM (Ship or Station) U. S. NAVAL AIR STATION, WHIDBEY ISLAND, WASHINGTON										IF UNIDENTIFIED INDICATE BY USING "X" AND CONSECUTIVE NUMBER HERE														
1. NAME PARKS, Richard Earl										2. SEX <input checked="" type="checkbox"/> MALE <input type="checkbox"/> FEMALE					3. RACE <input checked="" type="checkbox"/> CAUCASIAN <input type="checkbox"/> NEGRO <input type="checkbox"/> OTHER (Specify)									
4. STATUS <input checked="" type="checkbox"/> MILITARY <input type="checkbox"/> RESERVE <input type="checkbox"/> RETIRED <input type="checkbox"/> DEPENDENT <input type="checkbox"/> VAP <input type="checkbox"/> OTHER (Specify)										5. LENGTH OF SERVICE (Years and months) 12 10					6. AVIATION <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO									
7. FILL IN SERVICE NO. 38455					8. GRADE/RATE LCdr					9. BRANCH OF SERVICE USN					10. PLACE OF BIRTH (City and State or Country) Roscoe, Pennsylvania									
11. DATE OF BIRTH (Month, day and year) (b) (6)										12. AGE (Years, months) (Days, if under 1 year) 34 4										13. RELIGION P				
14. COLOR OF EYES Brown					15. COLOR OF HAIR Brown					16. COMPLEXION Ruddy					17. HEIGHT (b) (6)									
18. MARKS AND SCARS (Entered in full; describe)										19. FINGERPRINT - STATE WHICH FINGER (Right index preferred)														
20. NEXT OF KIN OR FRIEND (Relationship, name and address) Wife: Wanda Jo Parks, (b) (6)										21. FINGERPRINT - STATE WHICH FINGER (Right index preferred)														
22. ADMITTED TO SICK LIST FROM (If on active duty, last duty station before current admission to sick list) HATTON - ONE TWO THREE, WHIDBEY ISLAND, WASHINGTON										23. DATE ADMITTED TO SICK LIST (Month, day, year) April 5, 1967 1432														
24. PLACE OF DEATH Mesa Eagle Peak, 20 miles Southeast of Alturas, California										25. TIME OF DEATH (Month, day, year, hour) April 5, 1967 1432														
26. CAUSE OF DEATH 1. DISEASE OR CONDITION DIRECTLY LEADING TO DEATH. (This does not mean the mode of dying, e.g., heart failure, asphyxia, etc. It means the disease, injury or complication which caused death.) Injuries, Multiple, Extreme DUE TO (b) DUE TO (c) 2. ANTECEDENT CAUSES. (Morbid conditions, if any, giving rise to above cause (a), stating the underlying cause last) 3. OTHER SIGNIFICANT CONDITIONS. (Conditions contributing to death but not related to the disease or condition causing death)										APPROXIMATE INTERVAL BETWEEN ONSET AND DEATH Immediate														

DO NOT WRITE IN THIS SPACE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80



25. NAME

PARKS, Richard Earl

(b) (6)

## 26. SUMMARY OF FACTS RELATING TO DEATH

LCDR Parks was pilot in command in U. S. Navy jet aircraft A3B, Bureau No. 138917, enroute from NAS, Miramar, California, to NAS, Whidbey Island, Oak Harbor, Washington. The aircraft crashed in Warner Mountain Range near Eagle Peak, 20 miles Southeast of Altamira, California. Total destruction of the aircraft occurred as it crashed through large (18"-48" diameter) trees into the hillside at 7400 feet elevation. Heavy snow prohibited thorough excavation of crash site.

Decedent was grossly identified by aircraft manifest and location of remains in proximity to cockpit instruments on pilot's side. Gross description of (b) (6) remains to follow from Dr. George R. Nicholson, Pathologist, Presbyterian Inter-community Hospital, Klamath Falls, Oregon, and will be appended as enclosure to VAS-123 MGR 1-67.

(b) (6) Contract mortician, O'Hair's Memorial Chapel, Klamath Falls, Oregon, has remains for preparation and disposition in accordance with the wishes of the Next Of Kin.

## 27. DISPOSITION OF REMAINS

Steele and Wolf Funeral Home, Weirton, West Virginia, in accordance with the wishes of the Next Of Kin.

28.

(b) (6)

DATE SIGNED 19 April 1967

SIGNATURE

(Medical Officer)

LCDR

(Rank)

EMCJ USN

APPROVED: COURT OF INQUIRY OR BOARD OF INVESTIGATION

(b) (6)

DATE SIGNED 19 APR 1967

SIGNATURE

(Commanding Officer)

ODR

(Rank)

USN



G. R. NICHOLSON, M. D.  
PHYSICIAN - PATHOLOGIST  
2865 Daggett Street  
KLAMATH FALLS, OREGON  
97601

AIRCRAFT ACCIDENT  
Pathologist's Report

IDENTIFICATION

Casualties:

<u>NAME</u>	<u>AGE</u>	<u>RANK</u>	<u>SERIAL NUMBER</u>	<u>STATUS</u>
KING, Donald E.	35	LCDR	(b) (6)	Instruction Pilot
READER, James M.	32	LCDR		Observer
PARKS, Richard E.	36	LCDR		Pilot in Command
MILLER, Jr., Carl V.	23	ADJ3		Plane Captain

INFORMATION RELATIVE TO ACCIDENT

AIRCRAFT: Navy Jet A3B No. 138917

ESTIMATED ALTITUDE BEFORE EMERGENCY: 18,000 feet MSL.

ALTITUDE AT CRASH SITE: 7,400 feet MSL.

WEATHER CONDITIONS: Snow showers; ceilings 5,000 ft.; visibility  $\frac{1}{2}$  mile.

RADIO AND RADAR CONTACT: Radio at 1430 hours with Oakland Center; Radar contact by Oakland and Seattle Centers and NORAD.

PILOT CONTROL AT TIME OF ACCIDENT: Parks believed to be in the left seat and at controls.

NATURE OF ACCIDENT: Pending--apparent control loss at 18,000 feet MSL.

TIME OF ACCIDENT: 5 April 1967 at 1432 hours.

SPEED AND ANGLE OF IMPACT: 550 Knots at flight angle of approximately 30 degrees from horizontal.

SEVERITY OF DAMAGE TO AIRCRAFT: Total destruction.

STATED CAUSE OF ACCIDENT: Pending.

INFORMATION RELATIVE TO ESCAPE

All four parachutes and parts of harnesses were apparently found at scene of crash. Fragments of seat belts torn and fragmented were found and one seat belt fragment was found still attached to the base of a fragment of seat. It

INFORMATION RELATIVE TO ESCAPE (Cont.)

is not known to this examiner whether escape was attempted in the air. The type of escape apparatus in the aircraft is not known to this examiner.

EXAMINATION OF TISSUES

Having been notified by Lt. Commander (b) (6) that examination of tissues was requested, all available tissue retrieved from the crash site was assembled and examined on April 12, 1967 at Presbyterian Intercommunity Hospital by myself and (b) (6). All tissue was weighed and the total found to be 57.5 lbs. All health records of the occupants were reviewed in an attempt to find any significant anatomic variation that might help in identification. Major blood types and body weights obtained from the records were as follows:

KING, Donald E.  
MILLER, Carl V.  
PARKS, Richard E.  
REEDER, James M.

(b) (6)

The only other significant information gleaned from the records were the facts that Carl Miller had blonde hair and Donald King had sustained a (b) (6)

(b) (6)

Documentary evidence recovered at the crash site and shown to me included:

1. Part of the dental record and immunization card of Reeder, James M., 2. Insurance identification card of Miller, Carl with agent's name John T. Brown, Oak Harbor State Farm Insurance Company readable and 3. Liberty card Number (b) (6) dated 27 August 1964 of Miller, Carl V.

The tissue submitted consisted predominantly of bone, skeletal muscle, skin and tendinous tissue. There were (b) (6) presumably from different persons. Fingerprints had been previously obtained from both specimens by (b) (6). Other recognizable specimens included the following:

(b) (6)

(b) (6)

EXAMINATION OF TISSUES (Cont.)

(b) (6)

(b) (6)

(b) (6) Multiple segments of skeletal muscle and skin were obtained to be utilized for blood typing and possible alcohol analysis and possible carbon monoxide analysis should this be indicated. Microscopic examination of tissue (as attached) did not reveal pre-existent disease and no apparent inflammatory process occurs in the lung segments.

(b) (6)

(b) (6)

It is felt that the most significant evidence not examined here of the presence of four persons is the finding of four separate parachutes and harnesses at the crash site. This fact, plus the fact that four persons are apparently signed into the aircraft at the point of origin of the flight must suffice as evidence of four persons being present at the crash site. Should additional information or material become available to me, I will forward appropriate reports or material as they are received.

*George R. Richardson M.D.*



MICROSCOPIC EXAMINATION

Microscopic examination included the following:

(b) (6)



*CPD*



# MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT - PAC

OPNAV REPORT 3750-7

OPNAV FORM 3750-8C (REV. 3-63)

SPECIAL HANDLING REQUIRED - See OPNAV INSTRUCTIONS 3750.6E for instructions.

## SECTION F

## PATHOLOGICAL DATA

(Refer to Section F of instructions.)

### 1. INJURY CODE AND DISPOSITION

### 2. PRE-EXISTING PHYSICAL DEFECTS

A/A

3. UNCONSCIOUSNESS

☒ NO ☐ YES DURATION:

3/63-Fracture, distal head, left 5th metacarpal  
8/65-Fracture, medial malleolus, right ankle

4. DROWNED

5. ASPHYXIATED

6. SHOCK

☐ MILD

☐ MODERATE

☐ SEVERE

7. EXPOSURE

☐ MILD

☐ MODERATE

☐ SEVERE

8. EXTENT OF CARBONIZATION

None

9. IF ADMITTED TO SICK LIST, GIVE DIAGNOSIS

10. PLACE OF HOSPITALIZATION

NA

11. GROUNDED? IF YES, GIVE REASON

☒ NO ☐ YES

N.A.

12. DURATION (See instructions)

13. PRIMARY CAUSE OF DEATH

14. SECONDARY CAUSE OF DEATH

INJURIES, MULTIPLE, EXTREME #8690

N.A.

15. AUTOPSY CONDUCTED BY:

☒ PATHOLOGIST, MEDICAL OFFICER PRESENT

☐ PATHOLOGIST, MEDICAL OFFICER NOT PRESENT

☐ MEDICAL OFFICER

16.

☒ PROTOCOL ATTACHED

☐ WILL BE FORWARDED

17. WAS "AUTOPSY MANUAL, NAVMED P5065" USED?

☒ YES ☐ NO

18. IF NO AUTOPSY CONDUCTED, GIVE REASON

19.

INJURIES

PHASE SUSTAINED

A

E

S

R

CAUSE AND MECHANISM (If unknown, theorize)

INJURIES, MULTIPLE, EXTREME

X

Cockpit disintegrated as aircraft crashed through trees.

### 20. REMARKS

See Pathologist's Report and NAVMED N which are attached.

MOB NO.

1-67

MODEL A/C

A3B

SUBO

138917

IDENTIFICATION OF INDIVIDUAL

H

NAME OF INDIVIDUAL

KING, Donald E. LCDR (b) (6)

CERTIFICATE OF DEATH  
REVISED 10-1-55) FIGHT

See FARRED DEPT. for instructions regarding number of copies and submission.

FROM (State):

U. S. NAVAL AIR STATION, WHIDBEY ISLAND, WASHINGTON

IF UNIDENTIFIED INDICATE BY USING "X" AND CONSECUTIVE NUMBER HERE

1. NAME <b>KING, Donald Edwin</b>		2. SEX <input checked="" type="checkbox"/> MALE <input type="checkbox"/> FEMALE		3. RACE <input checked="" type="checkbox"/> CAUCASIAN <input type="checkbox"/> NEGROID <input type="checkbox"/> OTHER (Specify)	
4. STATUS <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> RESERVE <input type="checkbox"/> RETIRED <input type="checkbox"/> DEPENDENT <input type="checkbox"/> JAP <input type="checkbox"/> OTHER (Specify)		5. LENGTH OF SERVICE (Years and months) <b>15 00</b>		6. AVIATION <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
7. GRADE OR RANK <b>(b) (6) LCDR</b>		8. BRANCH OF SERVICE <b>USN</b>		9. PLACE OF BIRTH (City and State or Country) <b>Salt Lake City, Utah</b>	
10. DATE OF BIRTH (Month, day and year) <b>(b) (6)</b>		11. AGE (Years, months) (Days, if under 1 year) <b>35 7</b>		12. RELIGION <b>P</b>	
13. COLOR OF EYES <b>Brown</b>		14. COLOR OF HAIR <b>Brown</b>		15. COMPLEXION <b>Ruddy</b>	
16. HEIGHT <b>71"</b>		17. WEIGHT <b>(b) (6)</b>		18. FINGERPRINT - STATE WHICH FINGER (Right index preferred)	
19. MARITAL STATUS (Based on health record) <b>(b) (6)</b>		20. NAME OF SPOUSE (Name and address) <b>Wife: Donna Gene King, (b) (6)</b>			
21. ADMITTED TO SICK LIST FROM (If on active duty, last duty station before current admission to sick list) <b>HATTON - ONE TWO THREE, WHIDBEY ISLAND, WASHINGTON</b>		22. DATE ADMITTED TO SICK LIST (Month, day, year) <b>April 5, 1967 1432</b>			
23. PLACE OF DEATH <b>Near Eagle Peak, 20 miles Southeast of Alturas, California</b>		24. TIME OF DEATH (Month, day, year, hour) <b>April 5, 1967 1432</b>			
25. DISEASE OR CONDITION DIRECTLY LEADING TO DEATH. (This does not mean the mode of dying, e.g., heart failure, asthma, etc., it means the disease, injury or complication which caused death.) <b>Injuries, Multiple, Extreme</b>		(a) DUE TO (b) <b>(b) (6)</b>		APPROXIMATE INTERVAL BETWEEN ONSET AND DEATH <b>Immediate</b>	
26. ANTECEDENT CAUSES. (Morbid conditions, if any giving rise to above cause (a), stating the underlying cause, last.) <b>(b) (6)</b>		DUE TO (c) <b>(b) (6)</b>			
27. OTHER SIGNIFICANT CONDITIONS. (Conditions contributing to death but not related to the disease or condition causing death.) <b>(b) (6)</b>					

Not Available

DO NOT WRITE IN THIS SPACE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

KING, Donald Edwin

(b) (6)

## II. SUMMARY OF FACTS RELATING TO DEATH

King was traveling as instructor pilot in U. S. Navy jet aircraft A3B, Bureau No. 138917, enroute from NAS, Miramar, California, to NAS, Whidbey Island, Oak Harbor, Washington. The aircraft crashed in Warner Mountain Range near Eagle Peak, 20 miles Southeast of Alturas, California. Total destruction of the aircraft occurred as it crashed through large (18"-48" diameter) trees into the hillside at 7400 feet elevation. Heavy snows prohibited thorough excavation of crash site.

Deceased was grossly identified by aircraft manifest, (b) (6)

(b) (6) and a wedding ring with inscription. Gross description of (b) (6) remains to follow from Dr. George R. Nicholson, Pathologist, Presbyterian Intercommunity Hospital, Klamath Falls, Oregon, and will be appended as enclosure to VAM-123 MOR 1-67.

(b) (6) Contract mortician, O'Hair's Memorial Chapel, Klamath Falls, Oregon, has remains for preparation and disposition in accordance with the wishes of the Next Of Kin.

## III. DISPOSITION OF REMAINS

Finley's Family Funeral Home, Portland, Oregon, in accordance with the wishes of the Next Of Kin.

1.

(b) (6)

DATE SIGNED 19 April 1967

SIGNATURE

LCDR

(EMC) USN

(Medical Officer)

(Rank)

2.

APPROVED: COURT OF INQUIRY OR BOARD OF INVESTIGATION

(b) (6)

DATE SIGNED 19 APR 1967

SIGNATURE

CDR

USN

(Commanding Officer)

(Rank)







CERTIFICATE OF DEATH  
NIGHTLY REPORT, 4-50) FRONT

See SANVED DIPT. for instructions regarding  
number of copies and submission

NAME (Print or Staple)

U.S. NAVAL AIR STATION, WHIDBEY ISLAND, WASHINGTON

IF UNIDENTIFIED INDICATE BY USING "AT" AND CONSECUTIVE  
NUMERICAL NAME

PERSON: James Merritt

☒ MALE ☐ FEMALE

☒ CAUCASIAN ☐ NEGRO ☐ OTHER

☒ ACTIVE ☐ RESERVE ☐ RETIRED ☐ DEPENDENT ☐ VET ☐ OTHER

12 3

☒ YES ☐ NO

(b) (6)

ICDR

USN

Antigo, Wisconsin

(b) (6)

32 9

6

14. COLOR OF HAIR

Brown

71"

16. WEIGHT

(b) (6)

18. MARRIAGE AND LEAVE (Marked in Report Section)

(b) (6)

Not Available

22. NEXT OF KIN OR FRIEND (Relationship, name and address)

Wife: Barbara Mary Reader, (b) (6)

24. ADDRESS TO WHICH SICK LIST (If on active duty, leave duty station before entering notification in)

126, U. S. NAVAL AIR STATION, MIRAMAR, CALIFORNIA

26. DATE ADMITTED TO SICK LIST (Month, day, year)

28. PLACE OF DEATH

Near Eagle Peak, 20 miles Southeast of Alturas, California

28. TIME OF DEATH (Month, day, year, hour)

April 5, 1967 1432

29. DISEASE OR CONDITION DIRECTLY LEAD (INC TO DEATH. (This does not mean the mode of dying, e.g., heart failure, asphyxia, etc., it means the disease, injury or condition which caused death.)

(a)

Injuries, Multiple, Extreme

APPROXIMATE  
INTERVAL BETWEEN  
ONSET AND DEATH  
Immediate

30. ANTECEDENT CAUSES (Morbid conditions, if any giving rise to above cause (a), stating the underlying cause last)

DUE TO (b)

DUE TO (c)

31. OTHER SIGNIFICANT CONDITIONS (Conditions contributing to death but not related to the disease or condition causing death)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

NAME, James Morrill

(b) (6)

SUMMARY OF FACTS RELATING TO DEATH

Deceased was traveling as observer in U. S. Navy jet aircraft A3B, Bureau No. 138917, enroute from NAS, Miramar, California, to NAS, Whidbey Island, Oak Harbor, Washington. The aircraft crashed in Warner Mountain Range near Eagle Peak, 20 miles Southeast of Altamira, California. Total destruction of the aircraft occurred as it crashed through large (18"-43" diameter) trees into the hillside at 7400 feet elevation. Heavy snow exhibited thorough excavation of crash site.

Deceased was grossly identified by aircraft manifest and the fact that portions of his pay and dental records were found among the wreckage. Gross description of (b) (6) remains to follow from Dr. George R. Nicholson, Pathologist, Presbyterian Intercommunity Hospital, Klamath Falls, Oregon, and will be appended as enclosure to VAH-123 MOR 1-67.

(b) (6) Contract mortician, O'Hair's Memorial Chapel, Klamath Falls, Oregon, has remains for preparation and disposition in accordance with the wishes of the Next Of Kin.

## DISPOSITION OF REMAINS

Taylor Funeral Home, West Grand Avenue, Wisconsin Rapids, Wisconsin, in accordance with the wishes of the Next Of Kin.

(b) (6)

DATE SIGNED 19 April 1967

SIGNATURE

LCDR

(Rank) USN

(Mortician/Officer)

(Rank)

APPROVED: COURT OF INQUIRY OR BOARD OF INVESTIGATION

(b) (6)

DATE SIGNED 19 APR 1967

SIGNATURE

CDR

USN

(Commanding Officer)

(Rank)





U. S. MARINE AIR STATION, WHEBER ISLAND, WASHINGTON

IT IDENTIFIED INDICATE IT WAS IT WAS CONTAINED IN  
NUMBER 4142



(b) (6)

(b) (6)

(b) (6)

Wife: Janet Lenore Miller, (b) (6)

April 5, 1967 1432

2. CHASE OR CONDITION DIRECTLY LEADING TO DEATH. (This does not mean the mode of dying, e.g. heart failure, asphyxia, etc. It means the disease, injury or complication which caused death.)

Injuries, Multiple, Extreme

APPROXIMATE  
INTERVAL BETWEEN  
ONSET AND DEATH  
Immediate

DATE: TO / /

3. OTHER SIGNIFICANT CONDITIONS. (Conditions contributing to death but not related to the disease or condition causing death.)

Not Available



MILLER, Carl Virgil, Jr.

(b) (6)

2. SUMMARY OF FACTS RELATING TO DEATH

Miller was traveling as aircrewman in U. S. Navy jet aircraft A3B, Bureau No. 138P17, enroute from NAS, Miramar, California, to NAS, Whidbey Island, Oak Harbor, Washington. The aircraft crashed in Warner Mountain Range near Eagle Peak, 20 miles Southeast of Altamira, California. Total destruction of the aircraft occurred as it crashed through large (18"-48" diameter) trees into the hillside at 7400 feet elevation. Heavy snow prohibited thorough excavation of crash site.

Deceased was grossly identified by aircraft manifest and the fact that he was the only blonde in the group. His liberty card and State Farm Mutual Automobile Insurance Card were found among the wreckage. Gross description of (b) (6) remains to follow from Dr. George R. Nicholson, Pathologist, Presbyterian Intercommunity Hospital, Klamath Falls, Oregon, and will be appended as enclosure to VAR-123 MOR 1-67.

(b) (6)

Deceased's next of kin, contact mortician, O'Fair's Memorial Chapel, Klamath Falls, Oregon, has remains for preparation and disposition in accordance with the wishes of the Next Of Kin.

3. DISPOSITION OF REMAINS

Burr Funeral Home, 202 Main Street, Mishawaka, Indiana, in accordance with the wishes of the Next Of Kin.

(b) (6)

DATE SIGNED 19 April 1967

SIGNATURE

LCDR

(MC) JUN

(Medical Officer)

(Rank)

APPROVED: COURT OF INQUIRY OR BOARD OF INVESTIGATION

(b) (6)

BE HELD.

DATE SIGNED 19 APR 1967

SIGNATURE

CDR

USN

(Commanding Officer)

(Rank)

OPNAV FORM 3750-8F (REV. 3-83)

SPECIAL HANDLING REQUIRED. See OPNAV INST 3750 AE for instructions

## SECTION G

## ESCAPE, PERSONAL AND SURVIVAL EQUIPMENT

LIST AND CODE IN ACCORDANCE WITH SECTION G OF INSTRUCTION I

PHASE CODES: A-ACCIDENT/MISHAP E-ESCAPE/EGRESS PHASE  
B-SURVIVAL R-RESCUE PHASE

1 EQUIPMENT DESCRIPTION INCLUDING SPECIFIC MODEL DESIGNATION	2 IDENTIFICATION	3 RE- QUIRED	4 AVAIL- ABLE	5 NEED	6 USED	7 FAILED	8 REMARKS (Explain failures, loss, and/or difficulty encountered. Use additional 8x10 1/2 plain paper if needed.)
HELMET, PILOT'S PROTECTIVE TYPE APH-6		Y	A	A	A		SEE SECTION "H" BELOW
OXYGEN MASK		Y	A	A	A		
SIERRA RETENTION FITTINGS		Y	A	A	A		
COVERALLS, SUMMER, 100%, KHAKI		Y	A	A	A		
GLOVES, WINTER, BLACK		Y	A	A	A		
VEST, SURVIVAL, SQUARE MADE		Y	A	A			
knife, survival							
knife, MC-1, shroud							
SEEK kit, soft pak, I II							
flare gun, Penguin							
light, fresnel lens, matrix							
TORSO HARNESS, INTEGRATED MA-2		Y	A	A	A		
BOOTS, IRON AGE		Y	A	A	A		
LIFE JACKET	MK-3C	Y	A	A			
PARACHUTE	NB-7D	Y	A	A			
LIFE RAFT	PK2A	Y	A				
UNDERWEAR, THERMAL			A	A	A		

## SECTION H

## NARRATIVE OF ESCAPE/EGRESS, SURVIVAL AND RESCUE PHASES

SEE ADDENDUM TO SECTION "H", PAGE FIVE.

MODR NO. 1-67	MODEL A/C A3B	BUNO 138917	IDENTIFICATION OF INDIVIDUAL "A"
------------------	------------------	----------------	-------------------------------------

NAME OF INDIVIDUAL

PARKS, Richard E. LCDR USN (b) (6)

ADDENDUM TO SECTION "H" ON PAGE FIVE(5) OF INDIVIDUAL "A"'S OF  
MEDICAL OFFICER'S REPORT ON AAR 1-67A OF HEAVY ATTACK SQUADRON  
ONE TWO THREE, OAK HARBOR, WASHINGTON

It should be noted that the items listed under each individual's section "G" are those which were presumed to be on his person at the time of the accident. Recollections of squadron contemporaries, para-loft checkout cards and this squadron's usual adherence to NATOPS requirements provide the basis for the reported data. Bits and pieces of survival gear, boots, gloves, flight suits, torso harnesses and lap belts were found. One lap belt was found in the locked position but pulled away from the seat at the retaining bolts on either side. Finding the AN/PRC-17A radio, which was known to be in the fourth seat survival gear, four parachutes and harnesses and inertial reels and two escape chute door actuating cylinders with an unfired cartridge in one (see enclosure III.1.), comprised the basis for concluding that no egress had been attempted.

That no egress was attempted seems peculiar. Several elements require discussion. As noted in enclosure (II.B), the weather was intermittently IFR/VFR. At the time the aircraft began to deviate from its flight path, regardless of the reason for the mechanical failure, the pilot may have sought a lower altitude voluntarily. Of course, the aircraft was probably uncontrollable. The sudden onset of erratic, high "G" maneuvers coupled with very unusual aircraft attitudes undoubtedly interfered with the effectiveness of any attempts at egress. Presuming that just prior to impact the aircraft was coming under some degree of control, the crewmembers may have considered themselves high enough above the terrain to effect a recovery without having to bailout.

The snow showers were probably at a lower level than expected. (During the week immediately following the accident the snow showers were periodically down to the 4-5,000 foot levels.) When the pilot realized the gravity of the situation; i.e., approaching trees, it was too late.

Lastly, egress from this type aircraft is sorely compromised by the addition of the fourth person. Ditch and bailout drills have been held with the aircraft on the ramp. With three persons the aircraft can be emptied in less than one minute. The addition of the fourth crewmember doubles the time required for all to exit. If this observation is true under controlled circumstances, it must be of even greater significance in actual in-flight emergencies. Since the total time between the onset of the emergency (as noted by the radar operator on his screen) and the occurrence of the accident was estimated to be less than two(2) minutes, the plausibility of the foregoing premise is credible.

LIST AND CODE IN ACCORDANCE WITH SECTION G OF INSTRUCTION: PHASE CODES: A-ACCIDENT/MISHAP E-ESCAPE/EGRESS PHASE  
 B-SURVIVAL B-RESCUE PHASE

1 EQUIPMENT DESCRIPTION INCLUDING SPECIFIC MODEL DESIGNATION	2 MODIFICATION	3 RE- QUIRED	4 AVAIL- ABLE	5 NEED	6 USED	7 FAILED	8 REMARKS [Explain failures, loss, and/or difficulty encoun- tered. Use additional 8x10 1/2 plain paper if needed.]
HELMET, PILOT'S PROTECTIVE A-13A		Y	A	A	A		SEE SECTION "H" BELOW
OXYGEN MASK		Y	A	A	A		
SIERRA RETENTION FITTINGS		Y	A	A	A		
COVERALLS, SUMMER, FLIGHT KHAKI		Y	A	A	A		
VEST, SURVIVAL, SQUADRON MADE		Y	A	A			
knife, survival 5"							
knife, MC-1, shroud cutter							
SEEK kit, soft pak, I & II							
flare gun, Penguin							
light, fresnel lens, matrix							
TORSO HARNESS, INTEGRATED MA-2		Y	A	A	A		
BOOTS, IRON AGE		Y	A	A	A		
LIFE JACKET	MK-3C	Y	A	A			
PARACHUTE	NB-7D	Y	A	A			
LIFE RAFT	PK2A	Y	A				
UNDERWEAR, THERMAL			A	A	A		

SECTION H NARRATIVE OF ESCAPE/EGRESS, SURVIVAL AND RESCUE PHASES

SEE ADDENDUM TO SECTION "H" OF INDIVIDUAL A's PAGE FIVE.

NR 1-67	MODEL A/C A3B	BUND 138917	IDENTIFICATION OF INDIVIDUAL "H"
NAME OF INDIVIDUAL KING, Donald E. LCDR USN (b)(6)			



## MEDICAL OFFICER'S REPORT OF ACCIDENT, INCIDENT, OR GROUND ACCIDENT — PAGE 5

OPNAV REPORT 3750-7

OPNAV FORM 3750-87 (REV. 3-83)

SPECIAL HANDLING REQUIRED. See OPNAV INST 3750.6E for instructions

SECTION G

ESCAPE, PERSONAL AND SURVIVAL EQUIPMENT

LIST AND CODE IN ACCORDANCE WITH SECTION 6 OF INSTRUCTION:

PHASE CODES: A-ACCIDENT/MISHAP  
S-SURVIVALE-ESCAPE/EGRESS PHASE  
R-RESCUE PHASE

1 EQUIPMENT DESCRIPTION INCLUDING SPECIFIC MODEL DESIGNATION	2 MODIFICATION	3 RE- QUIRED	4 AVAIL- ABLE	5 NEED	6 USED	7 FAILED	8 REMARKS (Explain failures, loss, and/or difficulty encountered. Use additional 8x10 1/2 plain paper if needed.)
HELMET, PILOT'S PROTECTIVE APH-6		Y	A	A	A		SEE SECTION "H" BELOW
OXYGEN MASK	A-13A	Y	A	A	A		
SIERRA RETENTION FITTINGS		Y	A	A	A		
COVERALLS, SUMMER, FLIGHT, ORANGE		Y	A	A	A		
GLOVES, SUMMER, FLIGHT		Y	A	A	A		
VEST, SURVIVAL, SQUADRON MADE		Y	A	A			
knife, survival 5"							
knife, MC-1, shroud cutter							
SEEK kit, soft pak, I & II							
flare gun, Penguin							
light, fresnel lens, matrix							
compass							
TORSO HARNESS, INTEGRATED MA-2		Y	A	A	A		
BOOTS, IRON AGE		Y	A	A	A		
LIFE JACKET	MK-3C	Y	A	A			
PARACHUTE	NB-7D	Y	A	A			
LIFE RAFT	PK-2A	Y	A				

SECTION H

NARRATIVE OF ESCAPE/EGRESS, SURVIVAL AND RESCUE PHASES

SEE ADDENDUM TO SECTION "H" OF INDIVIDUAL A's PAGE FIVE.

MOD NO	MODEL A/C	BS/NO	IDENTIFICATION OF INDIVIDUAL
1-67	A3B	138917	"R"
NAME OF INDIVIDUAL READER, James M., LCDR USNR (b) (6)			

DP-08

☆ U. S. GOVERNMENT PRINTING OFFICE: 1965-646526

OPNAV FORM 3780-80 (REV. 3-63)

SPECIAL HANDLING REQUIRED. See OPNAV INST 3750 AE for instructions.

SECTION I DETAILS OF ESCAPE/EGRESS/SURVIVAL PHASES REFER TO SECTION I OF INSTRUCTIONS

1. TOPOGRAPHY OF INDIVIDUAL'S LANDING SITE

☒ WATER ☒ LAND ☐ OTHER Aircraft crashed through trees, impacted with ground and exploded. No fire.

2. TYPE OF EGRESS

☐ EJECTION ☐ BAILOUT ☐ UNDERWATER ☐ NORMAL ☐ OTHER (State type)

3.	4.	REMARKS
<input checked="" type="checkbox"/>	3. NOT ATTEMPTED	Apparently did not realize actual terrain altitude.
	4. ATTEMPTED	
	5. ACCOMPLISHED	
	6. THRU CANOPY	
YES	EGRESS DIFFICULTIES	IF YES, EXPLAIN DIFFICULTIES
<input checked="" type="checkbox"/>	7. PRIOR TO EGRESS	Aircraft presumed in near uncontrollable condition.
	8. DURING EGRESS	
	9. SUBSEQUENT TO EGRESS	

10. GIVE TYPE AND MODEL OF EJECTION SEAT USED

☐ PRIMARY ☐ SECONDARY ☐ OTHER

11. SEQUENCE OF EJECTION

12. POSITION OF SEAT ON EJECTION

☐ UP ☐ DOWN ☐ FORWARD ☐ AFT ☐ OTHER 35° div e, slight left wing down IMPACT

13. AIRSPEED

396 KTS (est)

14. ALTITUDE AT TIME OF EXIT (FEET)

ABOVE SEA LEVEL: 7400

15. ABOVE TOPOGRAPHY

N.A.

16. WAVE INTERVAL

N.A.

17. AIR TEMPERATURE

N.A.

18. TIME IN RAFT

N.A.

19. WIND VELOCITY

13-15 Kts.

20. WATER TEMPERATURE

N.A.

21. WAVE HEIGHT

N.A.

22. VISIBILITY

Snow showers, 1/2 miles

23. ALKING FACTORS

Seattle Center radar lost contact @ 1431

NORAD radar lost contact @ 1431.9

Farmer heard explosion, saw smoke, notified sheriff.

Snow 4-5 feet deep

24. MEANS OF LOCATING ACCIDENT SITE

Air search-light civil a/c (sheriff)

Air search-military a/c (HU-16, F-101, C-130)

Ground search-and-cat and sheriff's party

25. MEANS OF LOCATING SURVIVOR

Navy flight surgeon from NAS Fallon, sheriff's

party and forest rangers confirmed no survivors.

26. DID INDIVIDUAL DEPART FROM LANDING SITE

(If Yes, Explain reason and sequence up to rescue)

☒ NO ☐ YES

SECTION II TRAINING FACTORS

1. DATE OF LAST TRAINING

LPC 7 MAR 66

EJECTION TOWER 7 MAR 66

EJECTION SEAT 7 MAR 66

SURVIVAL

2. DID THE LACK OF TRAINING AND/OR EXPERIENCE PLAY A PART IN ANY PHASE OF THIS MISHAP? (If yes, explain)

☐ NO ☒ YES

An indicated in enclosure (X) and as experienced two days after this accident by a sister squadron flying the same type aircraft, the loss of an engine particularly if combined with an explosion, can create a catastrophic situation. Weather, pilot recognition of the severity of his predicament and reaction time, aircraft maneuvers which could easily produce panic or at least vertigo--are all factors which would diminish the possibility of salvaging a recovery. VFR conditions and sufficient altitude have allowed others to extricate themselves from this potentially fatal situation. Whether or not any pilot could have effected a recovery in the present set of circumstances is conjectural.

WORK NO.

MODEL A/C

BUND

IDENTIFICATION OF INDIVIDUAL

1-67

A3B

138917

A

NAME OF INDIVIDUAL

PARKS, Richard E. LCDR (b) (6)

OP-05F

U. S. GOVERNMENT PRINTING OFFICE: 1963-698-431

## SECTION I DETAILS OF ESCAPE/EGRESS/SURVIVAL PHASES REFER TO SECTION I OF INSTRUCTIONS

## 1. TOPOGRAPHY OF INDIVIDUAL'S LANDING SITE

☐ WATER☒ LAND☐ OTHER

Aircraft crashed through trees, impacted with ground and exploded. No fire.

## 2. TYPE OF EGRESS

☐ EJECTION☐ BAILOUT☐ UNDERWATER☐ NORMAL☐ OTHER (State type)

B

E

## REMARKS

☒ 3. NOT ATTEMPTED

Apparently did not realize actual terrain altitude.

4. ATTEMPTED

5. ACCOMPLISHED

6. THRU CANOPY

YES

NO

EGRESS DIFFICULTIES

IF YES, EXPLAIN DIFFICULTIES

☒

7. PRIOR TO EGRESS

Aircraft presumed in near uncontrollable condition.

8. DURING EGRESS

9. SUBSEQUENT TO EGRESS

## 10. GIVE TYPE AND MODEL OF EJECTION SEAT USED

N.A.

## 11. METHOD OF FIRING SEAT

☐ PRIMARY☐ SECONDARY☐ OTHER

## 12. SEQUENCE OF EJECTION

## 13. POSITION OF SEAT ON EJECTION

☐ UP☐ DOWN☐ FORWARD☐ AFT☐ OTHER14. ATTITUDE OR MANEUVER OF A/C AT EGRESS  
IMPACT  
35° dive, slight left wing down

## 15. AIRSPEED

396 KTS (est)

## 16. ALTITUDE AT TIME OF EGRESS

IMPACT

## 17. ALTITUDE OF PARACHUTE OPENING

N.A.

## 18. WEIGHT

173

## 19. ABOVE SEA LEVEL

7400

## 20. ABOVE TOPOGRAPHY

## 21. TIME IN WATER

N.A.

## 22. TIME IN RAFT

N.A.

## 23. WIND VELOCITY

13-15 KTS

## 24. WAVE HEIGHT

N.A.

## 25. WAVE INTERVAL

N.A.

## 26. AIR TEMPERATURE

15-30° F

## 27. WATER TEMPERATURE

N.A.

## 28. VISIBILITY

Snow showers 1/2 mile

## 29. ALERTING FACTORS

Seattle Center radar lost contact @ 1431

NORAD radar lost contact @ 1431.9

Farmer heard explosion, saw smoke, notified sheriff. Snow 4-5 feet deep

## 30. MEANS OF LOCATING ACCIDENT SITE

Air search-light civil a/c (sheriff)

Air search-military a/c (HU-16, F-101, C-130)

Ground search-sno cat and sheriff's party

## 31. MEANS OF LOCATING SURVIVOR

Navy flight surgeon from NAS Fallon, sheriff's

party and forest rangers confirmed no

survivors.

## 32. DID INDIVIDUAL DEPART FROM LANDING SITE?

(If Yes, Explain reason and sequence up to rescue)

☒ NO ☐ YES

## SECTION J

## TRAINING FACTORS

## 1. DATE OF LAST TRAINING

LPC 12 SEPT 64

EJECTION TOWER

22 DEC 66

EJECTION SEAT

22 DEC 66

## SURVIVAL

## 2. DID THE LACK OF TRAINING AND/OR EXPERIENCE PLAY A PART IN ANY PHASE OF THIS MISADVENTURE (If yes, explain)

☐ NO ☒ YES

See remarks under individual "A". This pilot was instructor with considerable flight time, experience as LSO and previous tours with aircraft. Since he was flying in the B/N seat, he could not have done more that tell the pilot in command what to do. In the short interval that information may not have been forthcoming since there is a question that all radios were lost about the time of the accident.

## MOR NO.

## MODEL A/C

A3B

## BUNO

138917

## IDENTIFICATION OF INDIVIDUAL

H

## NAME OF INDIVIDUAL

1-67  
KING, Donald E. LCDR (b)(6)



MEDICAL OFFICER'S REPORT OF AN ACCIDENT, INCIDENT, OR GROUND ACCOUNT - PAGE 6

OPNAV REPORT 3750-7

OPNAV FORM 3750-8G (REV. 3-63)

SPECIAL HANDLING REQUIRED. See OPNAV INST 3750.6E for instructions

SECTION I

DETAILS OF ESCAPE/EGRESS/SURVIVAL PHASES REFER TO SECTION I OF INSTRUCTIONS

1. TOPOGRAPHY OF INDIVIDUAL'S LANDING SITE

☐ WATER ☒ LAND ☐ OTHER

Aircraft crashed through trees, impacted with ground and exploded. No fire.

2. TYPE OF EGRESS

☐ EJECTION ☐ BAILOUT ☐ UNDERWATER ☐ NORMAL ☐ OTHER (State type)

3. E

REMARKS

X 3. NOT ATTEMPTED

Apparently did not realize actual terrain altitude.

4. ATTEMPTED

5. ACCOMPLISHED

6. THRU CANOPY

YES NO

EGRESS DIFFICULTIES

IF YES, EXPLAIN DIFFICULTIES

X 7. PRIOR TO EGRESS Aircraft presumed in near uncontrollable condition.

8. DURING EGRESS

9. SUBSEQUENT TO EGRESS

10. GIVE TYPE AND MODEL OF EJECTION SEAT USED

N.A.

☐ PRIMARY ☐ SECONDARY ☐ OTHER

12. SEQUENCE OF EJECTION

13. POSITION OF SEAT ON EJECTION

☐ UP ☐ DOWN ☐ FORWARD ☐ AFT ☐ OTHER

14. ALTITUDE OR MANEUVER OF A/C AT IMPACT

35° dive, slight left wing down

15. AIRSPEED

396 KTS(est)

16. ALTITUDE AT TIME OF EXIT

IMPACT

17. ALTITUDE OF PARACHUTE OPENING

N.A.

18. WEIGHT

193

ABOVE SEA LEVEL 7400

ABOVE TOPOGRAPHY

19. TIME IN WATER

N.A.

20. TIME IN RAFT

N.A.

21. WIND VELOCITY

13-15 KTS

22. WAVE HEIGHT

N.A.

23. WAVE INTERVAL

N.A.

24. AIR TEMPERATURE

15-30° F

25. WATER TEMPERATURE

N.A.

26. VISIBILITY

Snow showers 1/2 mile

27. ALERTING FACTORS

Seattle center radar lost contact @ 1431

N.A.

MDRAD radar lost contact @ 1431.9

Farmer heard explosion, saw smoke, notified sheriff.

Snow 4-5 feet deep

28. MEANS OF LOCATING ACCIDENT SITE

Air search-light civil a/c (sheriff)

N.A.

Air search-military a/c (HU-16, F-101, C-130)

N.A.

Ground search-sno cat and sheriff's party

N.A.

29. MEANS OF LOCATING SURVIVOR

Navy flight surgeon from NAS Fallon, sheriff's party and forest rangers confirmed no survivors.

N.A.

N.A.

30. DID INDIVIDUAL DEPART FROM LANDING SITE?

(If Yes, Explain reason and sequence up to rescue)

☒ NO ☐ YES

SECTION II

TRAINING FACTORS

1. DATE OF LAST TRAINING

LPC 23 MAR 67

EJECTION TOWER

9 DEC 63

EJECTION SEAT

23 MAR 67

SURVIVAL

2. DID THE LACK OF TRAINING AND/OR EXPERIENCE PLAY A PART IN ANY PHASE OF THIS MISHAP? (If yes, explain)

☐ NO ☒ YES

See remarks under individual "A". This pilot was on leave to come to Oak Harbor to see his wife. He had apparently not had a formal ditch and bailout drill but was most likely briefed by the pilot in command. He is presumed to have ridden in the seat behind the pilot since the plane captain has to move about prior to takeoff and assist with checklist items. He is not considered as having contributed to the lack of attempt for bailout.

MOD NO.

MODEL A/C

A3B

SURO

138917

IDENTIFICATION OF INDIVIDUAL

R

NAME OF INDIVIDUAL

READER, James M. LCOR (b) (6)



SECTION I DETAILS OF ESCAPE/EGRESS/SURVIVAL PHASES REFER TO SECTION I OF INSTRUCTIONS

1. TOPOGRAPHY OF INDIVIDUAL'S LANDING SITE		Aircraft crashed through trees, impacted with ground and exploded. No fire.	
<input type="checkbox"/> WATER	<input checked="" type="checkbox"/> LAND	<input type="checkbox"/> OTHER	
2. TYPE OF EGRESS			
<input type="checkbox"/> EJECTION	<input type="checkbox"/> BAILOUT	<input type="checkbox"/> UNDERWATER	<input type="checkbox"/> NORMAL <input type="checkbox"/> OTHER (State type)
3. E	REMARKS		
<input checked="" type="checkbox"/> 3. NOT ATTEMPTED	Apparently did not realize actual terrain altitude.		
<input type="checkbox"/> 4. ATTEMPTED			
<input type="checkbox"/> 5. ACCOMPLISHED			
<input type="checkbox"/> 6. THRU CANOPY			
YES NO	IF YES, EXPLAIN DIFFICULTIES		
<input checked="" type="checkbox"/> 7. PRIOR TO EGRESS	Aircraft presumed in near uncontrollable condition.		
<input type="checkbox"/> 8. DURING EGRESS			
<input type="checkbox"/> 9. SUBSEQUENT TO EGRESS			
10. GIVE TYPE AND MODEL OF EJECTION SEAT USED		11. METHOD OF FIRING SEAT	
N.A.		<input type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> OTHER	
13. POSITION OF SEAT ON EJECTION		14. ATTITUDE OR MANEUVER OF A/C AT IMPACT	
<input type="checkbox"/> UP <input type="checkbox"/> DOWN <input type="checkbox"/> FORWARD <input type="checkbox"/> AFT <input type="checkbox"/> OTHER		35° dive, slight left wing down	
16. ALTITUDE AT TIME OF EXIT		15. AIRSPEED	
IMPACT		396 KTS (est)	
ABOVE SEA LEVEL 7400		17. ALTITUDE OF PARACHUTE OPENING	
N.A.		180	
19. TIME IN WATER		21. WIND VELOCITY	
N.A.		13-15 KTS	
23. WAVE INTERVAL		25. WATER TEMPERATURE	
N.A.		N.A.	
27. ALERTING FACTORS		29. SNOW SHOWERS	
Seattle Center radar lost contact @ 1431		N.A.	
NORAD radar lost contact @ 1431.9		N.A.	
Farmer heard explosion, saw smoke, notified sheriff.		Snow 4-5 feet deep	
Air search-light w/ civil aircraft (sheriff)		N.A.	
Air search-military a/c (H1-16, F-101, C-130)		N.A.	
Ground search-and cat and sheriff's party		N.A.	
Navy flight surgeon from NAS Fallon, sheriff's party and forest rangers confirmed no survivors.		N.A.	
N.A.		N.A.	
36. DID INDIVIDUAL DEPART FROM LANDING SITE? (If Yes, Explain reason and sequence up to rescue)			
<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES			

SECTION II TRAINING FACTORS	
1. DATE OF LAST TRAINING	2. DID THE LACK OF TRAINING AND/OR EXPERIENCE PLAY A PART IN ANY PHASE OF THIS MISHAP? (If yes, explain)
LPC 17 FEB 66	<input type="checkbox"/> NO <input checked="" type="checkbox"/> YES See remarks under individual "A". No training factors are considered applicable to this aircrewman for the squadron holds periodic ditch and bailout drills for all plane captains.

MOR NO. 1-67	MODEL A/C A3B	SUNG 138917	IDENTIFICATION OF INDIVIDUAL X
NAME OF INDIVIDUAL MILLER, Catt V., Jr. ADJ3 (b) (6)			


CONCLUSIONS AND RECOMMENDATIONS OF THE MEDICAL OFFICER ON AAR 1-67A,  
HEAVY ATTACK SQUADRON ONE TWO THREE, OAK HARBOR, WASHINGTON

A. CONCLUSIONS

1. It is concluded that the sudden material failure of the port engine produced such an instantaneously unusual attitude that the aircraft and its occupants were in extremis without any forewarning. Foul weather in the form of snow showers and terrain in the form of a mountain range contributed to the final fatal outcome. All evidence thus far is based on limited retrieval of aircraft parts and human remains due to snow cover at the accident site.

2. That there were no survivors to this accident may be due to one or more of the following factors: the rapidity of onset, the severity of aircraft maneuvers with high "G" forces involved, the pilot's hope of finding VFR conditions at a lower altitude but above the terrain, the regaining of some control over the aircraft, the short time span between onset of emergency and impact with the ground, the presence of the fourth crewmember and the lack of an ejection device.

3. (b) (5)



4. Psychological and physiological factors were considered; first, as a cause of the accident; next, as contributing to or compromising the handling of the accident; and lastly, as an explanation for the fatal outcome of all four crewmembers.

a. Hypoxia was pondered and discarded. Standard crew doctrine is that either the pilot or B/N will be on oxygen at all times even though the aircraft is pressurized. There have been enough episodes of cracked windshields and canopy panels that this rule is never violated. That the pressurization system failed slowly seems remote. It is possible but not probable since no yellow sheet ~~entire~~ noted such a discrepancy. Failure of the pressurization system has occurred in the past but was usually gradual in onset; i.e., recorded after several flights. Explosive decompression may have happened. Maintenance

ENCLOSURE (IX)

CONCLUSIONS AND RECOMMENDATIONS OF THE MEDICAL OFFICER ON AAR 1-67A,  
HEAVY ATTACK SQUADRON ONE TWO, THREE, OAK HARBOR, WASHINGTON (continued)

personnel who have been involved in other accidents in which engines disintegrated in flight have never known shrapnel to enter the fuselage in the region of the pressurization system. Had it occurred from a cracked canopy panel the aircraft dropped from 18,000 feet to impact point at 7,400 feet so rapidly that little effect could reasonably be expected as far as influencing the outcome.

b. Inflight fire has been suggested by the finding of one burned piece of fiberglass material from a fuel cell liner. On the other hand none of the tissue or personal equipment found bears any evidence of burning.

c. The crew apparently had eaten since an apple core was found in the wreckage. Review of the health records showed nothing related to hypoglycemic episodes in any of the crew.

d. The pilot, LCDR PARKS, was highly motivated and performing in an above average manner in the syllabus. Although he had had no previous experience in jet aircraft prior to his commencing jet instrument school in VF-126, he was considered to be a strong student. Whether or not any pilot could have averted disaster in this particular situation is an unanswerable rhetorical question.

In summary, no psychological or physiological factor is considered as causing the accident, contributing to it or significantly compromising any feature pertaining to its course.

B. RECOMMENDATIONS


1. This Flight Surgeon concurs with the recommendations of the AAR, particularly the expeditious installation of the Yankee extraction system.

2. Further recommendations will necessarily await the acquisition of more evidence from the accident site.

(b) (6)

LCDR MC USN

ENCLOSURE (IV)





RESCUE REPORT

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH INSTRUCTIONS: SEE REVERSE

OPNAV FORM 3750-13 (3-63) IIA 9107-601-7230

INSTRUCTIONS: SEE REVERSE

OPNAV REPORT SYMBOL 3750-14

1. FROM <b>COMMANDING OFFICER, HEAVY ATTACK SQUADRON-123</b>		2. DATE OF RESCUE <b>5 April 1967</b>		3. DATE OF RESCUE <b>NONE</b>	
3. LOCATION AND DUTIES OF RESCUE VEHICLE <b>11°20 120° 15 SEARCH FOR MISSING AIRCRAFT</b>		4. RESCUE VEHICLE (Type/model) <b>SEE PARA 12</b>		5. RESCUE BACK UP MEANS <b>FOREST SERVICE "SNOW CAT"</b>	
6. NUMBER OF PERSONNEL <b>100 BOY</b>	7A. IN RESCUE VEHICLE OR ON RESCUE TEAM <b>20 BOY</b>	7B. TO BE RESCUED <b>0</b>	7C. RESCUED <b>0</b>	7D. TIME SEQUENCE OF EVENTS (Local Date Time Group)	
7E. Alerts Received Method <b>051311H SEATTLE CENTER LOST RADIO CONTACT</b>		7F. Vehicle Reported Distance to Scene <b>051350H 250 NM</b>			
7G. Arrived on Scene Search Required <b>051700H AIRBORNE SEARCH FOR POSS SURVIVORS</b>		7H. Created Survivors Method of Locating <b>060300H AIRCRAFT C-47 LOST BY LIGHT</b>			
7I. Report Received What Was Sighted/First <b>060300H DIRECTED TO SITE BY RADIO FROM A-6</b>		7J. Report Received Subsequently <b>061644H RESCUE ATTEMPT CLOSED</b>			
7K. Survivor(s) Location (If different from Item 3) <b>Discovered</b>		7L. WEATHER CONDITIONS AT RESCUE SITE <b>SEA STATE: WAVE HEIGHT/FREQUENCY, TERRAIN DESCRIPTION MOUNTAINOUS CRASH SITE ELEVATION 7000 - 7500 FEET MSL, HEAVILY TIMBERED.</b>			
7M. EQUIPMENTS ACTUALLY USED DURING RESCUE <b>FOREST SERVICE "SNOW CAT"</b>		10. DIFFICULTIES ENCOUNTERED (List all difficulties and effect on final outcome of rescue attempt, i.e., ALERTING PERIOD, SEARCH/LOCATING, RETRIEVING, POST-RETRIEVAL) <b>AIRBORNE SEARCH HAMPED BY LOW CLOUDS, SNOW AND RAIN. SURFACE SEARCH MOVEMENT RESTRICTED DUE TO DEEP AND DRIFTING SNOW.</b>			

11. PERSONNEL REQUIRING RESCUE NAME- LAST FIRST INITIAL			GIVE REASON FOR RESCUE	FACTORS COMPLICATING RESCUE ATTEMPT Physical condition, ignorance of equipment, sea state, etc.
<b>DECE</b>			<b>Certified to be true</b>	
			<b>(b) (6)</b>	
			<b>LCDR</b>	<b>USN</b>

12. REMARKS: (Training of rescue teams or crews, communication equipments/technique, retrieval equipments/technique, rescue vehicle)

- THESE WERE NO SURVIVORS OF THIS CRASH.
- ALL SEARCH AND RESCUE ACTIVITIES WERE DIRECTED BY WESTERN AEROSPACE RESCUE AND RECOVERY CENTER, HAMILTON AFB.
- PARA 4. SEARCH AND RESCUE VEHICLES: (1) USAF C-130; (2) USAF HU-16; (1) USN HU-16; (1) USAF H-19; (2) USN CH-34; (2) USN A-6; (1) USN P-3.
- A CONSTANT AIRBORNE SEARCH WAS MAINTAINED UNTIL IDENTIFICATION OF DEGRADED AIRCRAFT WAS CONFIRMED.

13. ATTACH ENCLOSURES: Narratives of search, location and retrieving—Survivor's statements

14. NAME AND TITLE OF SUBMITTING OFFICIAL <b>LT (b) (6) ASST AVIATION SAFETY OFFICER</b>		SIGNATURE OF SUBMITTING OFFICIAL
15. NAME AND TITLE OF FORWARDING OFFICIAL <b>J. F. SUNDING, COMMANDING OFFICER</b>		SIGNATURE OF FORWARDING OFFICIAL

X 5100 ENGINE SECTION

X 1100 WING SKIN

X 1100 WING SKIN

205°M

X 1100 SKIN

X 1100 ENGINE SECTION

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

GROUND IMPACT

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

X 1100 SKIN

Enclosure (4)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6B

FELT

craft accident involving an A3B, NJ309, (BUNO 138917) on 5 April 1967.

I was a passenger in NJ309 (BUNO 138917) on a scheduled flight from NAS Whidbey to NAS Miramar on 4 April 1967. Assigned crewmembers were LCDR D. E. KING, pilot in command; LCDR R. E. PARKS, FRP; and C. V. MILLER, ADJ3, plane captain. We manned the aircraft at 1950. LCDRS KING and PARKS conducted the pre-flight in company with MILLER. All of us were wearing at least the minimum required survival equipment, i.e., torso harness, MK3C, APH-5 or APH-6, oxygen mask, and survival vest. Seating positions were as follows: LCDR PARKS, pilot's seat; LCDR KING, B/N seat; LCDR (b) (6), C/N or 3rd seat; and MILLER, 4th seat.

Starting procedures, taxi, ATC clearance instructions, take-off, climb-out, and level-off were normal and check lists utilized where required. We were airborne at 2021 (local) according to my watch. LCDR PARKS leveled-off on the assigned altitude of FL 210, and set up a cruise speed of 450 KTAS. The flight progressed normally in all respects. LCDR PARKS seemed to have the aircraft under control at all times. The auto pilot was not used. On one occasion LCDR KING told LCDR PARKS to watch his altitude. I don't know how much he had deviated from the assigned flight level. In-flight checks were conducted at least once each 30 minutes and all systems were normal. LCDR KING remarked that he thought the AN/C-27 UHF receiver was weak, but it sounded all right to me. Approaching the terminal area, LCDR PARKS asked LCDR KING if he should execute a tacan approach. LCDR KING said, "No, let's request a random radar penetration with a GCA hand-off. It's getting late and I'll give you a good work out tomorrow." The descent was routine and LCDR PARKS flew an excellent GCA. The landing touchdown was considerably harder than normal; however, in my opinion, it was not of sufficient magnitude to "down" the aircraft for a hard landing inspection. In addition, I was experiencing some physical discomfort in my abdomen due to recent surgery and a poor fitting torso harness; it had been nearly nine months since my last flight in A3B aircraft; and I was riding facing aft. These three factors possibly bear on my opinion as to how hard the landing was. LCDR KING acknowledged that the landing was hard by kidding LCDR PARKS about it. On the landing roll-out, LCDR PARKS asked LCDR KING if he should deploy the drag chute. LCDR KING's answer was rapid and emphatic, "Yes, on every landing!" The engines were shut down at 2255 (local). We went directly to the BOQ after closing out the flight plan. LCDR KING and I talked for a while, read for a few minutes and had the lights out on or about 2400. I don't know what time LCDR PARKS retired. He changed into civilian dress and said he was going to the TV lounge to watch the late movie. LCDR KING and I were awakened at 0700, dressed, had a substantial breakfast and reported to MCW-12 at 0800 in company with LCDR (b) (6). I don't know what time LCDR PARKS arose. In my

Enclosure (5)



opinion, LCDR KING and PARKS occupied the same seats for the trip home. LCDR PARKS was scheduled to receive an instrument check either on the way to or from NAS Miramar. No emergency procedures were given by LCDR KING on the way down, and he twice told LCDR PARKS that "I'll work you hard tomorrow." I was designated a Naval Aviator in August 1953. I have approximately 4,800 hours of flight time, of which nearly 1,200 is in the A3B aircraft.

(b) (6)



MILITARY FLIGHT PLAN		AIRCRAFT UNIT OF ASSIGNMENT/HOME STATION		AIRCRAFT SERIAL NO.	
TYPE OF FLIGHT PLAN <input type="checkbox"/> FIR <input type="checkbox"/> OVER <input type="checkbox"/> VFR <input type="checkbox"/> FVFR		RADIO CALL N1307		AIRCRAFT DESIGNATION TO CODE A3/B	
ESTIMATED TRUE AIRSPEED		DEPARTURE TIME (Z)		PROPOSED <input type="checkbox"/> ACTUAL <input checked="" type="checkbox"/> 2116Z	
INITIAL CRUISING ALTITUDE FL 220		POINT OF DEPARTURE NAS MIRAMAR		STANDARD INSTRUMENT DEPARTURE	
NAME AND NUMBER SAMPEDIO TWO		TO		ETC	
ROUTE OF FLIGHT					
<p>315/1</p> <p>FL 220</p> <p>IC</p> <p>SP</p> <p>7</p>					
REMARKS					
<p>VER DEPARTURE WEST</p> <p>280° Radial NMK TACAN</p> <p>AFTER TAKE-OFF</p>					
BANK/HONOR CODE		PSGR/CARGO CODE			
HOURS FUEL ON BOARD 3+30		DIST TO DESTN 1000		ALTERNATE AIR FIELD McChes AFB	
ETE TO ALTH 0710		NOTAMS		DD FORM 355F (Rt. and Del.)	
WEATHER		REQUEST CLEARANCE AFTER		DATE 4-5-67	
INST RATING SPEC		SIGNATURE OF PILOT IN COMMAND		SIGNATURE OF APPROVING AUTHORITY (b) (6) Captain U. S. Navy	
CREW/PASSENGER LIST - <input checked="" type="checkbox"/> Attached <input type="checkbox"/> See Passenger Manifest					
DUTY		NAME AND INITIALS		GRADE	
SERVICE NO.		ORGANIZATION AND LOCATION			
PILOT IN COMMAND		PARE, R.E.		LCDR	
		KING, D.E.		LCDR	
		MILNER, C.V. JR.		ADJ3	
		READER, J.M.		LCDR	
Certified to be true					
(b) (6)					
LCDR USN Enclosure (6)					
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPMVINST 3750.62					

# FLIGHT WEATHER BRIEFING

AIRCRAFT NO.

138917

BRIFING NO.

4-050

DATE

4-5-67

I.

TAKEN DATA

RUNWAY TEMP.

PRESSURE ALT.

TEMP. DEVIATION

VAPOR PRESSURE

SPECIFIC HUMIDITY

DENSITY ALTITUDE

CLIMB WINDS

REMARKS

IFR/NUW/ETD 2111Z/JTSEA DNUW.  
ETC 2+16/

II.

ENROUTE DATA

FLIGHT LEVEL

TEMPERATURE

WINDS

22000

NKK-RNO 250-50 RNO-LKV 220-25  
KKK-JFA 050-15

CLOUDS AT FLIGHT LEVEL

VISIBILITY AT FLIGHT LEVEL

☐ YES ☒ NO ☐ IN AND OUT

☐ HAZE ☐ DUST ☐ SMOKE ☐ PRECIPITATION

MINIMUM CEILING ENROUTE

1800 NUVW 3500'

MAXIMUM CLOUD TOPS

25,000' SCDDCB

MINIMUM FREEZING LEVEL

2500'

THUNDER/TORNS

TURBULENCE

PRECIPITATION

ICING

☒ NONE

☐ NONE

☒ NONE

☐ NONE

FEW

☒ CAT

☒ LGT

☒ RAIN

☐ DRZL

☒ CLEAR

☒ LGT

SCATTERED

TSTM

☒ MOD

☐ SHOWERS

☐ SNOW

☐ RIME

☐ MOD

NUMEROUS

☐ SVR

☐ SVR

☐ FREEZING

☐ MIXED

☐ MIXED

☐ SVR

HAIL

☒ IN CLOUDS

III.

TERMINAL DATA

DESTINATION (E-MAIL)

NUW 1180 40070 110/05-29.93

FORECAST

180 3500 7 VAR 05-29.92 2330 Z TO 0130 Z

ALTERNATE (E-MAIL)

TCM 113000/030 210/03 29.91

FORECAST

200 8 VAR/05-29.91 2340 Z TO 0140 Z

IV.

COMMENTS/REMARKS

Certified to be true

(b) (6)

LGR

USN

Enclosure (6)

(b) (6)

VOID TIME

2145Z

EXTENDED TO

RELEASED

V.

TELEVISION/TELEPHONE BRIEFING RECORD

WEATHER FACILITY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.05

TAPE NO.

START

STOP

PHONE CHARGE

TRANSCRIPTION OF ARTC CONTROLLER EVENTS 1406 to 1436 5 APRIL 67

<u>TIME</u>	<u>CALLER</u>	<u>EVENT</u>
1406.30	NJ309	"RENO 155°/78NM FL 180"
1419	OAKLAND CTR	Attempted 4 calls to NJ309 with no contact.
1427	OAKLAND CTR	Oakland Center advised Seattle Center that NJ309 was 10NM south of 41 - OON. Seattle acknowledged radar contact.
1428.0	OAKLAND CTR	"NJ309 this Oakland over."
	NJ309	"Oakland 309, loud & clear."
	OAKLAND CTR	"NJ309, contact Seattle Center 306.3, over."
	NJ309	"309, roger 306.3"
1428.46	UNKNOWN	"GARBLED _ _ FL 180"
1430.06	NJ309	"Seattle Center, NJ309 FL 180"
1430.20	SEATTLE CTR	"NJ309, roger, FL 180, squak IDENT"
1430.58	SEATTLE CTR	"NJ309, Seattle Center, over."
1432	SEATTLE CTR	"NJ309, Seattle Center, over."
1436		Seattle Center requests Lakeview to call NJ309 on UHF guard channel.

The times and events listed above are correct. Oral transmission are copied from abbreviated material and subject to variance, however, contents and purpose of transmission is specific.

Certified to be true

(b) (6)

Enclosure (7)

LCDR USN

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E



Statement of Floyd NMN BROOKS, Rancher, Jess Valley, Modoc County,  
California

On 5 April about 2:30 P.M. I was working outside and heard an explosion and saw smoke from the area just above Soup Springs on the ridge line between the Springs and Mill Creek Meadows. About ten minutes before that I had heard a sonic boom. I did not at anytime see or hear an airplane. The weather was cloudy with snow flurries. I could see the ridge line but the top of Eagle Peak was hidden in the clouds. Several hours later I called the county sheriff in Alturas and reported the incident.

Floyd Brooks

The Board Considers This Statement Creditable

Certified to be true

(b) (6)

LCDR USN

Enclosure (8)


SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E



PROJECTED FLIGHT PATH TO IMPACT POINT

9 FLIGHT PATH






9- FLIGHT PATH



9-2 FLIGHT PATH




AIRCRAFT ENTRY ANGLE INTO IMPACT AREA



9. IMPACT ANGLE





9-4 WRECKAGE SITE





ENGINE PHOTOGRAPHS




VAH-123 SERIAL 1-676 5 APRIL 1967 4-3R BUND 133917 PILOT PARKS

ENCLOSURE (10) VIEWS SHOWING DAMAGE TO BOTH ENGINES  
SPECIAL HANDLING REQUIRED 14W OPNAVINST 3750.6E



11 COCKPIT INSTRUMENTS

ATM-50-7 MARKS INDICATING ROTATION



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18



ATM


50-10


ROTATION



11-2 #2 ATM SCROLL

BURNED FIBERGLASS MATERIAL SHOWING NUMEROUS  
INDICATIONS OF POSSIBLE INFILTRATION BURNING





# Maintenance Officers Statement

A3B BUNO 138917 had accumulated 438.6 hours in 7 months of its current period. The last Calendar ODD Inspection was completed on 16 January 1967, and 246.3 hours had been flown since the completion of that inspection. Review of the last ten "B" sections of the OPNAV Form 3760-2 is not possible due to the loss of these flight records in the accident. The below tabulation listing discrepancies and corrective action taken or currently outstanding was extracted from the maintenance control master register. Both engines had normal oil consumption during this operating period.

Table of Aircraft Maintenance History Extracted from VAH-123 Maintenance Control Register for A3B BUNO 138917

<u>DATE</u>	<u>JCN</u>	<u>DISCREPANCY</u>	<u>CORRECTIVE ACTION</u>
22 MAR 67	470	HYD LEAK NLG DOOR	INSPECTED - NO EVIDENCE
22 MAR 67	471	HYD LEAK TAIL SKAG	INSPECTED - NO EVIDENCE
22 MAR 67	472	HYD LEAK PORT WING	INSPECTED - NO EVIDENCE.
22 MAR 67	475	HYD LEAK PORT MLG ACT	RESEALED PORT MLG ACT CYL
22 MAR 67	479	2 SMALL UTIL HYD STRAINERS #1 ADU CPT LEAKING	INSPECTED UTIL HYD FILTER FOUND NO EVIDENCE OF LEAK
22 MAR 67	515	HYD LEAK WING FOLD AREA	INSPECTED - NO EVIDENCE
22 MAR 67	556	WASH A/C	WASHED
23 MAR 67	755	STBD FIRE WRNG LITE ON ALL TIMES	REMOVED AND RE-INSTALLED STBD ENGINE. FOUND C/P IN PYLON SHORTED, REPAIR SAME. FOUND TEST SWITCH BAD, REPLACED. FOUND 3 ELEMENTS BAD AND 2 FLEXION CONNECTORS REPLACED. MEGGER & TESTED X'S GOOD.
25 MAR 67	929	HYD LEAK ON HYD FILTER IN #1 ADU CPT	TIGHTENED FILTER, TURNED X'ED GOOD
26 MAR 67	943	PORT ENG LATE TO START (18-2070) SUSPECT BAD IGNITER	CHANGED BOTH IGNITERS TURNED UP, X'ED GOOD
(27 MAR 67 & 3 APR 67)	074  917	OUTBOARD PORT BLEED VALVE LOWER RIVET SHEERED	REPLACED BROKEN SEAL RING AND POPPED RIVET

Enclosure (12)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E



<u>DATE</u>	<u>JCN</u>	<u>DISCREPANCY</u>	<u>CORRECTIVE ACTION</u>
29 MAR 67	278	2 LET STARTS PRIOR TO SUCCESSFUL LITE OFF STBD ENG	CHECK IGNITION SWITCH FOR CORRECT ADJ. CYCLED IGNITION TIMER THRU 4 TIMES. RUN FOR 30 SEC EACH TIME. TURNED UP 2 TIMES, NO MALFUNCTION, 1 GOOD
29 MAR 67	315	#1 ADU LOOSE	TIGHTENED TOP MOUNT BOLT AND RE-SAFETTED
30 MAR 67	399	NOSE GEAR ALT CYL LEAKING SLIGHTLY	T/U NO LEAKAGE FROM RUNNING NOSE GEAR THRU 7 OR 8 TIMES
30 MAR 67	510	CHECK RUN DOWN TIME ON PORT ENG, CLOCK MAY BE OFF	REPAIRED SHORTED C/P ON PORT TACH GEN. ALSO XED TACH IND AND GEN. BY SUBSTITUTION RUN DOWN TIME 44 SEC WITH A/C PARTS AND NEW PARTS.
31 MAR 67	684	ADU OIL LEAK BY PORT BULKE HINGE	CHANGED #1 ADU GOVERNOR T. U. AND X'ED FOR LEAKS AND PROPER OPERATION, X'S OK
31 MAR 67	685	HORIZ STBD ACT OIL LEAK	SERVICED ACT FOUND NO LEAKS, X'S GOOD
31 MAR 67	707	SEVERAL SOFT SPOTS IN RUDDER	
2 APR 67	771	STBD FIRE WARN LITE ON	DRIED OUT SHORT PIGTAILS SYSTEM X'S GOOD
3 APR 67	810	FIRE WARN LITE STBD ENG NO IND OF FIRE ON OVER TEMP ON VIS INSP TURNED ENG FOR ABOUT 7-8 MIN ELECT X FOR LOOSE OR WET CONNECTORS. LIGHT REMAINS ON.	FLEX LEAD B.D. REPLACED 4 FLEX LEADS. X'S GOOD
3 APR 67	914	#1 ADU AC FREQ 380 #2 ADU AC FREQ 410 AT IDLE	RESET FREQ'S IN #1 & #2 ADU'S
(3 APR 67 & 4 APR 67)	916	ADU OIL LEAK	CHANGED #2 AC GEN CARLOC SEALS AND OIL PUNGE GASKET
4 APR 67	953	REMOVED & REPLACED AC GEN	REMOVED & REPLACED #2 GEN X'S GOOD ON TURN

(b) (6)

LCDR (b) (6)

USN

2 Maint. Officer

Enclosure (12)

22 14 13-4

1. THE FOLLOWING INFORMATION IS FOR YOUR INFORMATION ONLY TWO  
2. ENGINE COMPARTMENT AND TWO THREE  
3. ENGINE COMPARTMENT AND TWO THREE  
4. ENGINE COMPARTMENT AND TWO THREE  
5. ENGINE COMPARTMENT AND TWO THREE  
6. ENGINE COMPARTMENT AND TWO THREE  
7. ENGINE COMPARTMENT AND TWO THREE  
8. ENGINE COMPARTMENT AND TWO THREE  
9. ENGINE COMPARTMENT AND TWO THREE  
10. ENGINE COMPARTMENT AND TWO THREE

11. ENGINE COMPARTMENT AND TWO THREE  
12. ENGINE COMPARTMENT AND TWO THREE  
13. ENGINE COMPARTMENT AND TWO THREE  
14. ENGINE COMPARTMENT AND TWO THREE  
15. ENGINE COMPARTMENT AND TWO THREE  
16. ENGINE COMPARTMENT AND TWO THREE  
17. ENGINE COMPARTMENT AND TWO THREE  
18. ENGINE COMPARTMENT AND TWO THREE  
19. ENGINE COMPARTMENT AND TWO THREE  
20. ENGINE COMPARTMENT AND TWO THREE

21. ENGINE COMPARTMENT AND TWO THREE  
22. ENGINE COMPARTMENT AND TWO THREE  
23. ENGINE COMPARTMENT AND TWO THREE  
24. ENGINE COMPARTMENT AND TWO THREE  
25. ENGINE COMPARTMENT AND TWO THREE  
26. ENGINE COMPARTMENT AND TWO THREE  
27. ENGINE COMPARTMENT AND TWO THREE  
28. ENGINE COMPARTMENT AND TWO THREE  
29. ENGINE COMPARTMENT AND TWO THREE  
30. ENGINE COMPARTMENT AND TWO THREE

31. ENGINE COMPARTMENT AND TWO THREE  
32. ENGINE COMPARTMENT AND TWO THREE  
33. ENGINE COMPARTMENT AND TWO THREE  
34. ENGINE COMPARTMENT AND TWO THREE  
35. ENGINE COMPARTMENT AND TWO THREE  
36. ENGINE COMPARTMENT AND TWO THREE  
37. ENGINE COMPARTMENT AND TWO THREE  
38. ENGINE COMPARTMENT AND TWO THREE  
39. ENGINE COMPARTMENT AND TWO THREE  
40. ENGINE COMPARTMENT AND TWO THREE

Certified to be true

(b) (6)

Enclosure (13)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

(b) (6)

USN

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

THE FOLLOWING INFORMATION IS AVAILABLE TO THE PUBLIC:

THE FACTS AT STONE ISLAND, TEXAS, HAD BEEN DISTORTED SUCH THAT  
REVEALED THAT THE PRESENT ATTITUDE OF AIRCRAFT WAS VERTICAL AND TAIL  
DOWN, WHILE NO DECISION IS SUBMITTED, IT SHOULD BE NOTED THAT A  
LOCAL MAN WITH NO KNOWLEDGE WOULD ASSUME THE ORIENTATION CHANGED  
IN THE STONE ISLAND.

THE INVESTIGATION SHOWED AN INDICATION OF ONE FIVE  
IN THE AREA OF THE INVESTIGATION. THE INDICATION  
OF THE INVESTIGATION WAS NOT POSSIBLE  
TO BE DETERMINED. IT IS REASONABLE TO ASSUME  
THAT THE INVESTIGATION IS CORRECT, HOWEVER, THE  
INVESTIGATION IS NOT YET COMPLETED.

1. ADD RF POWERING POINT FAILURE BETWEEN TWO ROTOR POSITS OF ONE  
2. INSTEAD OF, IMMEDIATELY AFTER ROTATING AT POSITION OF 180 DEGREES.

ON 11/11/68, NO OIL LEAKAGE OF OIL GENERATOR BEARING WAS CONCENTRATED  
A LEAK AREA INDICATING STATIONARY AXIAL IMPACT, WITH GENERATION  
OF HOT OIL WAS IN THE AREA OF BEARING ON JOURNAL INDICATING ROTATION  
ON 12/26/68

\* THE AIRCRAFT ENGINE AND BLAST AIR DUCT SYSTEM WITH COUPLING RECEIVED

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED  
DATE 08-19-2007 BY 60322 UCBAW

10. IF ANY CRACKS WHICH INDICATED ONLY IMPACT DAMAGE, CYLINDER

113

## Molecules (20)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH COUNTRY OF ORIGIN



WAS OBSERVED. DURING CONTROL HYDRAULIC PUMP FAN HANDLES  
WAS TURNED OFF. DURING GROUP DISASSEMBLY PARTS SHOWED NO  
EVIDENCE OF DAMAGE OR WEAR.

2. DURING CONTROL DISASSEMBLY DAMAGE BUNGE ASSEMBLY P/R ATTACHED WAS  
OBSERVED. BUNGE WAS ON CASE SO THAT COMPRESSION LOAD TEST WAS  
PERFORMED. BUNGE WAS ON CASE MISSING. NO DISCREPANCIES FOUND ON  
INTERNAL TESTS.

3. THE PORT OIL TEMPERATURE GAGE HAD DUAL INDICATORS. THE LEFT-HAND  
LINE WAS CRUMPLED BEHIND SHIELD AND REMOVAL OF SHIELD REVEALED  
THAT RIGHT-POINTING POSITION HAD BEEN DISENGAGED SO THAT NOTHING  
COULD BE DETERMINED ABOUT POINTER IMPACT POSITION. RIGHT-HAND  
POINTER WAS INTACT AND ITS POSITION INDICATED READING OF 150 DEGREES.  
HOWEVER, NOTE THAT THIS POSITION IS AGAINST UPPER LIMIT STOP AND  
POSITION OF HEADLINE NOT CERTAIN. NO SIGNIFICANT MARKS OBSERVED UNDER  
MAGNIFYING GLASS.

4. ONLY THE DIAL FACE WAS RECOVERED FROM THE ANGLE-OF-ATTACK INDICATOR.  
ELECTRICAL POWER WAS INDICATED OFF. ANGLE-OF-ATTACK SETTING WAS 23.5  
DEGREES. POINTER WAS MISSING SO NO DETERMINATION OF ANGLE-OF-ATTACK  
INDICATION COULD BE MADE.

5. ONLY THE DIAL FACE OF FUEL FLOW INDICATOR AVAILABLE. THE POINTER

PAGE THREE BURNING OF ENGINE

WAS MISSING SO THAT NO DETERMINATION OF IMPACT INDICATION POSSIBLE.  
AFTER LIGHT EXAMINATION REVEALED NOTHING.

6. THE RANGE ATTITUDE INDICATOR (VAC) HAD SPHERE DISTORTED SUCH THAT  
IT APPEARED THAT THE IMPACT ATTITUDE OF AIRCRAFT WAS VERTICAL AND TAIL  
DOWN. NO CORRELATION IS SUGGESTED. IT SHOULD BE NOTED THAT A  
TYPICAL UNIT WITH SPHERE REMOVED WOULD ASSUME THE ORIENTATION OBSERVED  
BY THE DAMAGED UNIT.

7. THE SPEED AND ALTITUDE INDICATOR SHOWED AN INDICATION OF 076 MILES  
WHEN RECEIVED. NO ATTEMPTS TO VERIFY THIS INDICATION BY MEASURING  
THE RESISTANCE SETTING OF THE RESOLVER. POTENTIOMETERS WAS NOT POSSIBLE  
BECAUSE POTENTIOMETER WAS BROKEN INSIDE. IT IS REASONABLE TO ASSUME  
THAT THE FIRST TWO DIGITS OF THE INDICATION ARE CORRECT. HOWEVER, THE  
UNIT'S DIGIT MAY BE IN ERROR BY PLUS THREE, MINUS FOUR.

8. NOISE OF FASTERING SCREW FAILURE BETWEEN TWO ROTOR PARTS OF ONE  
GENERATOR, INDICATOR UNIT ROTATING AT MOMENT OF IMPACT.

9. BRUSHING OF BRUSH WAYS OF DC GENERATOR BEARINGS WAS CONCENTRATED  
ON A SMALL AREA INDICATING STATIONARY AXIAL IMPACT, WITH GENERATOR  
ROTATING. THERE WERE NO MARKS ON ARMATURE INDICATING ROTATION  
AT IMPACT.

10. THE SHORT-TURN LONG BLEED AIR DUCT SEGMENT WITH COUPLING RECEIVED

PAGE FOUR BURNING OF ENGINE  
INDICATED ONLY 1 PART DAMAGE.

11. DURING FUEL GAGE TEST PUMP WAS RUNNING AT IMPACT.

12. SACRIFICIAL CYLINDER INDICATED ONLY IMPACT DAMAGE. CYLINDER  
WAS NOT EVEN FIRED.

B035/27  
ZCTFA701  
RTTU JAW RUWMMHVS132 1170103-UUUU--RUWMM  
ZNR UUUUU  
R 270102Z APR 67  
FM NAVAIREWORKFAC ALAMEDA  
TO RUWJMUA/NAVAIRSYSCOMREPAC  
INFO RUWMMFTA/NATRON ONE TWO THREE  
RUWJMUA/NAVAIREWORKFAC NDRIS  
RUEDBBB/NAVAIRSYSCOM  
RUWJMUA/COMNAVAIRFAC  
RUCILSA/NAVAUNSAFEEN NORVA  
RUEORRA/NATSE PHILA  
RUWMMFTA/COMFAIRWHIDBEY  
ZEN/COMFAIRALAMEDA  
RUWJAPA/CONREADATKCARAIRWING TWELVE  
RUWJNDA/NPRO LBEACH  
RUEDDPA/NPRO EAST HARTFORD

Apr 27 05 03.67

"INTERNAL ROUTING CORRECT  
AND TAKE FOR C VICE SUP.

BT

UNCLAS

A-3B BUNO 138917 FAILURE ANALYSIS

A. YOUR 131842Z APR 67 (NOTAL)

B. MY 191918Z APR 67

C. FONECON LCDR (b) (6) VAH-123 AND MR. BRIGHT THIS FACILITY

1. REF A REQUESTED FAILURE ANALYSIS CONTROL NUMBER 3282-67 OF  
SELECTED AIRCRAFT PARTS. REF B WAS A PARTIAL REPORT. THIS REPORT  
COVERS REMAINING ITEMS.

2. SECOND DC GENERATOR RECEIVED WITH ROTOR MISSING. UNABLE DETERMINE  
IF ROTOR TURNING AT IMPACT.

PAGE 2 RUWMMHVS132 UNCLAS

3. EMERGENCY ESCAPE CHUTE IMPULSE CARTRIDGE EX-82-2 WITH INKED DATE  
10-28-67 WAS TESTED AND FIRED WITHIN VOLTAGE AND CURRENT LIMITS.

4. REF C REQUESTED THAT FOLLOWING THREE ADDITIONAL ITEMS BE INCLUDED  
IN REPORT:

- ATM SHROUD SHOWED DEFINITE INDICATIONS THAT AIR TURBINE MOTORS  
WERE TURNING AT IMPACT.
- SUPPORT ASSEMBLY, CONTROL COLUMN AFT 4272754, BEARING  
AN202KPA7B, AND RETAINER HAS669-387 SHOWED ONLY IMPACT DAMAGE.
- PIECE OF BURNT WOVEN MATERIAL WAS IDENTIFIED AS FIBERGLAS CLOTH  
IMPREGNATED WITH POLYESTER RESIN BINDER AND NYLON WOVEN FABRIC.  
THIS WAS DETERMINED TO BE PART OF A FUEL CELL TANK LINER.  
TEMPERATURE OF BURNING ESTIMATED BETWEEN 500 AND 600 DEGREES  
FAHRENHEIT AS EVIDENCED BY CHARRED REMAINS OF NYLON AND  
TOTALLY BURNT POLYESTER RESIN BINDER.

5. THIS COMPLETES NAVAIREWORKFAC ALAMEDA ACTION ON CONTROL 3282-67.

BT

Certified to be true

CFW C/S ADMIN OPS OPCON AMO SUP COM SDD

(b) (6)

LCDR

USN

WU/DL

VAH-123

AT

Enclosure (13)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

## RESUME OF PILOT EXPERIENCE PAST FIVE YEARS

LCDR R. E. PARKS (b) (6)

<u>COMMAND ATTACHED</u>	<u>PERIOD ASSIGNED</u>	<u>MODEL AIRCRAFT</u>	<u>FLIGHT HOURS</u>	<u>CV INDGS DAY/NIGHT</u>	<u>TYPE</u>
US NAVAL POST GRAD SCHOOL	APR 1962 MAY 1963	TC-45J T-28	113	NONE	PROFICIENCY
VA-42	JULY 1963 DEC 1963	A-1H	144	16/8	OPERATIONAL
VA-176	DEC 1963 JAN 1966	A-1H	848	177/79	OPERATIONAL
USS LEXINGTON	JAN 1966 OCT 1966	C-1A	104	NONE	PROFICIENCY
VF-126	NOV 1966 DEC 1966	TF-9J	46	NONE	OPERATIONAL
VAH-123	DEC 1966 APR 1967	A3B	25	NONE	OPERATIONAL

Certified to be true

(b) (6)

LCDR

USN

Enclosure (14)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

## RESUME OF PILOT EXPERIENCE PAST FIVE YEARS

LCDR D. E. KING (b) (6)

<u>COMMAND ATTACHED</u>	<u>PERIOD ASSIGNED</u>	<u>MODEL AIRCRAFT</u>	<u>FLIGHT HOURS</u>	<u>CV LNDS DAY/NIGHT</u>	<u>TYPE</u>
VAH-10	APRIL 1962 JUNE 1963	A3B	261	160*	OPERATIONAL
US NAVAL POST GRAD SCHOOL	JULY 1963 DEC 1964	T2A	150	NONE	PROFICIENCY
BUPERS	JAN 1965 OCT 1965	T1A	61	NONE	PROFICIENCY
VAH-123	NOV 1965 APR 1967	A3B/A6A	530	14/6	OPERATIONAL

\*ONLY ONE LOG BOOK AVAILABLE

Certified to be true

(b) (6)

LCDR USN



From: Officer in Charge, Naval Weather Service Environmental Detachment,  
Whidbey Island, Oak Harbor, Washington  
To: Aviation Safety Officer, Heavy Attack Squadron ONE TWO THREE  
Subj: Summary of weather at and near site of A3B aircraft crash in  
Northern California mountains on 5 April 1967

1. The following is a summary of available weather observations as well as estimates and opinions of the weather that most likely occurred at points where no observations were available:

GENERAL SYNOPTIC SITUATION: During the afternoon of 5 April 1967 an upper-air closed low pressure cell was centered just off the Northern Oregon coast. This low was nearly stationary. The circulation around this upper-level low extended far enough to the South and East so as to overlie all of Oregon, Nevada, and California. Although no definite fronts appeared on the surface chart at this time at or near the area of interest, rather widespread unsettled, unstable surface and low level weather conditions did prevail over most of Western Nevada, Northern California, and Southern Oregon.

SPECIFIC OBSERVATIONS AND INTERPRETATIONS: Interpolation based on actual upper wind observations taken at 051800Z and 060000Z indicate that the 18,000-foot wind between Reno and Lakeview should have been from 240 degrees true at 35 to 40 knots. Reno, at 2200Z and 2300Z, reported only one layer of clouds. These clouds, based at 3400 feet above the ground, probably had tops no higher than 7000 or 8000 feet. However, on both of these observations Reno carried the remark, "ROTOR CLOUDS OVER VALLEY". Rotor clouds are normally associated with mountain wave conditions or other extremely turbulent conditions. Mountain waves and rotor clouds are usually observed over or on the lee side of mountainous terrain. Although Reno did not estimate a height of these rotor clouds, they might well have been between 14,000 and 24,000 feet. It is probable that considerable turbulence existed in and near these clouds.

Continuing Northward from Reno toward Lakeview an increase in low and middle clouds should have been encountered. This is an opinion based on rather sparse data since there aren't many weather observation stations on or near the route from Reno to Lakeview. A review of the weather reported by the stations in Northern California and Southern Oregon during the time in question reveals that most of the peaks and ridges higher than 5000 feet above sea level were probably obscured by low clouds and snow showers. Tops of all low and middle clouds were most likely 13,000 to 14,000 feet. A higher broken to overcast relatively dense cirrus cloud layer with bases about 26,000 feet and tops about 32,000 feet was observed over most of Northern California and Southern Oregon.

Enclosure (15)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

REPORTED OBSERVATIONS:

LKV 2043Z EST 1500 OVC, 15 MI, LIGHT SNOW, TEMP 35, DP 28,  
WIND 200/7  
LKV 2345Z 3000 SCTD EST 5000 BKN HI OVC CIRUS, 30 MI, TEMP 48,  
DP 19, WIND 180/10  
LMT 2200Z 3000 SCTD EST 5000 BKN 12,000 BKN HI OVC CIRUS, 10 MI,  
LIGHT SNOW SHOWERS, TEMP 40, DP 25, WIND 190/6, VISIBILITY  
LOWER SW-NW AND N, SNOW SHOWERS OCCASIONALLY VERY LIGHT  
LMT 2300Z 2800 SCTD EST 5000 BKN 12,000 BKN HI OVC CIRUS, 10 MI,  
TEMP 38, DP 26, WIND 280/13, CEILING RAGGED, SNOW SHOWERS  
OF UNKNOWN INTENSITY N AND E-SE  
SIY 2116Z 1500 SCTD MEASURED 2500 BKN 4500 OVC, 15 MI, LIGHT RAIN  
SHOWERS, WIND 260/15G20  
SIY 2200Z 2000 SCTD EST 3500 BKN 5000 OVC, 15 MI, LIGHT RAIN  
SHOWERS, TEMP 42, DP 32, WIND 200/15G20, CEILING RAGGED,  
LIGHT RAIN SHOWERS OCCASIONALLY VERY LIGHT  
SIY 2300Z 3000 SCTD EST 4500 BKN 8000 OVC, 20 MI, TEMP 40, DP 33,  
WIND 190/10G17, SNOW SHOWERS OF UNKNOWN INTENSITY NE  
MHS 2200Z 1500 SCTD EST 3000 OVC, 4 MI, LIGHT RAIN AND SNOW SHOWERS,  
TEMP 36, DP 34, WIND 130/13, RAIN BEGAN 2110Z  
MHS 2300Z INDEFINITE 1000 OBSCURED, 1/2 MI, MODERATE SNOW SHOWERS,  
TEMP 35, DP 34, WIND 140/8, RAIN ENDED 2245Z, MODERATE  
SNOW SHOWERS OCCASIONALLY LIGHT  
BNY 2020Z 500 SCTD EST 1500 BKN 10,000 OVC, 15 MI, LIGHT RAIN,  
WIND 250/10, LOWER CLOUDS W-SW, PASS OBSCURED  
RNO 2200Z EST 3400 BKN, 25 MI, TEMP 47, DP 22, WIND 190/18, ROTOR  
CLOUDS OVER VALLEY, SNOW SHOWERS OF UNKNOWN INTENSITY NE-  
SE, CLOUDS TOPPING SIERRA NEVADAS  
RNO 2300Z EST 3400 BKN, 25 MI, TEMP 47, DP 22, WIND 200/13, ROTOR  
CLOUDS OVER VALLEY, CLOUDS TOPPING SIERRA NEVADAS

LKV - LAKEVIEW, ELEVATION 4764 FT ABOVE SEA LEVEL  
LMT - KLAMATH FALLS, ELEVATION 4084 FT ABOVE SEA LEVEL  
SIY - MONTAGUE, CALIF, ELEVATION 2651 FT ABOVE SEA LEVEL  
MHS - MOUNT SHASTA, ELEVATION 3587 FEET ABOVE SEA LEVEL  
BNY - BURNEY, CALIF, ELEVATION 3100 FEET ABOVE SEA LEVEL  
RNO - RENO, ELEVATION 4400 FEET ABOVE SEA LEVEL

(b) (6)

Lieutenant Commander, USN

Statement of Capt. (b) (6), (b) (6) USAF, 322ND FIGHTER  
SQUADRON, Kingsley AFB, Oregon.

On 5 April 1967 I departed the base at around 1430 on a practice scramble in a F-101. Following handoff from departure control, Seattle Center requested I climb to FL 200 and vector 100° to effect a communications search with NJ309. I steered 100° for approximately 100NM with no communications results. Weather at FL 200 was IFR with only occasional light turbulence. At infrequent intervals I could momentarily see cloud layers below. I would estimate the weather at FL 180 to be similar with a little more intermittent VFR/IFR conditions.

I am currently flying F-101's and have a total of 3700 flight hours.

(b) (6)

Certified to be true

(b) (6)

LCDR USN

Enclosure (16)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6E

NNNNNZCNASC489CZCSLB983  
PTIUZYUW RUWMFTA0042 2982314-UUUU--RUCILSA.

ZNR UUUUU

P 252314Z OCT 67

FM HATRON ONE TWO THREE

TO RUEDBRB/NAVAIRSYSCOMHQ

RUWJMUA/NAVAIRSYSCOMREPAC

INFO RUWJMUA/COMNAVAIRPAC

ZEN/COMFAIRWHIDBEY

RUWMHVA/COMFAIRALAMEDA

RUWMHVA/NAVAIREWORKFAC ALAMEDA

RUWMHVA/CARAEWON THIRTEEN

RUCILSA/NAVAVNSAFECEN

RAEOHRA/NAVAIRTECHSERVFAC

RUWJNDA/NAVPLANTREPO LBEACH

RUWJAPA/COMREADATKCARAIRWING TWELVE

BT

UNCLAS

PRIORITY INVESTIGATION

A. BWFRPACINST 4730.84

B. NAVAIRSYSCOMREPAC 280121Z JUN 67 (NOTAL)

C. NAVAIREWORKFAC ALAMEDA (300) DIR REPORT 854 (NOTAL)

1. A3B 138917

PAGE TWO RUWMFTA0042 UNCLAS

2. NA

3. HORIZONTAL STABILIZER ACTUATOR S/R UNKNOWN

4. S/N RQ1680-739-5067-ADGA P/N 5380-824-549

5. DOUGLAS AIRCRAFT CO.

6. UNKNOWN

7. THIS IS A CONTINUATION OF REF B. FURTHER SEARCH RECOVERED  
REMAINING PART OF TRIM ACTUATOR. OTHER PART OF TRIM ACTUATOR  
REPORTED ON IN REF C.

8. REQUEST DIR IAV REF A.

BT

# 989.67  
C O G M M

OCT  
252314Z



VAH-123

4-5-67  
Purles

NNNNZCZCNASC729CSLA038  
RTTU JAW RUWJMUA5959 2002204-UUUU--RUCILSA.  
ZNR UUUUU

R 192204Z JUL 67  
FM NAVACREWORKFAC NORIS  
TO ZENI/NAVAIRSYSCOMREPAC  
INFO RUEDBHB/NAVAIRSYSCOMHQ  
ZENI/COMNAVAIRPAC  
RUWMFTA/COMFAIRWHIDBEY  
RUWJAPA/COMREDATKCRARIWING ONE TWO  
RUWMFTA/HATRON ONE TWO THREE  
RUCILSA/NAVAVNSAFCE  
RUEOHRA/NAVAIRTECHSERVFAC  
RUWMHVA/NAVAIREWORKFAC ALAMEDA  
RUWJNDA/NAVPLANTREPO L BEACH  
RUEDDPA/NAVPLANTREPO E HARTFORD

729/67

Cog, mmm  
Records

BT  
UNCLAS  
NAVAIRSYSCOMHQ PASS TO AIR-4113/504/53613  
A3B BUNO 138917 A/C ACCIDENT INVESTIGATION  
A. YOUR 280121Z JUN 67  
1. REF A CONTROL NO. 3282-67 REQ AN ENGINEERING ANALYSIS ON MAIN FUEL  
CONTROL, P/N 507650-L16, S/N 28112, REMOVED FROM ONE ENGINE OF SUBJ

PAGE TWO RUWJMUA5959 UNCLAS  
A/C.

2. INVESTIGATION REVEALED:
- A. FUEL CONTROL SUFFERED MAJOR IMPACT DAMAGE.
  - B. CONTROL MECHANISMS (CONTROL SHAFT, LINKAGE, BRACKET, AND LEVER ASSY, ETC.) WERE MISSING.
  - C. FUEL STRAINERS WERE CLEAN.
  - D. PRESSURE REGULATING VALVE - CLOSED POSITION (NORMAL). NO DISCREPANCIES.
  - E. FLYWEIGHT GOVERNOR ASSY - NO DISCREPANCIES.
  - F. CYLINDER CAM SPEED SENSOR - NO DISCREPANCIES.
3. CONCLUDE: DETERMINATION OF FUEL CONTROL OPERABILITY OR MALFUNCTION PRIOR TO IMPACT NOT FEASIBLE DUE TO MUTILATED CONIDON OF PARTS.
4. THIS IS A SUPPLEMENTAL REPORT TO NAVAIREWORKFAC NORIS PRIORITY DIR NO. 31 OF 12 MAY 1967.

BT

JUL  
192204Z

VAH-123  
4-5-67  
Clark  
NNNNZCZCNASC233LB858  
RTTE JAW RUWJMUAB621 1798121-EEEE--RUCILSA.

ZNY EEEEE

R 280121Z JUN 67

FM NAVAIRSYSCOMREPAC

TO RUWMFTA/HATRON ONE TWO THREE

ZENI/NAVAIREWORKFAC NORIS

RUWMHVA/NAVAIREWORKFAC ALAMEDA

INFO RUEDBHB/NAVAIRSYSCOMHQ

ZENI/COMNAVAIRPAC

RUCILSA/NAVAVNSAFECEN

RUEOHRA/NAVAIRTECHSERVFAC

RUWMFTA/COMFAIRWIDBET

RUWJAPA/COMREDATKCARATWING ONE TWO

RUWJNDA/NAVPLANTREPO L BEACH (DOUGLAS ACFT CO, INC)

RUEDDPA/NAVPLANTREPO E HARTFORD (PRATT AND WHITNEY ACFT DIV, UNITED ACFT CORP CONN)

BT

UNCLAS E F T O

A38 BUND 138917 ACFT ACCIDENT INVESTIGATION

A. HATRON-123 240233Z JUN 67

B. HATRON-123 110345Z APR 67

1. HATRON-123: REQ FWD REF A FUEL CONTROL, S/N 28112, TO NAVAIREWORKFAC NORIS CUSTOMER SERVICE CODE 525.2, AND HORIZONTAL TRIM ACTUATOR,

PAGE TWO RUWJMUAB621 UNCLAS E F T O

P/N DG5388824-549, TO NAVAIREWORKFAC ALAMEDA CUSTOMER SERVICE CODE 524.1. REF B REFERS. MARK CONTAINERS AND DOCUMENTS FOR PRIORITY DIR IAW REF C. ADCON SHIPPING MODE AND TCH OR B/L MRS. REFER NAVAIRSYSCOMREPAC CONTROL NR 3282-67.

2. NAVAIREWORKFAC NORIS: REQ CONDUCT ENGRG ANAL SUBJ FUEL CONTROL, S/N 28112, P/N 587658L-16, IAW REF C. ADCON RESULTS. REFER ABOVE CONTROL NR ALL FUTURE RELATED CORRES.

3. NAVAIREWORKFAC ALAMEDA: REQ CONDUCT ENGRG ANAL SUBJ HORIZONTAL TRIM ACTUATOR, P/N DG5388824-549, IAW REF C. ADCON RESULTS. REFER ABOVE CONTROL NR ALL FUTURE RELATED CORRES.

BT

233/07  
APR  
Cody RECORDS  
CWR2  
280121Z

NNNN, 11:164CZCSLA450  
RITU JAW RUWJMUA1396 1182356-UUUU--RUCILSA  
ZNR UUUUU

R 282356Z APR 67  
FM NAVAIREWORKFAC NORIS  
TO RUWMFTA/HATRON ONE TWO THREE  
INFO RUEDBHB/NAVAIRSYSCOMHQ  
ZENI/NAVAIRSYSCOMREPAC  
ZENI/COMNAVAIRPAC  
RUWMHVA/NAVAIREWORKFAC ALAMEDA  
RUEOHRA/NAVAIRTECHSERVFAC PHILA  
RUCILSA/NAVAVNSAFECEN  
RUWMFTA/COMFAIRWHIDBEY  
RUWJAPA/COMREADATKCARAIRWING TWELVE  
RUWJNDA/NAVPLANTREPO LBEACH  
RUEDDPA/NAVPLANTREPO E HARTFORD  
RUCILSA/NAVAIREWORKFAC NORVA  
RUCILVA/NAVAIRSYSCOMREPLANT  
BT

UNCLAS  
NAVAIRSYSCOMHQ PASS TO AIR-4113/53613  
A3B BUHO 138917 A/C ACCIDENT INVESTIGATION  
A. TELCON LT. (b) (6) VAW-123/S. BROWN NAVAIREWORKFAC NORIS ON

PAGE TWO RUWJMUA1396 UNCLAS  
27 APR 67

B. MY 220118Z APR 67 NOTAL

1. REF A REQ CONFIRM INCORP OF J57 ENG BULL NO. 535 AMEND - 1 IN  
J57-P10 EMGS S/N'S P607625 AND P632289 INSTALLED IN SUBJ A/C  
AT TIME OF ACCIDENT. REF B IS PRELIMINARY PRI DIR ON NAVAIRSYSCOMREPAC  
CONTROL NO. 3282-67.

2. HISTORY:

A. ENG. S/N P607625; NORIS SHOPS ENG. ASSY RECORD  
INDICATES J57 E.B. 535-A1 INCORP. CERTIFIED 7-9-66; NEW FORM 13090/40  
INDICATES INCORP E.B. 535-A1 2-3-64 AND CERTIFIED 7-9-66.

B. S/N P632289; NORIS SHOPS ENG. ASSY RECORD INDICATES  
J57 E.B. 535-A1 INCORP. CERTIFIED 7-11-66; NW FORM 13090/40  
INDICATES INCORP E.B. 535-A1 9-25-65 AND CERTIFIED 7-11-66.

3. PORTIONS OF THE ENGINES AFFECTED BY E.B. 535-A1 WERE NOT RECEIVED;  
THEREFORE INSPECTION COULD NOT VERIFY PHYSICAL INCORP. OF BULLETIN.

BT A3B 138917

APR 28 2356Z

NNNNZCZCNASC225CZCSLB099

RTTU JAW RUWMHVA3132 1170105-0000--RUCILSA. 225/67

ZNR 00000

R 270102Z APR 67

FM NAVAIREWORKFAC ALAMEDA

TO RUWJMUA/NAVAIRSYSCOMREPAC

INFO RUWJMTA/HATRON ONE TWO THREE

RUWJMUA/NAVAIREWORKFAC NORIS

RUEDBHB/NAVAIRSYSCOM

RUWJMUA/COMNAVAIRPAC

RUCILSA/NAVAVNSAFECEN NORVA

RUEOHRA/NAISF PHILA

RUWJMTA/COMFAIRWHIDBEY

ZEN/COMFAIRALAMEDA

RUWJAPA/COMREADATKCAIRWING TWELVE

RUWJNDA/NPRO LBFACH

RUEDDPA/NPRO EAST HARTFORD

BT

UNCLAS

A-3B BUNO 138917 FAILURE ANALYSIS

A. YOUR 131804Z APR 67 (NOTAL)

B. MY 191918Z APR 67

C. FONECON LCDR (b) (6) VAW-123 AND MR. BRIGHT THIS FACILITY

1. REF A REQUESTED FAILURE ANALYSIS CONTROL NUMBER 3282-67 OF  
SELECTED AIRCRAFT PARTS. REF B WAS A PARTIAL REPORT. THIS REPORT  
COVERS REMAINING ITEMS.

2. SECOND DC GENERATOR RECEIVED WITH ROTOR MISSING. UNABLE DETERMINE  
IF ROTOR TURNING AT IMPACT.

PAGE 2 RUWMHVA3132 UNCLAS

3. EMERGENCY ESCAPE CHUTE IMPULSE CARTRIDGE EX-82-0 WITH INKED DATE  
10-28-67 WAS TESTED AND FIRED WITHIN VOLTAGE AND CURRENT LIMITS.

4. REF C REQUESTED THAT FOLLOWING THREE ADDITIONAL ITEMS BE INCLUDED  
IN REPORT:

A. ATM SHROUD SHOWED DEFINITE INDICATIONS THAT AIR TURBINE MOTORS  
WERE TURNING AT IMPACT.

B. SUPPORT ASSEMBLY, CONTROL COLUMN AFT 4272754, BEARING  
AN202KP478, AND RETAINER NS669-387 SHOWED ONLY IMPACT DAMAGE.

C. PIECE OF BURNT WOVEN MATERIAL WAS IDENTIFIED AS FIBERGLAS CLOTH  
IMPREGNATED WITH POLYESTER RESIN BINDER AND NYLON WOVEN FABRIC.  
THIS WAS DETERMINED TO BE PART OF A FUEL CELL TANK LINER.  
TEMPERATURE OF BURNING ESTIMATED BETWEEN 500 AND 600 DEGREES  
FAHRENHEIT AS EVIDENCED BY CHARRED REMAINS OF NYLON AND  
TOTALLY BURNT POLYESTER RESIN BINDER.

5. THIS COMPLETES NAVAIREWORKFAC ALAMEDA ACTION ON CONTROL 3282-67.

BT

Copy M8M

VAH-123

APR 13 89 17

4-5-67

1677

APR 67  
274192Z



NNNMZCNASC 337CZCSLA 425  
RTTU JAW RUWJMUA6188 1120118-UUUU--RUCILSA.  
ZNR UUUUU  
R 220118Z APR 67  
FM NAVAIRESO/KFAC NORIS  
TO ZENI/NAVAIRSXSOMREPAC  
INFO RUEDBHB/NAVAIRSYSOMHQ  
RUWMHVA/NAVAIREWORKFAC ALAMEDA  
ZENI/COMNAVAINPAC  
RUEOHRA/NAVAITECHSERVAFAC  
RUCILSA/NAVAVISFAFECEN NORVA  
RUWMFTA/COMFAIRWHIDBEY  
RUWJAPA/COMREDAITKCAIRWING ONE TWO  
RUWMFTA/HATRON ONE TWO THREE  
RUWJNDA/NAVPLANTREPO LBEACH  
RUEDDPA/NAVPLANTREPO E HARTFORD  
BT

UNCLAS  
NAVAIRSYSOMHQ PASS TO AIR-4113/53613  
A3B BUNO 133917 A/C ACCIDENT INVESTIGATION

- A. YOUR 131804Z APR 67  
1. REF A CONTROL NO 3282-67 REQ FAILURE ANALYSIS ON J57-P10  
ENGINES S/N'S P627625 AND P632289 REMOVED FROM SUBJ A/C.  
2. AS RECEIVED BOTH ENGINES REVEALED MAJOR IMPACT DAMAGE.

PAGE TWO RUWJMUA6188 UNCLAS

- A. INVESTIGATION INDICATED ENG S/N P627625 WAS STOPPED OR  
LOW RPM AT IMPACT. ENG S/N P632289 WAS ROTATING AT IMPACT.  
B. NO. 1 MAIN BEARING BOTH ENGINES NOT RECEIVED. ALL OTHER  
MAIN BEARINGS BOTH ENGINES FOUND IN SATISFACTORY CONDITION EXCEPT  
FOR IMPACT DAMAGE.  
3. CONCLUDE INVESTIGATION OF ENGINE COMPONENTS AS RECEIVED REVEALED  
NO INDICATIONS OF MALFUNCTION.  
4. INVESTIGATION CONTINUING.  
5. FORMAL PRI DIR TO BE SUBMITTED APPROX 5 MAY 1967.  
BT

837167

COB: MEM

APR  
220118

NNNNZCZCNASC669973  
RTTU JAW RUWJMUA5708 1102226-UUUU--RUCILSA.  
ZNR UUUUU

R 202226Z APR 67

FM COMNAVAIRPAC

TO RUWMFTA/HATRON ONE TWO THREE

INFO RUCILSA/NAVAVNSAFECEN

RUWJAPA/COMREADATKCARAIRWING TWELVE

RUWMFTA/COMFAIRWHIDBEY

BT

UNCLAS

AJB BUNO 138917 AAR

A. YOUR 200318Z APR 67

1. EXTENSION GRANTED AS REQ REF A.

BT

669  
67

Coy. Records

202226Z

NNNNMZCN/SC581  
RTTU JAW RUWMFTA0043 1100318-UUUU--RUCILSA.  
ZNR UUUUU  
R 200318Z APR 67  
FM MATRON ONE TWO THREE  
TO RUWJMU4/COMNAVAIRPAC  
INFO RUCILSA/NAVAVNSAFECEN  
RUWJAPA/COMREADATXCARAIRWING TWELVE  
ZEN/COMFAIRWHIDBEY  
BT  
UNCLAS  
ASS BUNO 138917 AAR  
A. OPNAVINST 3750.6E  
1. REQ 10 WORKING DAY EXTENSION SUBJ RPT.  
BT

#521/67

004 RECORDS

APR

200318Z

ZNR UUUUU  
R 191918Z APR 67  
FM NAVAIREWORKFAC ALAMEDA  
TO RUWJMUA/NAVAIRSYSCONREPAC  
INFO RUWJMFTA/HATRON ONE TWO THREE  
RUWJMUA/NAVAIREWORKFAC NORIS  
RUEDEHB/NAVAIRSYSCOM  
RUWJMUA/COMNAVAIRPAC  
RUEOHRA/NAVAIRTECHSERVAFAC PHILA  
RUCILSA/NAVAVNSAFECEN NORVA  
RUWJMFTA/COMFAIRWHIDBEY  
RUWJAPA/COMREADATKCARAIRWING TWELVE  
RUWJNDA/NAVPLANTREPO LBEACH  
RUEDDPA/NAVPLANTREPO EAST HARTFORD  
ZEN/COMFAIRALAMEDA  
BT  
UNCLAS

#546/67

EOG! M4 M

- A-38 BUNO 138917 FAILURE ANALYSIS  
A. YOUR 131804Z APR 67 (NOTAL)  
B. HATRON ONE TWO THREE 118345Z APR 67 (NOTAL)  
1. NAVAIREWORKFAC ALAMEDA TAKES REF A FOR ACTION.  
2. REF A REQUESTED FAILURE ANALYSIS CONTROL NO. 3282-67 OF SELECTED AIRCRAFT PARTS FROM ACCIDENT REPORTED REF B. THIS IS A PARTIAL REPORT. REMAINING ITEMS WILL BE REPORTED WHEN ANALYSIS COMPLETED.  
3. BOTH AIR TURBINE MOTORS WERE TURNING AT IMPACT. PRESSURIZATION TURBINE WAS TURNING AT IMPACT.

PAGE TWO RUWJMVA2572 UNCLAS

4. AILERON BOOST AND SURFACE CONTROL HYDRAULIC PUMP P/N A265319R6 BROKEN FROM IMPACT. ROTATING GROUP SUBASSEMBLY PARTS SHOWED NO HEAT DISCOLORATION OR EVIDENCE OF SEIZURE.  
5. COCKPIT CONTROL BOBWEIGHT BALANCE BUNGEE ASSEMBLY P/N A5544G3 HAD ONE-EIGHTH INCH DEEP DENT ON CASE SO THAT COMPRESSION LOAD TEST NOT POSSIBLE. SAFETY WIRING ON CAP MISSING. NO DISCREPANCIES FOUND ON INTERNAL PARTS.  
6. THE PORT OIL TEMPERATURE GAGE HAD DUAL INDICATORS. THE LEFT-HAND POINTER WAS CRUMPLED BENEATH SHIELD AND REMOVAL OF SHIELD REVEALED THAT ENTIRE POINTER MOVEMENT HAD BEEN DISENGAGED SO THAT NOTHING POSITIVE COULD BE DETERMINED ABOUT POINTER IMPACT POSITION. RIGHT-HAND POINTER WAS INTACT AND ITS POSITION INDICATED READING OF 150 DEGREES. HOWEVER, NOTE THAT THIS POSITION IS AGAINST UPPER LIMIT STOP AND VALIDITY OF READING NOT CERTAIN. NO SIGNIFICANT MARKS OBSERVED UNDER BLACK LIGHT.  
7. ONLY THE DIAL FACE WAS RECOVERED FROM THE ANGLE-OF-ATTACK INDICATOR. ELECTRICAL POWER FLAG INDICATED OFF. ANGLE-OF-ATTACK SETTING WAS 23.5 UNITS. POINTER WAS MISSING SO NO DETERMINATION OF ANGLE-OF-ATTACK INDICATION COULD BE MADE.  
8. ONLY THE DIAL FACE OF FUEL FLOW INDICATOR AVAILABLE. THE POINTER WAS MISSING SO THAT NO DETERMINATION OF IMPACT INDICATION POSSIBLE. BLACK LIGHT EXAMINATION REVEALED NOTHING.  
9. THE REMOTE ATTITUDE INDICATOR (VGI) HAD SPHERE DISTORTED SUCH THAT IT APPEARED THAT THE IMPACT ATTITUDE OF AIRCRAFT WAS VERTICAL AND TAIL DOWN. WHILE NO CORRELATION IS SUGGESTED, IT SHOULD BE NOTED THAT A TYPICAL UNIT WITH POWER REMOVED WOULD ASSUME THE ORIENTATION OBSERVED IN THE DAMAGED UNIT.  
10. THE ID-310/ARM TACAN INDICATOR SHOWED AN INDICATION OF 876 MILES WHEN RECEIVED HOWEVER ATTEMPTS TO VERIFY THIS INDICATION BY MEASURING THE RESISTANCE SETTING OF THE RESOLVER POTENTIOMETERS WAS NOT POSSIBLE BECAUSE POTENTIOMETERS WERE BROKEN INSIDE. IT IS REASONABLE TO ASSUME THAT THE FIRST TWO DIGITS OF THE INDICATION ARE CORRECT, HOWEVER, THE UNITS DIGIT MAY BE IN ERROR BY PLUS THREE, MINUS FOUR.  
11. MODE OF FASTENING SCREW FAILURE BETWEEN TWO ROTOR PARTS OF ONE AC GENERATOR, INDICATES UNIT ROTATING AT MOMENT OF IMPACT.  
12. BRINELLING ON RACEWAYS OF DC GENERATOR BEARINGS WAS CONCENTRATED ON A SMALL AREA INDICATING STATIONARY AXIAL IMPACT, WITH GENERATOR NOT ROTATING. THERE WERE NO MARKS ON ARMATURE INDICATING ROTATION AT IMPACT.  
13. THE EIGHT-INCH-LONG BLEED AIR DUCT SEGMENT WITH COUPLING RECEIVED INDICATED ONLY IMPACT DAMAGE.  
14. WING FUEL BOOST PUMP WAS RUNNING AT IMPACT.  
15. ESCAPE CHUTE CYLINDER INDICATED ONLY IMPACT DAMAGE. CYLINDER HAD NOT BEEN FIRED.

APR 1967



NNNNZCZCNASC923SLB077

RTTU JAW RUWJMUA8884 1331804-UUUU--RUCILSA.

ZNR UUUUU

R 131804Z APR 67

FM NAVAIRSYSCOMREPAC

TO RUWMFTA/HATRON ONE TWO THREE

ZENI/NAVAIREWORKFAC NORIS

RUWMHVA/NAVAIREWORKFAC ALAMEDA

INFO RUEDBHB/NAVAIRSYSCOMHQ

ZENI/COMNAVAIRPAC

RUEDHRA/NAVAIRTECHSERVAC

RUCILSA/NAVAUNSAFEEN

RUWMFTA/COMFAIRWHIDREY

RUWJAPA/COMREADATKCARAIRWING ONE TWO

RUWJNDA/NAVPLANTREPO LONG BEACH

RUEDDPA/NAVPLANTREPO E HARTFORD

BT

UNCLAS

A-38 BUNC 138917 AIRCRAFT ACCIDENT INVESTIGATION

A. HATRON 123 110345Z APR 67 FASEP

B. COMNAVAIRPAC/BWFRPAC INST 473C.BA

1. HATRON 123: REQ FWD REF A ENGINES TO NAVAIREWORKFAC  
NORIS AND SELECTED AIRCRAFT PARTS TO NAVAIREWROKFAC ALAMEDA.

PAGE TWO RUWJMUA8884 UNCLAS

MARK CONTAINERS AND DOCUMENTS FOR PRIORITY DIR IAW REF B.  
ADCON SHIPPING MODE AND DOCUMENT NRS. REFER NAVAIRSYSCOMREPAC  
CONTROL NR 3282-67.

2. NAVAIREWORKFAC NORIS: REQ CONDUCT FAILURE ANALYSIS  
SUBJ ENGINES S/Ns P607623 AND P632289 IAW REF B. ADCON  
RESULTS. ABOVE CONTROL NR ASGD.

3. NAVAIREWROKFAC ALAMEDA: REQ CONDUCT FAILURE ANALYSIS  
REF A SELECTED AIRCRAFT PARTS IAW REF B. ADCON RESULTS.  
ABOVE CONTROL NR ASGD.

BT

923  
67

Cog M+M  
A.I

OK  
131804Z

NNHNZCZCNABO536CZBLP053  
 PTTU JAW RUWMTABKAA3 181034Z-UUUU==RUCILBA  
 ZNR UUUUU  
 P R 110342Z APR 67  
 FM HATRON ONE TWO THREE  
 TO RUEHAAA/ZNO  
 RUCILBA/ZNAVA/NAFACEN  
 RUWJMUA/ZCOMNAVAIRPAC  
 INFO RUHLHL/ZCINCPACFLT  
 RUCILMA/ZCOMNAVAIRLANT,  
 RUWMMEA/ZCOMTWELVE  
 RUEBHH/ZNAVAIRBYSOMHQ  
 ZEN/ZCOMFAIRWHIDBEY  
 RUWJAPA/ZCOMREADATHCARIARWIM TWELVE  
 RUEODPA/DIR AFIP  
 RUCIJKA/AFIPERS  
 RUWJNDA/NAVPLANTREPO LDEACH  
 RUEODPA/NAVPLANTREPO HARTFORD  
 RUEBHH/ZCNAVMA  
 BT  
 UNCLAS FOR OFFICIAL USE ONLY  
 SUPPLEMENTARY MESSAGE REPORT NR 3NOF AIRCRA  
 A. OPNAVINST 3750.6E

PAGE TWO- RUMMETABBS UNCLAS FOR OFFICIAL USE ONLY

1. PARA 1 THRU 6 AND 9 THRU 11 REMAIN THE SAME  
2. PARA 7, PORT ENGINE FAILURE AND/OR DUAL ATM FAILURE SUSPECTED  
CAUSE FACTOR  
3. PARA 8, YES  
4. PARA 12, ENGINES (J=57; P=18; SN P=607625 AND SN P=632889)  
ATM'S WITH ACCESSORIES; FLIGHT INSTRUMENTS, FORWARDED FOR DIR.  
BT

A2

NNNNZCZCNASC542LQ  
PTTU JAW RUWMFTA00046 1010345-UUUU--RUCILSA.  
ZNR UUUUU  
P 110345Z APR 67  
FM HATRON ONE TWO THREE  
TO RUWJMUA/NAVAIRSYSCOMREPAC  
INFO RUWJMUA/COMNAVEIRPAC  
RUEDHRA/NAVAIRTECHSERVFAC  
RUCILSA/NAVAVWSAFECEN  
RUWJNDA/NAVPLANTREPO LBEACH  
RUEDDPA/NAVPLANTREPO E HARTFORD  
ZEN/COMFAIRWHIDBEY  
RUWJAPA/COMREADATKCARAIRWING TWELVE  
RUWJMUA/NAS NORIS  
RUWMHVA/NAS ALAMEDA  
BT  
UNCLAS  
PRIORITY INVESTIGATION  
A. BWFRFPAC 4730.8A  
B. OPNAVINST P3750.6E  
C. BUWEPINST 4700.2A  
D. TELECON NAVAIRSYSCOMREPAC WHIDBEY IS.  
BQM A-3B 138917

PAGE TWO RUWMFTA00046 UNCLAS

2. J57P10 S/R P607625
  - J57P10 S/R P632289
  3. 2 FUEL PUMPS
  - 2 FUEL CONTROLS
  - 2 BLEED VALVE GOV
  - 1 ATM ROTOR AND EXHAUST DUCT
  - 1 D/C GEN
  - 1 A/C GEN COIL
  - COCKPIT INST: TACAN, VGI, STBY GYRO
  4. OMITTED
  5. OMITTED
  6. OMITTED
  7. ACFT ENROUTE FROM NAS MIRAMAR TO NAS WHIDBEY IS. FL 180. 1 PLUS 15  
AFTER TAKEOFF CENTER CONTROLLER OBSERVED ON RADAR LEFT DEVIATION  
FROM COURSE FOLLOWED BY LOST CONTACT. WRECKAGE DISCOVERED NEXT DAY.  
NO SURVIVORS. SUSPECT CATASTROPHIC PORT ENG. FAILURE AND/OR DUAL  
ATM FAILURE.
  8. REQUEST PRIORITY INVESTIGATION IAW BWFRFPACINST 4730.8A AND  
OPNAVINST P3750.6E
- BT

542167

COB: MEM

APR  
110345Z

NNNNECNASC419SLB73R  
PTID JAW RUWMFTA0010 0990234-0000--RUCILSA.

ZNR 00000

P R 090234Z A PR 67

FM NATRON ONE TWO THREE

TO RUENAAA/CNO

RUCILSA/NAVAVNSAFECEN

RUWJXUA/COMNAVAIRPAC

INFO RUHLHL/CINCPACFLT

RUCILMA/COMNAVAIRLANT

RUWMMEA/COMTWELVE

RUEDBHB/NAVAIRSYS COMHQ

ZEN/COMFAIRWHIDBEY

RUWJAPA/COMREADATKCAIRWING ONE TWO

RUEDPDA/DIR AFIP

RUCIJFA/BUPERS

RUWJNDA/NAVPLANTREPO LBEACH

RUEDBHB/CHNAVMAT

BT

UNCLAS

FOR OFFICIAL USE ONLY

SUPPLEMENTARY MESSAGE REPORT NR 2 OF AIRCRAFT ACCIDENT

4. OPNAVINST 3750.6E

PAGE TWO RUWMFTA0010 UNCLAS

B. MY 060300Z APR 67 (PASEP)

C. MY 062340Z APR 67 (PASEP)

1. PARA 1 THRU 9 AND 11 REMAIN THE SAME

2. PARA 10 BAILOUT ATTEMPT UNDETERMINED

3. PARA 12, PILOT RICHARD EARL PARKS, LCDR, (b) (6) USN, 1310,

ACTIVE, FATAL; DONALD EDWIN KING, LCDR, (b) (6) USN, 1310,

ACTIVE, FATAL, INSTRUCTOR PILOT; CARL VIRGIL MILLER JR., ADJ3,

(b) (6) USN, ACTIVE, FATAL, PLANE CAPTAIN; JAMES MERRITT

READER, LCDR, (b) (6) USN, 1310, ACTIVE, FATAL, PAX; AAR BOARD

AT SCENE

BT

A3B 138917

VAH-123 1-67A

4-5-67

APR 9 0234Z



NNNNNTSCHASCI440ZCSLA421  
PTTU JAW RUWMFTA0095 0962340-UUUU--RUCLT  
ZNR UUUUU

P.R. 062340Z APR 67  
FM HATRON ONE TWO THREE  
TO RUEHAAA/CNO  
RUCILSA/NAVAVNSAFECEN  
RUWJUMUA/COMNAVAIRPAC  
INFO RUHLHL/CINCPACFLT  
RUWMMEA/COMTWELVE  
RUCILMA/COMNAVAIRLANT  
RUEDBHB/NAVAIRSYSOMHO  
ZEN/COMFAIRWHIDBEY  
RUWJNPA/COMREADATKCARAIRWING TWELVE  
RUWJNDA/NAVPANTREPO LBEACH  
RUEDBHB/CHNAYMAT  
RUEDPDA/DIR AFIP  
BT

UNCLAS FOR OFFICIAL USE ONLY  
SUPPLEMENTARY MESSAGE REPORT OF AIRCRAFT ACCIDENT  
A. OPNAVINST 3750.6E  
B. 260320Z APR 67 NOTAL  
1. 408, 138917, VAH-123, 1-67A, PARKS.

PAGE TWO RUWMFTA0095 UNCLAS

2. NAS MIRAMAR TO NAS WHIDBEY IS, IFR, PLUS 15.
3. ALFA.
4. ACFT COLLISION WITH GROUND.
5. PILOTS FILED J-5 FROM NAS MIRAMAR TO NAS WHIDBEY, IFR, FLT LEVEL 180. COMMUNICATIONS WERE GOOD UNTIL OAKLAND CENTER CLEARED ACFT TO SWITCH TO SEATTLE CENTER. NO RADIO CONTACT WAS MADE WITH SEATTLE CENTER. AT 1431U, SEATTLE CENTER LOST RADAR CONTACT. NORAD ALSO LOST RADAR CONTACT AT 1432U. NORAD REPORTED THE ACFT CHANGED GROUND SPEED FROM 443 KTS AT 1431U TO 396 KTS AT 1432U, AND CHANGED TRACK FROM 340 DEGREES M TO 327 DEGREES M DURING THE SAME TIME. ALT. WAS REPORTED AS 16,750 FT. NO DISTRESS TRANSMISSIONS WERE RECEIVED.
6. 1400U KLAMATH FALLS WX. 3000 FT. CEILING WITH LCT SNOW SHOWERS, TEMP 40 DEGREES F, DEW PT. 25 DEGREES F, WITH CEILINGS LOWERING. CUMULUS BUILDUPS WERE TO FL 200.
7. UNKNOWN.
8. UNKNOWN.
9. UNKNOWN.
10. BAILOUT UNKNOWN. NO KNOWN SURVIVORS AT THIS TIME.
11. NONE.

PAGE THREE RUWMFTA0095 UNCLAS

12. WRECKAGE FOUND THIS A.M. ON THE 1270/80 MI. OF KLAMATH FALLS VORTAC AT 6500 FT. LEVEL OF MOUNTAINS. SAR OF AREA CONTINUING. NEGATIVE RESULTS. AAR BOARD ENROUTE TO CRASH SCENE. STATUS OF INJURIES OF FATALITIES UNKNOWN AT THIS TIME. SUPPLEMENTARY MSG NR 2 TO FOLLOW.

BT

A38 138917 VAH-123 1-67A 4-5-67

144/67

SUPP

AAR

APR

0623402

## MESSAGE DRAFT

SND 4462 (New 2/50)

CLASSIFICATION

UNCLASSIFIED

DATE: 6 APR 1967

FROM: NAVAL AVIATION  
SAFETY CENTER

DRAFTER: (b) (6)

CAPT. (b) (6)

## ACTION

VAH-123  
COM TWELVE  
COM THIRTEEN

O.D.

ENCL	INFO
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>

CNO  
NAVAIRSYSCOMHQ  
COMNAVAIRPAC  
COMFAIR WHIDBEY  
NAS WHIDBEY  
COMREADXCARALWING-12  
NAVAIRSYSPAC

## TEXT

UNCLAS E F T O

A3B BUNO 138917 ACCIDENT

1. LCDR (b) (6) USN, CLMD TOP SECRET  
WILL INVESTIGATE SUBJECT ACCIDENT. INVESTIGATOR CURRENTLY AT  
ALAMEDA AND WILL ARRANGE EARLIEST TRANSPORTATION.
2. INSTRUCTIONS CONTAINED IN OPNAVINST P37 O-4E PAGE 19, PARA 30.B,  
AND PAGE 25, PARA 39A (PRESERVATION OF WRECKAGE) APPLY.

H3B 138917 VAH-123 H-5-07  
REFERENCE MESSAGETRANSMIT BY  
RADIO —

CLASS OF REF.

CWO

15 COMM. OFFICE

DATE/TIME GROUP

062233Z

